



COMMENTS AND RATINGS

West Lothian Trusted Trader Scheme

Property Matters

NUMBER OF FEEDBACK FORMS RECEIVED: 273 (showing most recent 30)

AVERAGE SATISFACTION SCORE (OUT OF 10): 9.8

The following feedback forms have been completed by previous customers, rating their experience of dealing with Property Matters.

Total cost of the work £ 1200 Description of the work undertaken: STRIP WOODCHIP WALLPAPER FROM L/ROOM PLASTER WALLS AND CEILING, EMULSION ALL Hang FEATURE PAPER ON ONE WAY Your comments: Fantastic service. Arranged quickly within a suitable budget. Friendly and approachable - very happy overall.	Date received: 8th October 2026 Total cost of work: £1200 Description of work: Strip woodchip wallpaper from living room. Plaster walls and ceiling, emulsion all. Hang feature paper on one way. Comments: Fantastic service. Arranged quickly within a suitable budget. Friendly and approachable – very happy overall.			
Customer Ratings (Out of 10)	Value for money	Quality of work	Service	Tidiness
	10	10	10	9

ONLINE FEEDBACK PROVIDED	Date received: 3 rd October 2026			
	Total cost of work: £2500.00			
	Description of work: Painted hall staircase and landing, kitchen, utility room, lounge, installed coving in the lounge.			
	Comments: Provided an excellent job for us, very clean workers, attention to detail was excellent, communication was also very open and honest explaining what was involved, any additional extras were discussed freely, I cannot recommend this company enough, very trustworthy and reliable, turned up when they said they would. I would not hesitate to use again. Very competitive in his pricing too.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ 1750.00	Date received: 10 th July 2026			
	Total cost of work: £1750			
Description of the work undertaken: Supply & Fit New Kitchen Ceiling Due to water damage, new LED spot lights, plaster skim ceiling and aimes tape, emulsion white to finish	Description of work: Supply and fit new kitchen ceiling due to water damage, new LED spot lights, plaster skim ceiling and aimes tape, emulsion white to finish.			
	Comments: None provided.			
Your comments:	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	9

Total cost of the work £ 1300	Date received: 5 th June 2026			
	Total cost of work: £1300			
Description of the work undertaken: To carry out repairs to soffit boards Paint all external boards x2 coats of treatment , clean out gutters, paint gutters, gable ends also paint garage door and gas boxes	Description of work: To carry out repairs to soffit boards, pint all external boards x2 coats of treatment, clean out gutters paint gutters, gable ends also paint garage door and gas boxes.			
	Comments: Brilliant work.			
Your comments: Brilliant work	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	9	9	9

Total cost of the work £ 2700 Description of the work undertaken: TO TAKE DOWN EXISTING FENCING, TAKE AWAY FROM SITE RE-BUILD NEW RANCH STYLE FENCE 45 METERS AND PAINT TO FINISH Your comments: I highly recommend Gary & his team fantastic job done	Date received: 5th June 2026 Total cost of work: £2700 Description of work: To take down existing fencing, take away from site. Rebuild new ranch style fence 45 meters and paint to finish. Comments: I highly recommend Gary & his team. Fantastic job done.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	8	9	9

Total cost of the work £ 2800.50 Description of the work undertaken: STRIP WALLPAPER FROM STAIRCASE, UPPER AND LOWER HALLWAY AND DINING ROOM, SKIM WALL TO GOOD FINISH, X2 COATS EMULSION ALL WOODWORK, BUILD X2 SHELVES IN CUPBOARD, INSTALL CO2 ALARM PUT UP CURTAIN POLES AND BLINDS Your comments: I have Gary's services before and won't go past him, good work along with a good personality	Date received: 5th June 2026 Total cost of work: £2800.50 Description of work: Strip wallpaper from staircase, upper and lower hallway and dining room, skim all to good finish, x2 coat emulsion, all woodwork, build x2 shelves in cupboard, install CO2 alarm put up curtain poles and blinds. Comments: I have used Gary's services before and won't go past him, good work along with a good personality.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	9	10	9

Total cost of the work £ 2475. Description of the work undertaken: REMOVE WALLPAPER ON ALL AREAS, PREP WALLS TO MAKE GOOD SURFACE, PLASTER OVER ARTEX CEILING, EMULSION ALL TO A FINISH Your comments: Got an overwhelming sense of trust instantly from Gary and am very happy with the end result.	Date received: 29th April 2026 Total cost of work: £2475 Description of work: Remove wallpaper on all areas, prep walls to make good surface, plaster over artex ceiling, emulsion all to a finish. Comments: Got an overwhelming sense of trust instantly from Gary and am very happy with the end result.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	9

ONLINE FEEDBACK PROVIDED	Date received: 8th April 2026 Total cost of work: £3850 Description of work: Initially, only the painting of a couple of internal rooms; however, the quality of work was excellent, so I added the following; Prep and painting the other internal rooms. Prep and painting of the whole house exterior. Painting the whole of the boundary fence and garden structures. Renewal/repair of boundary fence where required. New felt to the garden hut roof. The quality work has completely lifted the look of the whole of my property, both internally and externally. Comments: Gary's work quality was excellent in all aspects. It is no surprise that he has a 9.8 rating from 265 reviews. He submitted his initial competitive quote on time. His costs for the additional works were more than fair. He used only quality materials. He cleaned up at the end of each day. His communication could not be bettered. Gary is very professional, polite, and trustworthy. I will be using Gary again in the future when the need arises, and I highly recommend him to others.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 25th February 2026 Total cost of work: £650 Description of work: Constructed feature walls in 2 bedrooms Comments: (The work listed is from the end Oct 2025): Constructed fixtures for a wall mounted TV brackets. Repositioned mains socket to be hidden behind TV's. Constructed a length of pipe to hide HDMI cables behind walls. All of the work was made more challenging because the wall in one bedroom was constructed from compressed straw (Stramit boards). Gary was friendly and always turned up when he said he would, even over the course of a few days while waiting on filler hardening and always tidied up.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ <u>2400</u> Description of the work undertaken: <u>TO STRIP WALLPAPER IN KITCHEN, BEDROOM, PLASTERSKIM</u> <u>ALL WALLS + CEILINGS TO GOOD FINISH. EMULSION WALLS +</u> <u>CEILINGS, WOODWORK, DO FLOOR REPAIRS, PLASTER OVER ALL</u> <u>HEATING VENTS ON WALLS,</u> Your comments: <u>ALL WORK DONE TO AN EXCELLENT STANDARD.</u> <u>VERY PLEASED WITH WORK ETHIC AND WILL USE</u> <u>AGAIN TO DO MORE DECORATING. PEOPLE HAVE</u> <u>COMMENTED ON HOW GOOD THE WORK WAS.</u>	Date received: 24th February 2026 Total cost of work: £2400 Description of work: To strip wallpaper in kitchen, bedroom, plasterskim all walls and ceilings to good finish, emulsion walls and ceilings, woodwork, do floor repairs, plaster over all heating vents on walls. Comments: All work done to an excellent standard. Very pleased with work ethic and will use again to do more decorating. People have commented on how good the work was.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	9

ONLINE FEEDBACK PROVIDED	Date received: 9th February 2026 Total cost of work: £150 Description of work: O-ring connecting cistern to seat was eroded, attempted to recondition, had to replace entire flushing mechanism (can't buy o-ring on their own). Comments: Had Gary out for a non-emergency plumbing job and honestly couldn't be happier. He kept in touch the whole time, turned up exactly when he said he would (which already puts him in plumbing legend status), and was an absolute pleasure to deal with. Friendly, professional, got the job done quickly, and the price was very reasonable too — no sharp intakes of breath or mystery charges. Top bloke, top service. Would 100% recommend and will definitely be calling Gary again.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ 1850 Description of the work undertaken: REMOVE W/C, UPLIFT FLOOR TILES, UPLIFT PLYWOOD, REMOVE DAMAGED CABER FLOORING, ADD NEW JOISTS, TREAT AREAS, NEW FLOORING, NEW PLYWOOD, RE-TILE FLOOR, REPLACE W/C, FIX CUPBOARD FLOORING, PAINT ANTI-MOULD Your comments: GARY WAS FAIRLY QUICK GETTING BACK TO ME AFTER TEXTING HIM. HE IS VERY FRIENDLY AND TALKS THROUGH WHAT HE IS DOING AND WHY. WE ARE REALLY HAPPY WITH THE REPAIR WORK HE CARRIED OUT.	Date received: 5th January 2026 Total cost of work: £1850 Description of work: Remove W/C, uplift floor tiles, uplift plywood, remove damaged caber flooring, add new joists, treat areas, new flooring, new plywood, re-tile floor, replace W/C, fix cupboard flooring, paint anti-mould. Comments: Gary was fairly quick getting back to me after texting him. He is very friendly and talks through what he is doing and why. We are really happy with the repair work he carried out.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	9	10	10

Total cost of the work £ 750 Description of the work undertaken: TO FIX WALLS TO GOOD CONDITION EMULSION WALLS + CEILINGS ON LARGE STAIRCASE Your comments: Work done to an excellent standard. Gary was very friendly and professional.	Date received: 17th December 2025 Total cost of work: £750 Description of work: To fix walls to good condition, emulsion walls and ceilings on large staircase. Comments: Work done to an excellent standard. Gary was very friendly and professional.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ 1150 Description of the work undertaken: PREP WALLS IN ALL AREAS, EMULSION SMALL FLAT, WALLS, CEILINGS, WOODWORK TO A FINISH Your comments: FANTASTIC WORK. GREAT GUY	Date received: 25th April 2025 Total cost of work: £1150 Description of work: Prep walls in all areas, emulsion small flat, walls, ceilings, woodwork to a finish. Comments: Fantastic work. Great guy.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ <u>800</u> Description of the work undertaken: <u>TAKE DOWN WATER DAMAGED</u> <u>KITCHEN CEILING, REPLACE WITH NEW</u> <u>PLASTERBOARD, AIMES TAPE, SKIM CEILING</u> <u>WITH PLASTER, EMULSION TO A FINISH</u> Your comments: <u>GREAT SERVICE FROM GARY. KEPT ME UP TO DATE WITH ALL OF THE</u> <u>WORK AND ARRIVED ON TIME EVERY DAY HE WAS HERE. THE STANDARD</u> <u>OF WORK WAS ACTUALLY BETTER THAN THE ORIGINAL WHICH I WAS</u> <u>IMPRESSED WITH. SO VERY HAPPY WITH ALL ASPECTS OF THIS JOB.</u>	Date received: 19th March 2025 Total cost of work: £800 Description of work: Take down water damaged kitchen ceiling, replace with new plasterboard, aimes tape, skim ceiling with plaster, emulsion to finish. Comments: Great service from Gary. Kept me up to date with all of the work and arrived on time every day he was here. The standard of work was actually better than the original which I was impressed with. So very happy with all aspects of this job.								
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">Value for money</td> <td style="width: 25%;">Quality of work</td> <td style="width: 25%;">Service</td> <td style="width: 25%;">Tidiness</td> </tr> <tr> <td style="text-align: center;">10</td> <td style="text-align: center;">10</td> <td style="text-align: center;">10</td> <td style="text-align: center;">10</td> </tr> </table>	Value for money	Quality of work	Service	Tidiness	10	10	10	10
Value for money	Quality of work	Service	Tidiness						
10	10	10	10						
Customer Ratings (Out of 10)									

Total cost of the work £ <u>1200</u> Description of the work undertaken: <u>MULTIPLE JOBS DONE ON A</u> <u>RENTED PROPERTY AS FOLLOWS</u> <u>TREAT MOULD IN AREAS, FIX DOOR HANDLES, NEW TOILET</u> <u>RE-GROUT SHOWER, FIX SMOKE ALARMS, EMULSION ALL ROOMS</u> <u>REPAIRS TO FLOORING</u> Your comments: <u>GARY DID ALOT MORE WORK FOR ME THAN</u> <u>WHAT WAS QUOTED FOR, GREAT TO WORK WITH</u> <u>FULLY RECOMMEND HIM AND KEEP UP THE GOOD</u> <u>WORK GARY, IT WAS A PLEASURE.</u>	Date received: 10th March 2025 Total cost of work: £1200 Description of work: Multiple jobs done on a rented property as follows. Treat mould in area's, fix door handles, new toilet, re-grout shower, fix smoke alarms, emulsion all rooms, repairs to flooring. Comments: Gary did a lot more work for me than what was quoted for, great to work with. Fully recommend him and keep up the good work Gary, it was a pleasure.								
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">Value for money</td> <td style="width: 25%;">Quality of work</td> <td style="width: 25%;">Service</td> <td style="width: 25%;">Tidiness</td> </tr> <tr> <td style="text-align: center;">9</td> <td style="text-align: center;">9</td> <td style="text-align: center;">10</td> <td style="text-align: center;">10</td> </tr> </table>	Value for money	Quality of work	Service	Tidiness	9	9	10	10
Value for money	Quality of work	Service	Tidiness						
9	9	10	10						
Customer Ratings (Out of 10)									

Total cost of the work £ Description of the work undertaken: <u>Upstairs water pipes burst flooding my flat</u> <u>causing bathroom ceiling to come down damaging the</u> <u>floor walls in the hall and kitchen.</u> Your comments: <u>work carried out to my rented property to</u> <u>an exelent standard. Extremely happy with</u> <u>work.</u>	Date received: 19th February 2025 Total cost of work: Not provided Description of work: Upstairs water pipes burst flooding my flat causing bathroom ceiling to come down damaging the floor, walls in the hall and kitchen. Comments: Work carried out to my rented property to an excellent standard. Extremely happy with work.								
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">Value for money</td> <td style="width: 25%;">Quality of work</td> <td style="width: 25%;">Service</td> <td style="width: 25%;">Tidiness</td> </tr> <tr> <td style="text-align: center;">10</td> <td style="text-align: center;">10</td> <td style="text-align: center;">10</td> <td style="text-align: center;">9</td> </tr> </table>	Value for money	Quality of work	Service	Tidiness	10	10	10	9
Value for money	Quality of work	Service	Tidiness						
10	10	10	9						
Customer Ratings (Out of 10)									

Total cost of the work £ 550 Description of the work undertaken: REPAIRED WALLS BY SKIMMING PLASTER. AFTER ELECTRICIAN CUT HOLES OUT OF WALLS FOR NEW SOCKETS Your comments: Had a wonderful experience with Gary. A very warm and bubbly man. He communicated well and was prompt on finishing the job. Very trusting. Highly recommend Gary!	Date received: 19th February 2025 Total cost of work: £550 Description of work: repaired walls by skimming plaster after electrician cut holes out of walls for new sockets. Comments: Had a wonderful experience with Gary. A very warm and bubbly man. He communicated well and was prompt on finishing the job. Very trusting. Highly recommend Gary!			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	9	10	9

Total cost of the work £ 750 Description of the work undertaken: SUPPLIED AND FITTED A FULL LENGTH HANDRAIL TO STAIRCASE, PLASTERED x 2 CEILINGS Your comments: Gary did a brilliant job. I am very pleased.	Date received: 5th February 2025 Total cost of work: £750 Description of work: Supplied and fitted a full length handrail to staircase, plastered x 2 ceilings. Comments: Gary did a brilliant job. I am very pleased.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ 600 Description of the work undertaken: SUPPLY & FIT SINK FOR BATHROOM SUPPLY & FIT KITCHEN TAP. TOILET SEAT AND CEILING LIGHT Your comments: All the work was undertaken swiftly and the items supplied were excellent. The workplace was clean & tidy after the work was complete.	Date received: 30th January 2025 Total cost of work: £600 Description of work: Supply and fit sink for bathroom. Supply and fit kitchen tap. Toilet seat and ceiling light. Comments: All the work was undertaken swiftly and the items supplied were excellent. The work place was clean and tidy after the work was complete.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ <u>780</u> Description of the work undertaken: <u>RE-GROUTED SHOWER CUBICLE</u> <u>AND REPAIRED DOWNSTAIRS CEILING</u> <u>DUE TO WATER DAMAGE</u> Your comments: <u>GOOD SERVICE & EXPLAINED ALL WORK & COST BEFORE</u> <u>STARTING, REVISED COST (REDUCTION) ONCE WORK COMPLETED</u> <u>WOULD USE AGAIN & RECOMMEND TO OTHERS.</u>	Date received: 30th January 2025 Total cost of work: £780 Description of work: Re-grouted shower cubicle and repaired downstairs ceiling due to water damage. Comments: Good service and explained all work and cost before starting, revised cost (reduction) once work completed. Would use again and recommend to others.								
Customer Ratings (Out of 10)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th style="width: 25%;">Value for money</th> <th style="width: 25%;">Quality of work</th> <th style="width: 25%;">Service</th> <th style="width: 25%;">Tidiness</th> </tr> <tr> <td style="text-align: center;">10</td> <td style="text-align: center;">10</td> <td style="text-align: center;">10</td> <td style="text-align: center;">10</td> </tr> </table>	Value for money	Quality of work	Service	Tidiness	10	10	10	10
Value for money	Quality of work	Service	Tidiness						
10	10	10	10						

Total cost of the work £ <u>1100</u> Description of the work undertaken: <u>PLASTER STAIRCASE WALL</u> <u>EMULSION FULL STAIRCASE TO A</u> <u>FINISH</u> Your comments: <u>WE HAVE USED GARY FOR WORK BEFORE AND</u> <u>HAVING HAD SUCH A GOOD EXPERIENCE WITH</u> <u>HIM, WENT STRAIGHT BACK FOR THIS JOB. WE</u> <u>ALSO HAVE PLANS TO GET HIM BACK FOR OTHER</u> <u>JOB TOO. GREAT GUY AND FANTASTIC, AT WHAT HE DOES</u>	Date received: 16th December 2024 Total cost of work: £1100 Description of work: Plaster staircase wall, emulsion full staircase to a finish. Comments: We have used Gary for work before and having had such a good experience with him, went straight back for this job. We also have plans to get him back for other jobs too. Great guy and fantastic at what he does.								
Customer Ratings (Out of 10)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th style="width: 25%;">Value for money</th> <th style="width: 25%;">Quality of work</th> <th style="width: 25%;">Service</th> <th style="width: 25%;">Tidiness</th> </tr> <tr> <td style="text-align: center;">10</td> <td style="text-align: center;">10</td> <td style="text-align: center;">10</td> <td style="text-align: center;">10</td> </tr> </table>	Value for money	Quality of work	Service	Tidiness	10	10	10	10
Value for money	Quality of work	Service	Tidiness						
10	10	10	10						

Total cost of the work £ <u>180</u> Description of the work undertaken: <u>VARIOUS JOBS OUTSIDE THE HOUSE</u> <u>I.E. PUT UP NAME BOARD, INSTALL UPVC COVERINGS</u> <u>TO FRONT DOOR. REPLACE OUTSIDE SECURITY LIGHT</u> <u>AND ALARM BOX (SUPPLIED BY CUSTOMER)</u> Your comments: <u>GARY WAS FRIENDLY, POLITE, PATIENT AND HELPFUL.</u> <u>HE MADE SURE THAT EACH JOB WAS COMPLETED</u> <u>EXACTLY AS WE WANTED</u>	Date received: 4th December 2024 Total cost of work: £180 Description of work: Various jobs outside the house i.e. put up name board, install UPVC coverings to front door. Replace outside security light and alarm box (supplied by customer). Comments: Gary was friendly, polite, patient and helpful. He made sure that each job was completed exactly as we wanted.								
Customer Ratings (Out of 10)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th style="width: 25%;">Value for money</th> <th style="width: 25%;">Quality of work</th> <th style="width: 25%;">Service</th> <th style="width: 25%;">Tidiness</th> </tr> <tr> <td style="text-align: center;">9</td> <td style="text-align: center;">10</td> <td style="text-align: center;">10</td> <td style="text-align: center;">10</td> </tr> </table>	Value for money	Quality of work	Service	Tidiness	9	10	10	10
Value for money	Quality of work	Service	Tidiness						
9	10	10	10						

Total cost of the work £ 15,000 Description of the work undertaken: BUILD NEW FENCE x 12 MTRS BUILD NEW PATIO WALL Your comments: Gary was a very pleasant chap to deal with and built up a good rapport with my elderly parents for whom the work was being done. We were all very satisfied with all aspects of the work.	Date received: 25th November 2024 Total cost of work: £15,000 Description of work: Build new fence x 12 mtr's. Build new patio wall. Comments: Gary was a very pleasant chap to deal with and built up a good rapport with my elderly parents for whom the work was being done. We were all very satisfied with all aspects of the work.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ 1575 Description of the work undertaken: REPAIR LEAKING RADIATOR REPLACE WET/DAMAGED PLASTERBOARD CEILING SKIM + EMULSION CEILING AND WALLS TO A FINISH Your comments: NOT ONLY DID I GET A FANTASTIC JOB, BUT NOW A FRIEND HIGHLY RECOMMEND GARY	Date received: 25th November 2024 Total cost of work: £1575 Description of work: Repair leaking radiator. Replace wet/damaged plasterboard ceiling. Skim and emulsion ceiling and walls to a finish. Comments: Not only did I get a fantastic job, but now a friend. Highly recommend Gary.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	9

Total cost of the work £ 400 Description of the work undertaken: PROFESSIONAL BLACKSMITH ON BOARD WITH MADE TO ORDER SIZE AND FIT DISABLED HAND RAILS AT FRONT DOOR STEP Your comments: Gary was the only Joiner on the Trusted Trader Scheme who replied to me and kept in touch. He went above and beyond to fit my hand rails - getting a blacksmith to make them up. I won't hesitate to use Gary again.	Date received: 31st October 2024 Total cost of work: £400 Description of work: Professional blacksmith on board with made to order size and fit disabled handrails at front door step. Comments: Gary was the only joiner on the Trusted Trader scheme who replied to me and kept in touch. He went above and beyond to fit my handrails - getting a blacksmith to make them up. I won't hesitate to use Gary again.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ 265 Description of the work undertaken: TO SUPPLY & FIT A NEW SHOWER PUMP TO A LOW PRESSURE SYSTEM Your comments: Gary was extremely efficient and carried out the work with skill and care. Fast service, friendly and explained job and work required. Extremely helpful and made sure I was satisfied with work completed. Gary was brilliant and I have no hesitation in recommending him to others.	Date received: 29th August 2024 Total cost of work: £265 Description of work: To supply and fit a new shower pump to a low pressure system. Comments: Gary was extremely efficient and carried out the work with skill and care. Fast service, friendly and explained job and work required. Extremely helpful and made sure I was satisfied with work completed. Gary was brilliant and I have no hesitation in recommending him to others.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ 350 Description of the work undertaken: REMOVE BATH SILICONE (MOULDY) ADD BATH SUPPORTS TO STRENGTHEN IT DIG OUT TILE GROUT, APPLY NEW GROUT AND SILICONE Your comments: All work undertaken to a very high standard. Everything explained. Nothing too much trouble. Friendly and professional, would not hesitate to use again.	Date received: 20th August 2024 Total cost of work: £350 Description of work: Remove bath silicone (mouldy), add bath supports to strengthen it, dig out tile grout, apply new grout and silicone. Comments: All work undertaken to a very high standard. Everything explained. Nothing too much trouble. Friendly and professional, would not hesitate to use again.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ 910 Description of the work undertaken: PLASTERSKIM CEILING TO HIDE NEW PLASTERBOARD PATCH (LOFT HATCH) FEATHER ALL WALLS IN HALLWAY AND STAIRCASE, EMULSION ALL TO A FINISH X 2 COATS Your comments: A very professional job carried out well and in a pleasant and friendly manner. I have used his services since this job which was also well done.	Date received: 28th June 2024 Total cost of work: £910 Description of work: Plaster skim ceiling to hide new plasterboard patch (loft hatch). Feather all walls in hallway and staircase, emulsion all to a finish x 2 coats. Comments: A very professional job carried out well and in a pleasant and friendly manner. I have used his services since this job which was also well done.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	9

Total cost of the work £ <u>475.</u> Description of the work undertaken: <u>REPLACED BATHROOM SINK</u> <u>AND TOILET, SUPPLY & FIT</u> Your comments: <u>Great job by Gary, instant feeling</u> <u>of trust and warmth, cared about</u> <u>the work and all left tidy</u> <u>would recommend.</u>	Date received: 17th June 2024 Total cost of work: £475 Description of work: Replaced bathroom sink and toilet, supply and fit. Comments: Great job by Gary, instant feeling of trust and warmth, cared about the work and all left tidy. Would recommend.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10