

COMMENTS AND RATINGS

West Lothian Trusted Trader Scheme

Allbright Electrical Contractors

NUMBER OF FEEDBACK FORMS RECEIVED: 100 (showing most recent 30)

AVERAGE SATISFACTION SCORE (OUT OF 10): 9.8

The following feedback forms have been completed by previous customers, rating their experience of dealing with Allbright Electrical Contractors.

| ONLINE FEEDBACK PROVIDED | Date received: 5 th December 2024 | | | |
|------------------------------|--|-----------------|---------|----------|
| | Total cost of w | ork: £2700 | | |
| | Description of work: Replace all lights to LED ceiling panels. | | | |
| | Comments: Excellent workmanship, professional, polite and clear. Skilled and turned up on time on both days, efficient and transparent and honest. | | | |
| | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 |

| ONLINE FEEDBACK PROVIDED | Date received: 24 th October 2024 | | | |
|------------------------------|---|-----------------|---------|----------|
| | Total cost of work: £900 | | | |
| | Description of work: Home EV charger installed. | | | |
| | Comments: Great service, efficient and very professional and friendly. Completed work with no mess left behind. | | | |
| | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 |

| ONLINE FEEDBACK PROVIDED | Date received: 1st October 2024 | | | |
|------------------------------|--|-----------------|---------|---------------|
| | Total cost of work: Not provided | | | |
| | Description of work: Outside lighting, including front door down lighters and security lights; and smoke/heat/ CO2 alarms fitted throughout inside Comments: Excellent service and extremely professional company. Cannot fault and have no hesitation in recommending. | | | inside ely |
| | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 |

| ONLINE FEEDBACK PROVIDED | Date received: 1st July 2024 Total cost of work: £262 | | | |
|------------------------------|---|-----------------|---------|---------------------------------|
| | Description of work: EICR for a completion certification | | | n certificate. |
| | Comments: First time using Callum and would definitely recommend. We needed an EICR to provide to the council to obtain a completion certificate for works completed some time ago. Callum had availability within the week and job was done within an hour. Full report to the council and certificate received. Thanks again. | | | R to on ago. d job was |
| | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 9 | 10 | 10 | 10 |

| ONLINE FEEDBACK PROVIDED | Date received | Date received: 26 th April 2024 | | | | |
|------------------------------|---|---|---|----|--|--|
| | Total cost of w | Total cost of work: £610.63 | | | | |
| | back door. Re chrome shave mirror. Supply | Description of work: Various small jobs. New light at back door. Replace bathroom mirror. Replace chrome shaver socket. Replace wall mounted circul mirror. Supply and fit lithium co detector. Various sockets replaced/repaired. TV aerial booster fitted. Comments: Excellent work by a father and son team They arrived early and just worked their way through the various jobs, including some 'add-ons' on the day. Tidied up impeccably at the end. Would highly recommend them. | | | | |
| | They arrived e the various job day. Tidied up | | | | | |
| | Value for money | Quality of Service Tidines | | | | |
| Customer Ratings (Out of 10) | 9 | 9 | 9 | 10 | | |
| | L | 1 | 1 | I | | |

| ONLINE FEEDBACK PROVIDED | Date received: 12 th April 2024 Total cost of work: £1068 | | | |
|------------------------------|---|-----------------|---------|----------|
| | Description of work: Outdoor socket box changes, installation of outdoor wall lights and floodlight. Unde kitchen cabinet LED lights and wall mirror light installation. | | | |
| | Comments: Very unprofessional. Father and son who bicker with each other all day and huff and puff their way through work. Messy and disorganised. Disrespectful towards private things in my home and lack of concern for leaving doors wide open while raining and cold outside and having a small dog in the house that could have escaped. Quick and happy to quote with nothing being a problem. Very different attitude once they start the work. | | | |
| | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 7 | 7 | 1 | 1 |

Trader right to reply:

As shown by other very positive reviews on this website, we have, for more than 34 years been a well respected and highly rated company.

As this is the second time we have worked for you we are saddened you could not approach us with your comments before you posted them on various places on the internet.

| ONLINE FEEDBACK PROVIDED | Description of which best surpliced in the with that efficients which best surpliced in the without a breamand the with that efficients in the well in advants. | Description of work: £192 Description of work: 1. Advise on new shower unit which best suited my needs. 2. Install new shower unit, and set up same. 3. Correct wiring faults regarding hall light switches. 4. Reconnect ceiling pendant unit and test same. Comments: 'Allbright' made the initial visit as promised. They were punctual on the day they allocated to carry out the job. They both worked without a break and completed the tasks in a very reasonable time frame. They encountered a snag regarding the plumbing of the old shower, but dealt with that efficiently. I was made aware of the costs well in advance, and was happy with the quoted charge. | | | |
|------------------------------|---|--|---------|----------|--|
| | Value for money | Quality of work | Service | Tidiness | |
| Customer Ratings (Out of 10) | 10 | 9 | 10 | 10 | |

| ONLINE FEEDBACK PROVIDED | Date received: 25 th April 2022 | | | | |
|------------------------------|---|-----------------|---------|----------|--|
| | Total cost of work: £1105.48 | | | | |
| | Description of work: Installation of an electric car home charging point, including initial survey of the location. UK government grant deducted from invoice. | | | | |
| | Comments: Installed on final day eligible for grants, and Allbright made sure this happened. The work was done professionally, and all relevant paperwork was supplied ASAP to enable additional claim for Scottish grant. The associated app was demonstrated upon completion. I would definitely recommend Allbright. | | | | |
| | Value for money | Quality of work | Service | Tidiness | |
| Customer Ratings (Out of 10) | 9 | 10 | 10 | 10 | |

| ONLINE FEEDBACK PROVIDED | Date received: 25 th April 2022 | | | |
|------------------------------|---|-----------------|---------|----------|
| | Total cost of work: £96 | | | |
| | Description of work: Move aerial point to new position behind television that was already wall mounted. | | | |
| | Comments: Although always busy, Allbright Electrica managed to slot my job into their schedule within a couple of days. David and Callum arrived at the appointment time, are always polite and friendly and on completion of the work, left the area neat and tidy. Wouldn't hesitate to recommend them and will certainly use them again. | | | |
| | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 |

| ONLINE FEEDBACK PROVIDED | Date received | Date received: 14 th March 2022 | | | |
|------------------------------|--|--|---------|-------------|--|
| | Total cost of w | ork: £72 | | | |
| | Description of work: Identify faulty underfloor heating which was causing the system to trip. | | | oor heating | |
| | Comments: Very prompt service which is ideal whe you don't know why most of the electrics in your house are not working. Much appreciated. | | | | |
| | Value for money | Quality of work | Service | Tidiness | |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 | |

| ONLINE FEEDBACK PROVIDED | Date received: 25 th February 2022 Total cost of work: £1350 | | | |
|------------------------------|--|-----------------|---------|----------|
| | Description of work: Installation of EV charge point a my home address including design and commissioning and support through the grant application process. | | | |
| | Comments: The guys have been brilliant from start to finish - really professional and on the day of the installation they were on time, worked to an exceptional level and ensured that a full handover took place before they left my premises. All details of what was required to be done and why were explained in full detail. You could not ask for more and I would not hesitate to use them again for any further projects I may have and would highly recommended them to anyone. | | | |
| | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 |

| ONLINE FEEDBACK PROVIDED | Date received: 15th February 2022 Total cost of work: Not provided. Description of work: Provided and installed an electric car charger unit. Comments: I thought they were very professional, from the first contact they arranged to come out quickly and provided quote and information, then booked us in for the work to be done at a convenient time. On installation day they were punctual, polite, friendly, the kind of people you can talk to and ask questions. Showed me how to work everything before they left and house was all clean and tidy when job was complete. Would not hesitate to use them again and would happily recommend them to anyone. | | | |
|------------------------------|---|----|----|----|
| | Value for Quality of Service Tidines work | | | |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 |

| ONLINE FEEDBACK PROVIDED | Date received: 12th May 2021 | | | |
|------------------------------|---|-----------------|---------|----------|
| | Total cost of work: £450 Description of work: A lot electrical wires to sort as | | | |
| | kitchen refurb. | | | |
| | Comments: First class service. Great guys down to earth which always good. I've used few times and intend to have them back again. An electrician company you can trust to do job proper. | | | |
| | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 |

| ONLINE FEEDBACK PROVIDED | Date received: 10 th May 2021 | | | |
|------------------------------|---|-----------------|---------|---|
| | Total cost of w | ork: £375 | | |
| | Description of work: Supplied armoured cable for supply to new summer house and first fit wiring for sockets and lighting. Supplied, wired and fitted twir waterproof outdoor socket at rear of property. Comments: Excellent service. Provided great advice and were flexible in dealing with requirements whe looking at options to supply power to a new summer house. Friendly and tidy experts! Have already recommended to others. | | | viring for fitted twin erty. eat advice ents when w summer |
| | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 |

| | T | | | |
|------------------------------|---|-----------------|---------|----------|
| ONLINE FEEDBACK PROVIDED | Date received: 21st September 2020 | | | |
| | Total cost of work: £40 | | | |
| | Description of work: Outside light fitted. | | | |
| | Comments: Great service. The guys were both friendly and chatty. Everything was left very tidy; would definitely use again and recommend. | | | |
| | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 |

| Grasen put BACK TO ORIGINAL STATE | Description of the work of CARLE GRANTS Description of the work undertaken: WALL DRIVED IN BEDROOM TO PUSH CARLE OUT SIDE 45 OF CARLE RUN ALONG GORDEN, DUG DOWN & RADINGEO BY INDERCRENO CHARGES GITTED AT BACK END OF GORDEN YOUR COMMENTS: | Total cost of w Description of cable outside, down and replaced back end of gath comments: Guthe day arrived | te received: 7th September 2020 tal cost of work: OLEV/EST GRANTS scription of work: Wall drilled in bedroom to proble outside, 45 of cable run along garden, dug wn and replaced by workmen. Charger fitted ack end of garden. mments: Guys were in touch before start day, a day arrived on time. Job done and place tidy arden put back to original state. | | n, dug fitted at art day, on |
|-----------------------------------|--|---|--|---------|------------------------------------|
| money work | DAY ARRIVED ON TIME JOS DONE & PLACE TROY. | Value for | Quality of | Service | Tidiness |

| ONLINE FEEDBACK PROVIDED | Date received: 4 th September 2020 | | | | |
|------------------------------|--|-----------------|---------|--------------|--|
| | Total cost of work: £587 | | | | |
| | Description of work: Replace old consumer unit with new 10 way amendment consumer unit. | | | er unit with | |
| | Comments: Fantastic service provided by Allbright Electrical Contractors Ltd. Contacted them to provide a quote for replacing our old consumer unit. Received a quick response to our request and job was completed within a few days of receiving the detailed quote. Would definitely recommend them, very professional service. | | | | |
| | Value for money | Quality of work | Service | Tidiness | |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 | |

| | Т | | | |
|------------------------------|--|-----------------|---------|----------|
| ONLINE FEEDBACK PROVIDED | Date received: 26 th August 2020 | | | |
| | Total cost of work: £593.66 | | | |
| | Description of work: Remove and replace main fuse box. Re-purpose two electric sockets, rewire electrical switch and light boss, check wiring on stair lighting. | | | |
| | Comments: The electricians were punctual and friendly. They kept me informed as to how the wow was progressing. Everything was left clean and twill definitely use the firm again. | | | |
| | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 |

| Total cost of the work £ | Date received: 16th July 2020 | | | |
|---|--|-----------------|---------|----------|
| Description of the work undertaken: Y2 External electrical Socials Your comments: | Total cost of work: Not provided Description of work: x2 external electrical sockets. Comments: Very courteous, easy to speak with. Ve efficient and tidy. | | | |
| Very Curteaus, easy to speak with- | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 |
| | Ī | • | • | |

| Total cost of the work £ | Date received: 25 th February 2020 | | | |
|---|--|-----------------|---------|-----------|
| Description of the work undertaken: Install RCO Spur Unit for electric towel Rayl and install towel Rayl in Bathroom. Install held Outside light. Replace existing Sportights With Leld Spotlights Your comments: | Total cost of work: Not provided Description of work: Install RCD spur unit for electric towel rail and install towel rail in bathroom. Install I.e.d outside light. Replace existing spotlights with I.e.d spotlights. Comments: 1st class service. | | | . Install |
| ISI CLASS SEIDI CC. | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 9 |

| | | | | 1 |
|--|---|-----------------|---------------|-----------|
| Description of the work undertaken: Snotallauca of Hob Oken + Mealed Yowel Rail. Culsicle securly light. Reparted switch on Electric Yele. | Date received: 24 th February 2020 Total cost of work: N/A Description of work: Installation of hob, oven and heated towel rail. Outside security light. Repaired switch on electric fire. | | | |
| Very professional and competent persons Explained everything in a concise manner Have no hesitation in recommending to my friends of family | Comments: Ve persons. Expla Have no hesita and family. | ined everythin | g in a concis | e manner. |
| | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 |

| Total cost of the work £ | Date received: | : 13 th Decembe | er 2019 | |
|--|------------------------------|---|--------------------------------|----------|
| Description of the work undertaken: INSTRUMENTAL TROUNCEMENT (REPLACEMENT) REPLACING OLD CONSUMEN UNIT WITH NEW CONSUMEN UNITS WITH R.C.B.O'S | Description of (replacements | vork: Not provice work: Installing). Replacing oler units with RC | ว 7 downlights d consumer เ | |
| Your comments: WORK CARRIED OUT TO A HIGHSTANDANG | | ork carried out teous and resp | | |
| OF MY PROPERTY | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 |

| Total cost of the work £ | Date received: 15 th October 2019 | | | |
|--|---|-----------------|---------|----------|
| Description of the work undertaken: REPLACE FUGE BOX IN OARAGE | Total cost of w | ork: Not provid | led | |
| The state of the s | Description of work: Replace fuse box in garage. | | | arage. |
| Your comments: Good, Friendly service and turned up when | Comments: Good, friendly service and turned up when they said they would. | | | ned up |
| they said they would | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 8 | 10 | 10 | 10 |

| Total cost of the work £ | Date receive | d: 10 th October | 2019 | |
|---|---|-----------------------------|---------|----------|
| Description of the work undertaken: | Total cost of | work: Not provi | ded | |
| PAT TESTING Spotlight Ends Replacement Light Inthing replacement Cleatrical Sunth repair | Description of work: PAT testing. Spotlight bulb replacement. Light fitting replacement. Electrical switch repair. | | | |
| Your comments: Excellent! Lots of additional much mo completed as meday - no need by a return NSIE. Poute, hendly, helpful electricism - will def. recommend | Comments: Excellent! Lots of additional work was completed on Monday – no need for a return visit Polite, friendly, helpful electricians – will def. recommend. | | | |
| - Tome, preting, tappia, educations mucha, 1420 volume | Value for money | Quality of work | Service | Tidiness |
| ustomer Ratings (Out of 10) | 10 | 10 | 10 | 10 |

| Total cost of the work £ | Date received: 27 th September 2019 | | | |
|---|--|-----------------|---------|----------|
| Description of the work undertaken: | Total cost of work: Not provided | | | |
| Leid Strip light, Conduct, Essebagard, putdoor Cable | Description of work: Power to external workshop. 8 x twin sockets, LED strip light, conduit, fuseboard, outdoor cable. | | | |
| Your comments: great Workmanship. Would use again 100% | Comments: Great workmanship. Would use again 100%. | | | |
| | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 |

| Total cost of the work £ Description of the work undertaken: OLD STRIP & GARS RAPLACES IN KITCHEN OVEN & HOB DISCONNIGOTAD AND NIGHT ONES INSTALLED. Your comments: OLD OVANIBOB WAS TRIPPING & ATRICAN OFF CALLED ALLBRICHT AND THAT CARR FOLLOWING AND AND | Date received: Total cost of words of the cost of words of the cost of words of the cost o | ork: Not provid work: Old strip and hob discon d oven/hob wa t and they cam ue. They returr | led lights replace nected and restripping elements to discontinuity. | ctricity off. ay and nect old |
|---|--|--|--|-------------------------------------|
| OLD COUMAN AND INSTALL NAW ONA VARY ALLONDOMINA | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 |

| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 | |
|---|---|---------------------------|---------|----------|--|
| Total cost of the work £ | Date received: | 14 th August 2 | 019 | | |
| Description of the work undertaken: WEW CONSUMEN UNIT, REPLACED FAMILY BASHROOM LIGHT/ EXTRACTION FAM ARE ARRES POWEN FO LEXTERNAN SUMMEN HOURS | Total cost of work: Not provided Description of work: New consumer unit, replaced faulty bathroom light/extractor fan and applied power to external summer house. | | | | |
| YOURCOMMENTS: VERY DETAILS EXPERIMENT BUTSON JUS STAND KEPT ME INFORMOR AS JUS PROGRESSED FINISHED JUS WITHIN AGREE TIMESBAGS. I WAS WATCHING MY | Comments: Very detailed explanations before job started. Kept me informed as job progressed. Finished job within agreed timescales. I was watching my baby grandson and the guys are ve child friendly. | | | | |
| BABY CARNESON AND Phs Luys ARY NORY CHILD FAILING | Value for money | Quality of work | Service | Tidiness | |
| customer Ratings (Out of 10) | 10 | 10 | 10 | 10 | |

| Total cost of the work £ | Date received: 19th July 2019 | | | |
|--|--|-----------------|---------|----------|
| Description of the work undertaken: & SAFETY FULL HOUSE ELECTRICAL CHECK AND UPDATE (FUSE ROXES REPLACED ETC.) SUPPLY S FIT OUTSIDE ELECTRICAL POWER POINTS | Total cost of work: Not provided Description of work: Full house electrical safety check and update (fuse boxes replaced etc.) Supply and fit outside electrical power points. Comments: Very happy with all work carried out. | c.) Supply | | |
| VERY HAPPY WITH ALL WORK CARRIED OUT | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 |

Т

| Total cost of the work £ | Date received: 31st May 2019 | | | |
|---|--|-----------------|---------|----------|
| Description of the work undertaken: REPLACEMENT OF OLD LIGHT FITTINGS WITH | Total cost of w | ork: Not provid | led | |
| BYCHGY EFFICIENT LED - INDOOR AND OUTDOOR | Description of work: Replacement of old light fittings with energy efficient LED – indoor and outdoor. Comments: Quick response and quote, tidy workers, turned up on time, polite and courteous. | | | |
| Your comments: QUICK RESPONSE & QUOTE TIDY WORKERS, TURNED | | | | |
| UD ON TIME POLITE 4 CURTERUS | Value for money | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 |

| Total cost of the work £ | Date received: 24 th April 2019 | | | | |
|--|---|----------------------------------|---------|----------|--|
| Description of the work undertaken: | Total cost of | Total cost of work: Not provided | | | |
| FILTED SUSPERS SUSPERS CHOSEN STEED CHOSES | Description of work: Fuse box replaced, fan fitted, light fitted, smoke alarms and heat sensors fitted. | | | | |
| | Comments: | Comments: No complaints. | | | |
| Your comments: | Value for money | Quality of work | Service | Tidiness | |
| Customer Ratings (Out of 10) | 10 | 10 | 10 | 10 | |

Т