

Our ref: PCS/143108 Your ref:

If telephoning ask for: Alasdair Milne

20 November 2015

Fiona McBrierty Planning & Economic Development West Lothian Civic Centre Howden Road South Livingston West Lothian EH54 6ff

By email only to: wlldp@westlothian.gov.uk

Dear Fiona

# West Lothian Local Development Plan Publication of Proposed Plan

Thank you for consulting SEPA on the Proposed Local Development Plan for West Lothian.

We welcome the opportunity you have given us for early, continual and effective engagement in the plan-making process.

As indicated in several of our representation forms we would welcome a meeting to discuss the content of our representations in more detail and we look forward to arranging this at a time convenient to you.

# 1. Summary of SEPA response

- 1.1 In response to the Proposed Plan consultation we have submitted 81 representation forms in relation to the plan polices (18) and proposed allocations (63). For completeness we have summarised these in Tables 1 and 2 below indicating in the case of the allocations those where we require a modification to the developer requirements. We have been unable to submit our comments on the allocations via the Council's online form but have done this for our policy comments.
- 1.2 As summarised in Table 1 we are pleased to be able to support 18 policies. However, we have recommended changes to the wording of 4 policies. Please note that in some instances we have supported elements of a policy but also requested modifications.
- 1.3 We have included with this covering letter an Excel spreadsheet which contains our detailed comments in respect of flood risk for **all** housing and employment allocations. Of key importance to you are Columns O, P and Q of the spreadsheet which set out our detailed comments as well as an indication of where we are requiring modifications. We would stress the importance of the Council taking note of our detailed comments on flood risk in some instances where the Council has requested a Flood Risk Assessment in the



Chairman David Sigsworth

Chief Executive James Curran

### **Strathearn House**

Broxden Business Park, Lamberkine Drive, Perth, PH1 1RX tel 01738 627989 fax 01738 630997 www.sepa.org.uk developer requirements we have highlighted that the review of flood risk may indicate the site to be constrained by flood risk with the proposed units being unachievable.

- 1.4 For clarity, from this we have extracted into Table 2 below those which require the developer requirements to be modified. As summarised in that Table, we have requested that the requirements for 64 sites are expanded to address flood risk. We have not requested the removal of any allocations.
- 1.5 Our comments on the proposed allocations relate <u>only</u> to flood risk. As you are aware, you have sought our input on the Expression of Interest allocations as well as a large number of sites submitted to the Council following that exercise, plus additional sites submitted following the Main Issues Report consultation. We have been providing comments in respect of flood risk and the water environment and co location in response to each 'batch' of sites sent to us between December 2011 and May 2015. Many of our comments in respect of flood risk were based on the previous version of SEPA's Flood Maps, which was revised in January 2014. On this basis, we have reviewed all of the housing and employment allocations on the basis of the revised flood map. This has led, in some instances, to our position changing.
- 1.6 As discussed with you at our meeting on 27 October 2015, we have had significant difficulty in responding to the proposed plan due to delays in obtaining robust Geographic Information System (G.I.S.) data although we appreciate the assistance you have given us in this regard. Nevertheless, this has resulted in us not being able to comment at all in respect of the 'Other' development allocations within the Proposed Plan. These allocations have, at this stage, no defined boundary and as such we are unable to comment on the associated flood risk.
- 1.7 Unfortunately this means that in some cases we must attach some uncertainty to the validity of the comments we have provided, both in respect of flood risk and the water environment and with regard to co-location issues (where a site use is proposed within the vicinity of a SEPA-regulated site or vice-versa). To a greater extent, matters of co-location and the water environment are perhaps more readily understood and accommodated by development design/modification and we can attach greater confidence to those sites which have been subject to previous comment as noted above in paragraph 1.5.
- 1.8 In respect of **flood risk** however it is necessary to reserve our position in respect of the viability of developments promoted in the LDP if these have been made without full regard to all information available at this time. In most cases the developer requirement for site-specific FRA, if implemented, to inform layout, density and design will suffice at the development management stage. Furthermore plan policy in respect of flood risk and associated duties under Planning legislation and the FRMA will help to guide development appropriately. However there may be some instances where development capacity is sufficiently compromised by flood risk not identified in the site-assessment process, such that serious questions may arise as to the deliverability of the planned development. In some cases this may mean that we are obliged to object to development management applications with fail to demonstrate compliance with SPP and other guidance/policy.
- 1.9 Our response to the ER also highlights potential difficulty in demonstrating a robust assessment in all the respects above has been carried out and we would welcome the opportunity to meet with you to discuss how best these matters could be resolved.
- 1.10 We have also provided a response to the Strategic Flood Risk Assessment and this is contained within Appendix 2. Our comments in respect of Potentially Vulnerable Areas are

included within Appendix 3. Our response to the Action Programme is contained within Appendix 4.

# 2. Comments applying to multiple allocations within the Proposed Plan

- 2.1 The sites have been assessed against the <u>SEPA Flood Maps</u> (published in January 2014). The flood maps have been produced following a consistent, nationally-applied methodology for catchment areas equal to or greater than 3km<sup>2</sup> using a Digital Terrain Model (DTM) to define river corridors and low-lying coastal land. The maps are indicative and designed to be used as a strategic tool to assess, flood risk at the community level and to support planning policy and flood risk management in Scotland.
- 2.2 The flood risk advice contained in this letter is supplied to you by SEPA in terms of Section 72 (1) of the Flood Risk Management (Scotland) Act 2009 on the basis of information held by SEPA as at the date hereof. It is intended as advice solely to West Lothian Council as Planning Authority in terms of the said Section 72 (1).Our briefing note entitled: Flood Risk Management (Scotland) Act 2009: Flood risk advice to planning authorities outlines the transitional changes to the basis of our advice inline with the phases of this legislation.

It should be noted that we have issued a separate response to the Environmental Report through the SEA Gateway.

If you have any queries relating to this letter, please contact Alasdair Milne on

Yours sincerely

Alasdair Milne Senior Planning Officer Planning Service

# Appendix 1 - SUMMARY OF SEPA REPRESENTATIONS

# Table 1 - Summary of policy representations

Policy	Representation
DES 1 Design Principles	Support
EMG 1 Water Environment	Support and requirement for modification
EMG 2 Flooding	Support and requirement for modification
EMG 3 Sustainable Drainage	Support
EMG 4 Air Quality	Support
ENV 6 Peatland and Carbon Rich	Support
Soils	
ENV 8 Green Network	Support
ENV 11 Protection of the Water	Support
Environment/Coastline and	
Riparian Corridors	
HOU 4 Windfall Housing	Support
Development in Linlithgow and	
Linlithgow Bridge INF 1 Infrastructure Provision and	Current and requirement for modification
Developer Obligations	Support and requirement for modification
MRW 2 Supporting Principles for	Support
Mineral Extraction	oupport
MRW 3 Impediments to Mineral	Support
Extraction	
MRW 7 Waste Management on	Support
Construction Sites	
MRW 8 Waste Management	Support and requirement for modification
Facilities	
MRW 9 Landfill Sites	Support
NRG 1 Climate Chance and	
Sustainability	
NRG 3 Wind Energy Development	Support (but please note our comments in respect of the associated SPG)
NRG 5 Energy and Heat Networks	Support

# Table 2 - summary of allocation representations to be modified

Site Allocations	Representation Type
H-BA 2	No FRA required within developer requirements. We require an FRA which assesses the risk from a potential culverted watercourse which flows through the site. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Site may be constrained due to flood risk hence capacity of 70 may not be achievable.
H-BA 11	No developer requirements for an FRA. <b>We require an FRA</b> and this should assess the risk from the Boghead Burn and small watercourses. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding.

E-BB 5b	No FRA in developer requirements. <b>We require an FRA</b> which assesses the risk from the small watercourses which flow through/ adjacent to the site. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.
	A basic FRA was produced in 2007 by WSP for the larger site. No risk identified. The FRA produced does not appear to consider the risk from small watercourses which were out with the SEPA flood map (i.e. <3km2)
E-BB 5d	No FRA in developer requirements. <b>We require an FRA</b> which assesses the risk from the small watercourses which flow through/ adjacent to the site. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.
E-BL 1	No developer requirements for FRA. <b>We require an FRA</b> which assesses the risk from the small watercourse which potentially flows through the site. Historic maps indicate the presence of a watercourse within the site. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.
H-EC 5	No developer requirements for FRA provided for this site. <b>We require an</b> <b>FRA</b> which assesses the risk from the small watercourse which flows through the site. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Surface water flooding recorded nearby in 2008. No further details
H-EC 9	provided and contact with FPO is recommended. No developer requirements FRA for this site. <b>We require an FRA</b> which assesses the risk from small watercourses which flow through/ adjacent to the site. The site would appear to be sufficiently elevated above the River Almond. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Surface water flooding recorded nearby in 2005.
H-LW 4	No developer requirements for FRA. <b>We require a FRA</b> to determine the flood risk from the small watercourses that run through and adjacent to the site, including the Longhill Burn/West Calder Burn and tributary of Harwood Water. It is likely the majority of the site is developable and site layout and topographic information may be sufficient.

	A FRA was carried out for Rusha guarry in 2008 (carried out by Entec
	Consultants) and included information on realignment of the Longhill Burn
	which runs through part of this site.
H-LW 5	No developer requirements for FRA. We require a FRA should the
-	proposals change from 0877/MSC/09 to locate buildings to low lying areas
	adjacent to watercourses.
	A FRA was carried out for Rusha quarry in 2008 (carried out by Entec
	Consultants) and included information on the Longford Burn which runs
	through the site.
Armadale CDA	No developer requirements for FRA provided for this larger site in
Previous ref CDA LT	proposed plan. Not all of this site is covered by other allocations. We
and CDA LB	require an FRA which assesses the risk from the small watercourses
	which flow through the site. The FRA should consider any structures, e.g.
	culverts/ bridges, which may exacerbate flooding. Review of the surface
	water 1 in 200 year flood map shows that there may be flooding issues
	within the site. This should be investigated further and it is recommended
	that contact is made with the flood prevention officer.
Armadale CDA	No developer requirements for FRA provided for this larger site. Not all of
Previous ref CDA-CS	this site is covered by other allocations. We require an FRA which
	assesses the risk from the small watercourses which flow through the site.
	The FRA should consider any structures, e.g. culverts/ bridges, which may
	exacerbate flooding. Review of the surface water 1 in 200 year flood map
	shows that there may be flooding issues within the site. This should be
	investigated further and it is recommended that contact is made with the flood prevention officer.
Armadale CDA	Our comments for this site are the same as for H- AM 1 namely:
Previous ref CDA-TF	our comments for this site are the same as for the Awrit hamely.
	Developer requirements state: "Site susceptible to flooding. Flood Risk
	Assessment required". Several sections of sewer are also noted as flowing
	through the site and we would recommend that development does not
	take on top or immediately adjacent to this flood risk. Review of the
	surface water 1 in 200 year flood map shows that there may be flooding
	issues within/ adjacent to the site. This should be investigated further and
	it is recommended that contact is made with the flood prevention officer.
Armadale CDA	Our comments for this site are the same as for H-AM 12 namely:
Previous ref CDA -	
SN	Developer requirements mentions "Site susceptible to flooding. Flood Risk
	Assessment required. Water resilient measures required. Small
	watercourses flow through site and these should not be culverted."
	Manual distribution of the <b>FDA</b> should be a side a second s
	We would highlight that the FRA should consider any structures, e.g.
	culverts/ bridges, which may exacerbate flooding. Review of the
	surface water 1 in 200 year flood map shows that there may be flooding
	issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the fleed provention officer
Armadale CDA	it is recommended that contact is made with the flood prevention officer. No developer requirements for FRA provided for this larger site. Not all of
Previous ref CDA-SS	this site is covered by other allocations. We require an FRA which
	assesses the risk from the small watercourse which flows on the boundary
	of the site. In addition, there may be a culverted watercourse going
	through the site which should be investigated. The FRA should consider
	any structures, e.g. culverts, which may exacerbate flooding. Review of the

	surface water 1 in 200 year flood map shows that there may be flooding
	issues within/ adjacent to the site. This should be investigated further and
	it is recommended that contact is made with the flood prevention officer.
H-BA 18	Review of the surface water 1 in 200 year flood map shows that there may
	be extensive flooding issues within the site. This should be investigated
	further and it is recommended that contact is made with the flood
	prevention officer. We require that a DIA is included within the
	developer requirements. Site may be constrained due to surface water
	flood risk issues.
H-BL 3	Developer requirement mentions "Flood Risk Assessment required which
	assesses the flood risk from the Barbauchlaw Burn". The Burn does not
	flow through the site but adjacent to it. Our previous comments were for
	the larger site. We would highlight that the developer requirement should
	consider a flow path should the burn flow onto the road as potentially
	indicated by the surface water flow path. There is a small watercourse
	which was investigated as part of a previous FRA and is a known flood
	risk. This should also be considered.
H-BD 5	Although the shapefiles provided to us by the Council show this allocation,
	it does not appear in the proposed plan. If it is within the Plan, we require
	an FRA which assesses the risk from the small watercourse which flows
	on the boundary of the site. The FRA should consider any structures, e.g.
	culverts, which may exacerbate flooding. Consideration should also be given to the pond on-site. Review of the surface water 1 in 200 year flood
	map shows that there may be flooding issues within the site. This should
	be investigated further and it is recommended that contact is made with
	the flood prevention officer.
Broxburn CDA	No developer requirements are provided for the CDAs but this allocation is
Previous ref EOI-	not within any other development site reference either. We require an
0138g	FRA which assesses the risk from the small watercourse which flows
	along the eastern boundary of the site. Also the canal flows along the
	northern boundary of the site and consultation with Scottish Canals is
	recommended. Review of the surface water 1 in 200 year flood map shows
	that there may be flooding issues within the site. This should be
	investigated further and it is recommended that contact is made with the
	flood prevention officer.
East Calder CDA	No developer requirements for FRA provided for CDAs but parts of this
Previous ref CDA-AD	allocation are development site reference either. We require an FRA
	which assesses the risk from small watercourses which flow through/
	adjacent to the site. The site would appear to be sufficiently elevated
	above the River Almond. The FRA should consider any structures, e.g.
	culverts, which may exacerbate flooding. Review of the surface water 1 in
	200 year flood map shows that there may be flooding issues within the
	site. This should be investigated further and it is recommended that
	contact is made with the flood prevention officer.
	Surface water flooding recorded nearby in 2005. No further details
	provided and contact with FPO is recommended.
East Calder CDA	No developer requirements for FRA provided for CDAs but parts of this
Previous ref CDA-RW	allocation are not within any other development site reference either. <b>We</b>
	require an FRA which assesses the risk from small watercourses which
	flow through/ adjacent to the site. The site would appear to be sufficiently
	elevated above the River Almond. The FRA should consider any

	structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding
	issues within the site. This should be investigated further and it is
	recommended that contact is made with the flood prevention officer.
Livingston CDA	We cannot see this site within the table in the proposed plan. We require
Old ref: CDA-GF	<b>FRA</b> to assess risk to site from Breich Water and River Almond. It is likely
	the majority of the site is developable and site layout and topographic
	information may be sufficient. Review of the surface water 1 in 200 year
	flood map shows that there may be flooding issues within the site. This
	should be investigated further and it is recommended that contact is made
	with the flood prevention officer.
E-LV 1	No developer requirements mentioned in relation to flood risk. We require
	a FRA to assess the flood risk from the small watercourse which runs
	along the western and southern boundary of the site. The impact of
	culverts on flood levels in the watercourse should be considered. Review
	of the surface water 1 in 200 year flood map shows that there may be
	flooding issues in part of the site. This should be investigated further and it
	is recommended that contact is made with the flood prevention officer.
E-LV 11	No developer requirements mentioned in relation to flood risk. FRA
	required to assess risk from small drain to north of site. Given proposed
	site use, basic information likely to be acceptable including site layout and
	levels. Measures to ensure no increased runoff likely to be required.
E-LV 15	Developer requirements mentions "Development must respect location of
	Lochshot Burn and Greenway to south and no buildings within 10m of
	south boundary". We <b>require an FRA</b> to determine the risk to the site from
	the Lochshot Burn and also small watercourses that run along north and
	west boundaries. The majority of the site is likely developable and site
	layout and topographic information may be sufficient. Review of the
	surface water 1 in 200 year flood map shows that there may be flooding
	issues in part of the site. This should be investigated further and it is
<b>E</b> 1.)/ 40	recommended that contact is made with the flood prevention officer.
E-LV 16	Developer requirements mentions "Respect Lochshot Burn and Greenway
	to north". We <b>require a FRA</b> to determine flood risk to the site from the
	Lochshot Burn. The majority of the site is likely developable and site layout
	and topographic information may be sufficient.
E-LV 17	No developer requirements mentioned in relation to flood risk. We <b>require</b>
	<b>a FRA</b> to assess the risk of flooding to the site from the small watercourse to the west of the site. Consideration of flood risk from the pond is also
	advised. It is likely the majority of the site is developable and site layout
	and topographic information may be sufficient. Review of the surface water
	1 in 200 year flood map shows that there may be flooding issues in the
	developed area of Appleton Place and the map may also be indicating a
	pond on site. This should be investigated further and it is recommended
	that contact is made with the flood prevention officer.
E-LV 23	No developer requirements mentioned in relation to flood risk. We <b>require</b>
-	<b>a FRA</b> to determine the flood risk to the site from the Killandean Burn. The
	majority of the site is likely to be developable and site layout and
	topographic information may be sufficient to determine risk. Flood risk from
	the small watercourse issuing to the southwest of the site should also be
	considered.
E-LV 24	No developer requirements mentioned in relation to flood risk. We require
	a FRA to determine the flood risk to the site from the Killandean Burn. The

	majority of the site is likely to be developedale and site loweyt as a
	majority of the site is likely to be developable and site layout and topographic information may be sufficient to determine risk. Flood risk from the small watercourse in the southwest and northeast of the site should also be considered.
E-LV 25	No developer requirements mentioned in relation to flood risk. We <b>require</b> <b>a FRA</b> to determine the flood risk to the site from the Killandean Burn and small drain running through the site. The majority of the site is likely to be developable and site layout and topographic information may be sufficient to determine risk.
E-LV 33	No developer requirements mentioned in relation to flood risk. We <b>require</b> <b>a FRA</b> for the small watercourse on the northern boundary. The majority of the site is likely developable and site layout and topographical information may be sufficient. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues along the east and south parts of the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.
E-LV 34	No developer requirements mentioned in relation to flood risk. We <b>require</b> <b>a FRA</b> for the small watercourses running along the western boundary and through the middle of the site. The impact of culverts on flood levels should be considered.
E-LV 35	No developer requirements mentioned in relation to flood risk. We <b>require</b> <b>a FRA</b> for the small watercourse running through the site (culverted in parts) and also running along the northern boundary. Development should not take place on top of, or immediately adjacent to, culverted watercourses.
E-LV 36	No developer requirements mentioned in relation to flood risk. We <b>require</b> <b>a FRA</b> for the small watercourse on the northern boundary. The majority of the site is likely developable and site layout and topographical information may be sufficient. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues along the east and south parts of the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.
E-LV 42	No developer requirements mentioned in relation to flood risk. We <b>require</b> <b>a FRA</b> for the small watercourse which runs under the Tailend Roundabout adjacent to the site. The SEPA flood map indicates that should the culvert under the roundabout surcharge the site may be impacted. The majority of the site is likely to be developable and site layout and topographic information may be sufficient.
E-LV 43	No developer requirements mentioned in relation to flood risk. We <b>require</b> <b>a FRA</b> for the small watercourse which runs under the Tailend Roundabout adjacent to the site. The SEPA flood map indicates that should the culvert under the roundabout surcharge the site may be impacted. The majority of the site is likely to be developable and site layout and topographic information may be sufficient.
E-LV 45	Developer requirements mentions "Re-alignment of Beugh Burn and integrated SUDS scheme". We would <b>require a FRA</b> to assess the risk to the site from the Beugh Burn and any proposed re-alignment works. A number of small watercourses/drains run through the site and flood risk from these should also be assessed. <b>Developer requirements need to</b> <b>include requirement for FRA as re-alignment should not be</b> <b>undertaken without detailed assessment. Re-alignment works will</b> <b>also require CAR licence.</b>

E-LV 46	Developer requirements mentions "Separation of Linhouse Water and protection of watercourse from surface water contamination". We <b>require</b> <b>a FRA</b> to determine flood risk from the small watercourses that run through the site. This should include any culverted watercourses and no development should take place above these structures. The majority of the site is likely to be developable and site layout and topographical information may be sufficient.
H-LV 2	No developer requirements mentioned in relation to flood risk. We <b>require</b> <b>a FRA</b> to determine flood risk to the site from the small watercourse on the southern boundary of the site.
H-LV 9	Developer requirements mentions "Introduction of water resilience measures required. The site has a history of flooding and retaining runoff. There is a culverted watercourse traversing the site". Although no flood risk identified from SEPA flood maps or historic records, given the comments we would <b>require a FRA</b> to determine the flood risk from the culverted watercourse. There should also be no development above, or immediately adjacent to, a culverted watercourse.
H-LV 29	No developer requirements mentioned in relation to flood risk. We <b>require</b> <b>a FRA</b> to assess the risk to the site from the River Almond. This should consider any impacts of structures i.e. culverts and bridges. FRA has been carried out by Mott MacDonald for Rivers and Fisheries Trusts of Scotland to investigate potential removal of Howden Bridge Weir. This does not extend to full site but indicates potential risk to part of site.
MU6	We cannot locate this site within the table in proposed plan. We <b>require a FRA</b> to assess the flood risk to the site from the small watercourse running along the northern site boundary. Impacts of any structures on flood risk should be considered.
MU4	We cannot locate this site within the table in proposed plan. We <b>require a</b> <b>FRA</b> to assess the flood risk to the site from the small watercourse running along the western site boundary. Impacts of any structures on flood risk should be considered. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues to parts of the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.
MU9	We cannot locate this site within the table in the proposed plan. We require a FRA to assess the flood risk to the site from the small watercourse running through the site. This appears to be partly culverted and the Impacts of any structures on flood risk should be considered.
Old ref: LIV31	We cannot locate this site within the table in proposed plan. We <b>require a FRA</b> to assess the flood risk to the site from the small watercourse running along the northern site boundary. Impacts of any structures on flood risk should be considered. Same site as MU5?
MU1	We cannot locate this site within the table in proposed plan. We <b>require a FRA</b> to assess the flood risk to the site from the River Almond and the tributary to the south of the site.
MU7	We cannot locate this site within the table in proposed plan. We <b>require a</b> <b>FRA</b> to assess the flood risk to the site from the small watercourse running along the northern site boundary. Impacts of any structures on flood risk should be considered.
MU5	We cannot locate this site within the table in proposed plan. We <b>require a FRA</b> to assess the flood risk to the site from the small watercourse running

	along the northern site boundary. Impacts of any structures on flood risk
	should be considered. Review of the surface water 1 in 200 year flood map
	shows that there may be flooding issues to parts of the site. This should
	be investigated further and it is recommended that contact is made with
	the flood prevention officer.
Old ref: COU35	We cannot locate this site within the table in proposed plan and could find
	no reference. May possibly be a culverted watercourse running through
	site and if so would require FRA to assess flood risk. Further information
	required as to existence of culvert
Old ref: LC1	We cannot locate this site within the table in proposed plan and could find
	no reference We <b>require a FRA</b> to assess the risk to the site from the
	small watercourse (tributary of Murieston Water) running through site and
	also Murieston Water adjacent to eastern site boundary. The impact of
	structures i.e. culverts and bridges, on flood levels should be considered.
Polbeth CDA	No developer requirements noted in proposed plan relating to flood risk.
Old ref: CDA-MO	We <b>require a FRA</b> to determine flood risk to site from Breich Water and
	West Calder Burn. We previously commented on LIVE/0349/FUL/11 and
	LIVE/0875/FUL/14 and had no objection as the sites did not encroach on
	the functional floodplain. This larger site includes area immediately
	adjacent to the watercourses. It is likely the majority of the site is
	developable and site layout and topographic information may be sufficient.
	SEPA have river gauging station on Breich Water adjacent to site.
Polbeth CDA Old ref: CDA-CB	No developer requirements noted in proposed plan relating to flood risk.
	We <b>require a FRA</b> to determine flood risk to site from the West Calder
	Burn. It is likely the majority of the site is developable and site layout and
	topographic information may be sufficient. Report of surface water flooding
H-LW 1	adjacent to site in July 2007. No developer requirements mentioned relating to flood risk. We <b>require a</b>
	<b>FRA</b> for the small watercourse running through the site. It is likely the
	majority of the site is developable and site layout and topographic
	information may be sufficient.
H-PB 2	Not mentioned in settlements in proposed plan relating to flood risk. We
	require FRA to assess risk to site from West Calder Burn. Site layout and
	topographical information may be sufficient.
E-LW 3	No developer requirements assigned with this allocation relating to flood
	risk. A <b>flood risk assessment is required</b> as outlined within our
	responses on previous allocationsEWc1 & EOI-0164. Review of the
	surface water 1 in 200 year flood map shows that there may be flooding
	issues within/ adjacent to the site. This should be investigated further and
	it is recommended that contact is made with the flood prevention officer.
E-LW 4	No developer requirements assigned with this allocation relating to flood
	risk. A <b>flood risk assessment is required</b> as outlined within our
	responses on previous allocationsEWc4 & EOI-0164. Review of the
	surface water 1 in 200 year flood map shows that there may be flooding
	issues within/ adjacent to the site. This should be investigated further and
	it is recommended that contact is made with the flood prevention officer.
E-WH 1	This allocation is not within the proposed plan supporting document dated
	October 2015. Flood risk is extremely complex in this area and a
	detailed assessment would be required. We provided comments on an
	application, 0493/P/02, for the erection of an office and yard
H-WH 3	No developer requirements assigned to this allocation for flood risk. Flood
	risk assessment is required to assess the risk from the numerous small

	watercourses flowing through the development site. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues
	within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention
Winchburgh CDA Old ref: CDA-GS	This CDA allocation has been commented on within allocations H-WB 07 to 10. No developer requirements assigned to this allocation in relation to flood risk.
Winchburgh CDA Old ref: CDA-GN	No developer requirements assigned to this allocation in relation to flood risk. <b>We would require a flood risk assessment.</b> Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The site lies adjacent to the Union Canal and contact should be made with Scottish Canal to ensure there is no residual risk of flooding
Winchburgh CDA Old ref: CDA-NS	Part of the CDA allocation has been commented on within allocations H- WB13. No developer requirements assigned to this allocation and we require a flood risk assessment
Winchburgh CDA Old ref: CDA-MS	No developer requirements assigned to this allocation in relation to flood risk. We <b>require a flood risk assessment</b> is carried out. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. We have commented on this CDA on allocations H WB 05 and H WB 06.
Winchburgh CDA Old ref: CDA-NN	No developer requirements assigned to this allocation in relation to flood risk. We <b>require a flood risk assessment</b> is carried out.
Winchburgh CDA Old ref: CDA-CP	No developer requirement relating to flood risk. We comment on this CDA on allocation H WB 4. A pond is located within the site and it is possible that the outflow from this watercourse is culverted beneath the site. The surface water and fluvial flood map are solely identifying the pond. A <b>FRA</b> <b>is required</b> and should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding.
E-WB 2	The developer requirements state that a flood risk assessment and drainage impact assessment are <u>possibly</u> required. The developer requirements are insufficient and a <b>FRA is required</b> . There is a small watercourse which flows along the northern boundary of the site. The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding.

# Appendix 2 – SEPA Comments on Strategic Flood Risk Assessment

We have reviewed the Strategic Flood Risk Assessment document and would offer the following comments:

# Section 1.2

• The punctuation in the sentence starting "*the council is mindful*" requires to be amended as it is an important sentence which as it stands, does not read well.

# Section 1.8

- We would recommend that this section could be made clearer by deleting the sentence which starts "*In identifying sites for inclusion*...", since the sites which <u>do</u> require mitigation are covered in the sentence which follows.
- Replace 'mitagtory' with 'mitigatory'
- Add 'informed by a satisfactory Flood Risk Assessment' following 'standoffs to watercourses for example'
- Within the sentence which starts 'SEPA and the council may request', delete 'large' as allocations could be any size and require a Flood Risk Assessment.

### Section 2.4

• With regard to the sentence which starts 'Where high rates of runoff', we would suggest additional text 'Such natural flood management can have a positive effect on downstream flooding but cannot be wholly relied upon to facilitate development on sites previously at risk from such flooding'.

### Section 4.1

• Within the sentence which starts 'To provide a baseline' we recommend that this be modified to read 'new development <u>or redevelopment'</u>.

# Heading for Section 6

• Typo in 'supplementary'

# <u>Appendix 3 - Potentially Vulnerable Area (PVA) details for allocations which fall</u> within a PVA

In December 2011, SEPA published the National Flood Risk Assessment (NFRA) required by the Flood Risk Management (Scotland) Act 2009. The NFRA identifies areas that are potentially vulnerable to flood risk (Potentially Vulnerable Areas or PVAs). This information does not imply that all sites within a PVA are subject to flood risk.

The NFRA datasets will in future help to support Flood Risk Management Planning by 2015. Development Plans in future will require to have regard to Flood Risk Management Plans.

We have considered the strategic information in the FRMA with respect to PVA locations within the development plan area and would advise that the location of this Development Plan is within the following PVA's and the key information available in the FRMA for these PVAs includes:

# PVA 10/13

- Summary of main impacts Assessment of future flood risk and past events shows that the River Avon and several burns present: impact to a large number of residential properties; limited impact to low category community facilities; impact to some commercial properties; limited impact to transport links; impact to extensive areas of high grade agricultural land and impact to extensive areas of sensitive designated sites, with frequent reports of flooding in the area between 1771 and 2009. Existing defences on Mains Burn offer partial protection to some of these impacts.
- Main sources of flood risk fluvial and pluvial
- Number of existing properties currently at risk 932

### PVA 10/14

- Summary of main impacts Assessment of future flood risk and past events shows small watercourses present: limited impact to transport links; impact to high grade agricultural land; impact to sensitive designated sites, with infrequent reports of flooding in the area provided.
- Main sources of flood risk fluvial and pluvial
- Number of existing properties currently at risk 6

### PVA 10/15

- Summary of main impacts Assessment of future flood risk and past events shows fluvial and coastal sources present: impact to a small number of commercial properties; impact to minor transport links; limited impact to agriculture and impact to sensitive designated sites, with past reports of flooding in the area.
- Main sources of flood risk fluvial, coastal and pluvial
- Number of existing properties currently at risk 49

### PVA 10/27

- Summary of main impacts – Assessment of future flood risk and past events shows that the River Almond, Gogar Burn and small watercourses present: impact to a large number of residential properties; limited impact to low category community facilities; impact to a large number of commercial properties; impact to major transport links; impact to extensive area of high grade agricultural land and impact to extensive areas of sensitive designated sites, with frequent reports of flooding in the area between 1836 and 2010. Existing defences on Brox Burn offer partial protection to some of these impacts.

- Main sources of flood risk fluvial and pluvial
- Number of existing properties currently at risk 1651

Any locations within a Development Plan outwith a PVA, should not be assumed to be free from flood risk. SEPA has produced the NFRA as the first stage of the Flood Risk Management Planning process. This sub-catchment area is not included as a PVA because it is below the threshold of significance of the NFRA/PVA method.

# Appendix 4 – SEPA Response to Draft Action Programme



Our ref: PCS143108 Your ref:

If telephoning ask for: Alasdair Milne

20 November 2015

Fiona McBrierty Planning and Economic Development West Lothian Civic Centre Howden Road South Livingston EH54 6FF

By email only to: <a href="mailto:wlldp@westlothian.gov.uk">wlldp@westlothian.gov.uk</a>

Dear Fiona

# West Lothian Local Development Plan – Draft Action Programme

Thank you for your consultation letter of 9 October 2015. We welcome the opportunity to comment on the Action Programme (AP) document which, once formally adopted, will form part of the Local Development Plan (LDP). We recognise that the AP is not intended to be read in isolation and that the information relating to any site should be read in conjunction with the proposal details in the West Lothian LDP allocations. We recommend that our comments below be taken into account in the finalising of the AP.

We note page 13 of the Action Programme contains a range of other actions which will be identified as the LDP moves forward. From this table it is clear that the Action Programme as it relates to policies is to be developed further. We would welcome the opportunity to assist with this in the coming months.

- The types of action that we would expect to be included would be the delivery of key infrastructure and the preparation of supplementary guidance. Actions are not limited to those by the planning authority and we would expect to be identified as a delivery partner, but not lead, for specific actions.
- We would highlight that actions must link to the delivery of the policies and proposals in the plan or mitigation proposed in the SEA. We do not require actions to be included that have no link to the policies and proposals or SEA. Examples of actions that we may want to see included in the APPs (subject to policy/proposal link) are presented below:
  - Developer requirements for allocated sites relating to our interests eg. flood risk, river basin planning, zero waste.

- Statutory supplementary guidance to deliver the detail of policy areas relating to our remit such as flood risk, renewable energy developments, waste management and/or river basin planning interests.
- Delivery of flood management measures including food prevention schemes (and natural flood management measures) required to enable delivery of the proposals in the plan.
- Plans for the local delivery of green infrastructure requirements. This may include statutory supplementary guidance on how green and blue networking will be taken forward in the LDP area, the economic advantages and multiple benefits in terms of Council objectives.
- o Deliver mitigation measures identified through the SEA process
- Heat mapping of plan area to identify potential heat sources for new development (as per Policy NRG 5 in the Proposed Plan).

Whilst we note that West Lothian Council recognise that the document is a 'working document', we recommend that the document be seen as a 'live' document rather than be reviewed every 2 years. More regular reviews (such as quarterly or 6 monthly reviews) could be undertaken. This does not mean that a new AP is required to be published on the passing of each review date but rather the AP can be identified as a living electronic document on the authority website which will contain the most up-to-date position of the plan at that moment in time. This will allow the AP to be seen as a progressive/project management document and allow all interested parties to be made aware of the most up-to-date position for any given area at any given time.

Finally, we note confirmation within the Proposed Plan supporting documents that a range of Supplementary Guidance will be produced in the coming months— we would welcome the opportunity to comment on these documents at an early stage in their production and look forward to continuing to work closely with West Lothian Council in this regard.

If you have any queries relating to this letter, please contact me by telephone on

Yours sincerely

Alasdair Milne Senior Planning Officer Planning Service

14-20 A delevel Notains Construction Place 16-20 A delevel Notains 16-20 A d															
	•		Site Use	Site Name		Eastings N	•	medium to high risk of flooding (Within or adjacent to indicative 1 in	less than 3km2 hence no n modelled in Indicative	t allocation could increase the probability of	SEPA holds e.g. historic record of flooding from f any source / post flood survey / Approved Local Authority or SEPA Flood	present and current	comments including aspects for consideration in site specific FRA e.g. structures complicate flood risk at site including bridges, culverts etc. Please identify where appropriate FR relevant development requirements are attached in order that we can support these in	support the relevan development requirements in	it 1
			Employment - ext to										Assessment required." We would require an FRA which assesses the risk from the small watercourse which flows through the site. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended		
$ 1 \times 1 $				Muirhousedykes Mains (previously							Surface water flooding to nearby property in 2007. No further details provided and contact with FPO is		No FRA required in developer requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Adjacent site (H-AD 03) mentions significant groundwater issues. The council may wish to confirm this issue does not affect		N
14.02       Appleade       Non-transmission       Non-transmission </td <td>Π-Αυ Ι</td> <td>Addieweii</td> <td>Housing</td> <td>Known as Ross Court Minor)</td> <td>ΗΑΦ</td> <td>298,148</td> <td>661,938 NO</td> <td>Sunace water – part</td> <td>INDITE</td> <td>ΝΟ</td> <td>Surface water flooding to nearby property in 2007. No further details provided and contact</td> <td>None known</td> <td>Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the small watercourses that flow through the site." The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Site will likely be constrained due to flood risk hence capacity of</td> <td>Tes</td> <td>N</td>	Π-Αυ Ι	Addieweii	Housing	Known as Ross Court Minor)	ΗΑΦ	298,148	661,938 NO	Sunace water – part	INDITE	ΝΟ	Surface water flooding to nearby property in 2007. No further details provided and contact	None known	Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the small watercourses that flow through the site." The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Site will likely be constrained due to flood risk hence capacity of	Tes	N
<ul> <li>A driverel</li> <li>Notice di location</li> <li>A driverel</li> <li>Notatione</li> <l< td=""><td>H-AD 2</td><td>Addiewell</td><td>Housing (capacity 20)</td><td>Meadowhead Avenue north</td><td>HAd7</td><td>299,059</td><td>662,442 No</td><td>Surface water – part</td><td>going through site</td><td>Yes</td><td>recommended. Surface water flooding to nearby property in 2007. No further details</td><td>None Known</td><td>wish to consider removal of allocation. Developer requirements mentions "Significant</td><td>Yes</td><td>N</td></l<></ul>	H-AD 2	Addiewell	Housing (capacity 20)	Meadowhead Avenue north	HAd7	299,059	662,442 No	Surface water – part	going through site	Yes	recommended. Surface water flooding to nearby property in 2007. No further details	None Known	wish to consider removal of allocation. Developer requirements mentions "Significant	Yes	N
<ul> <li>h.0 dieleel</li> <li>h.0 diel</li></ul>	H-AD 3	Addiewell	Housing	Loganlea Road	LATE-0008	298,185	662,083 No	No	None	No	with FPO is	None Known	required." We do not have any more info on this risk. Developer requirements mentions "Flood Risk	Yes	N
<ul> <li> <ul> <li></li></ul></li></ul>	H-AD 4	Addiewell	Housing	Loganlea Crescent / Place	HAd4	298,551	662,472 No	Fluvial - small part	None	Yes	No	None Known	the western boundary of the site." We would note that the Skolie Burn flows along eastern	Yes	N
Inger site. Not all of this site is covered by         orther allocations. We would require an FRA         Commented on this site       which assesses the site meal         previously (PCS113394,       watercourses which flow through the site.         PCS101746, PCS111914,       The FRA should consider any structures, e.g.         0451/P/09) and although       cuterts/bridge, which meay exacerbate         we revould       flooding. Review, which meay exacerbate         objection to some of the       year flood map shows that there may be         phased development we       objection to some of the       year flood map shows that there may be         phased development we       notestanget       investigated further and it is recoinsemended         Surface water – small       multiple watercourses       objection to parts of the       that contact is made with the flood prevention		Armadale	CDA			294,386	667,657 10/13	Surface water – part	going through site	Yes	this site as part of Lower Bathville/ Armadale Station consultations (PCS103067, PCS107089, PCS140231, PCS106741, 1044/P/08, 0893/P/08,	None Known	larger site in proposed plan. Not all of this site is covered by other allocations. We would require an FRA which assesses the risk from the small watercourses which flow through the site. The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the		N
		Armadale	CDA		CDA-CS	294,544	669,001 10/13		•	Yes	previously (PCS113394, PCS101716, PCS111914, 0451/P/09) and although we removed our objection to some of the phased development we have an outstanding objection to parts of the	None Known	larger site. Not all of this site is covered by other allocations. We would require an FRA which assesses the risk from the small watercourses which flow through the site. The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention		Ν

# . MODIFICATION TO PLAN: Recommend removal from plan

1. MODIFICATION TO PLAN: Assessment of flood risk required (sought by developer requirement)

No No

No No

No No

No No No No

Yes No

No Yes

		CDA CDA		CDA-TF CDA-SN		667,212 10/13 668,619 10/13	Surface water – small part Surface water – small part	-		C C	None Known None Known	Same as H-AM 1 same as H-AM 12 No developer requirements provided for this	
,	Armadale	CDA		CDA-NH	293,683	667,293 part 10/13	Surface water – small part	adjacent to site		We commented on parts of this site (PCS132400, PCS129084, PCS131005) as part of the Armadale Station development and associated phased development.	None Known	larger site. Not all of this site is covered by other allocations. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. No developer requirements provided for this	
	Armadale	CDA		CDA-SS	292,679	668,224 10/13	Surface water – small part	t culverted through site	Yes	Νο	None Known	larger site. Not all of this site is covered by other allocations. We require an FRA which assesses the risk from the small watercourse which flows on the boundary of the site. In addition, there may be a culverted watercourse going through the site which should be investigated. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
E-AM 1	Armadale	Employment	Tarreoch Farm	CDA-TF	294,876	666,968 10/13	Surface water – part	multiple watercourses through site		We commented on parts of this site (PCS106741) as part of the Armadale Station development and associated phased development and removed our objection subject to conditions.	None Known	Developer requirements mentions a "Flood Risk Assessment and Drainage Assessment required, use existing ponds where possible." We require an FRA which assesses the risk from the Boghead Burn and tributaries (and ponds) which flow through the site. The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes
E-LV 47	Armadale	Employment		CDA-AN & EOI- 0013	302,055	666,747 no	Surface water / fluvial – small part	on boundary	Yes	Νο	None Known	Developer requirements mentions "River Almond to south, possible requirement for Flood Risk Assessment and Drainage Impact Assessment." The FRA should also take into account any small watercourses within/ adjacent to the site. The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. For clarity and consistency, the council may wish to stipulate that an FRA is required rather than a possible requirement.	Yes
1-AM 1	Armadale	Housing	Muirfield North Street	HAm8	293,880	668,950 10/13	Surface water – adjacent	None	Yes	Νο	None Known	Developer requirements mentions "Site susceptible to flooding. Flood Risk Assessment required". Several sections of sewer are also noted as flowing through the site and we would recommend that development does not take on top or immediately adjacent to this flood risk. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes
1-AM 2	Armadale	Housing	Heatherfield West	HAm10	294,569	668,737 10/13	Surface water – part	adjacent to site	Yes	Νο	None Known	Developer requirements mentions "Flood Risk Assessment required." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes

No Yes No Yes

No No

No Yes

No No

No No

No No

No No

												flooding in 2007. Flood Risk Assessment required." Review of the surface water 1 in	
												200 year flood map shows that there may be flooding issues within/ adjacent to the site.	
												This should be investigated further and it is	
												recommended that contact is made with the flood prevention officer. We previously state	Ч
												that no FRA required as we did not have	
H-AM 3	Armadale	Housing	Nelson Park / Mallace Ave	HAm12c	294,462	668,514 10/13	Surface water – part	None	Yes	No	None Known	additional flood risk information.	Yes
												No FRA required in developer requirements. Cant find any record of previous consultation	
H-AM 4	Armadale	Housing	High Academy Street		293,565	668,377 10/13	No	None	No	No	None Known	on this site.	Yes
												Developer requirements mentions "Site	
										Commented on this as		susceptible to flooding Flood Risk Assessmen required." The FRA should consider any	t
										part of Colinshiel Farm (PCS101716, 0451/P/09)		structures, e.g. culverts/ bridges, which may	
										and have an outstanding		exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there	9
										objection to the larger site but phases have		may be flooding issues within/ adjacent to the	
										been approved as out		site. This should be investigated further and it is recommended that contact is made with the	
H-AM 5	Armadale	Housing	Colinshiel Site A CDA		294,486	669,076 10/13	Surface water – small par	t going through site	Yes	with flood risk area.	None Known	flood prevention officer.	Yes
												Developer requirements mentions "Site	
										Commented on this as part of Colinshiel Farm		susceptible to flooding Flood Risk Assessmen required." The FRA should consider any	t
										(PCS101716, 0451/P/09)		structures, e.g. culverts/ bridges, which may	
										and have an outstanding		exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there	e
										objection to the larger site but phases have		may be flooding issues within/ adjacent to the site. This should be investigated further and it	
										been approved as out		is recommended that contact is made with the	;
H-AM 6	Armadale	Housing	Colinshiel site B CDA		294,774	669,013 10/13	Surface water – small pa	t going through site	Yes	with flood risk area.	None Known	flood prevention officer.	Yes
												Developer requirements mentions "Site	
												susceptible to flooding. Flood Risk Assessmer required." The FRA should consider any	nt
												structures, e.g. culverts/ bridges, which may	
												exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that	
												there may be flooding issues within/ adjacen	t
												to the site. This should be investigated	
H-AM 7	Armadale	Housing	Tarrareoch Southdale		294,243	667,438 10/13	Surface water – part	on boundary	Yes	No	None Known	further and it is recommended that contact is made with the flood prevention officer.	Yes
		-											
												Developer requirements mentions "Site susceptible to flooding. Flood Risk Assessmer	nt
												required." The FRA should consider any	
										We commented on this site as part of the larger		structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface	
										Armadale Station		water 1 in 200 year flood map shows that	
										application (PCS140231, PCS132400) and		there may be flooding issues within/ adjacent to the site. This should be investigated	t
										removed objection		further and it is recommended that contact is	
H-AM 8	Armadale	Housing	Tarrareoch remainder		294,321	667,396 10/13	Surface water – part	on boundary	Yes	subject to conditions.	None Known	made with the flood prevention officer.	Yes
												Developer requirements mentions "Flood Ris	k
												Assessment required. Drainage Impact Assessment required to assess the impact of	
												development on the local network." Review of	of
										Commented on the larger site previously		the surface water 1 in 200 year flood map shows that there may be flooding issues	
										(PCS111061) and noted		within to the site. This should be investigated	
H-AM 9	Armadale	Housing	Netherhouse Phase 1 R1A		293,740	667,121 part 10/13	Surface water – small par	rt None	Yes	the risk from small drainage ditches.	None Known	further and it is recommended that contact is made with the flood prevention officer.	Yes
		U			-,		<b>/</b>			<u>.</u>			
												Developer requirements mentions "Flood Ris Assessment required. Drainage Impact	k
												Assessment required to assess the impact of	
												development on the local network." Review of the surface water 1 in 200 year flood map	of
										Commented on the		shows that there may be flooding issues	
										larger site previously (PCS111061) and noted		adjacent to the site. This should be investigated further and it is recommended	
							Surface water – adjacent			the risk from small		that contact is made with the flood prevention	n
H-AM 10	Armadale	Housing	Netherhouse Phase 1 RB		293,582	667,193 part 10/13	to	on boundary	Yes	drainage ditches.	None Known	officer.	Yes
												Developer requirements mentions "Flood Ris	k
												Assessment required. Drainage Impact	
												Assessment required to assess the impact of development on the local network." Review	
										Commented on the site		of the surface water 1 in 200 year flood map	
										previously (PCS132400 and part of PCS131005,		shows that there may be flooding issues within/ adjacent to the site. This should be	
										PCS129084) and did not		investigated further and it is recommended	
H-AM 11	Armadale	Housing	Netherhouse remainder		293,761	667,316 10/13	Surface water – small par	rt None	Yes	identify any small watercourses.	None Known	that contact is made with the flood prevention officer.	n Yes
		U			-,	, -	<b>-</b>						

No No No

Developer requirements mentions "Record of flooding in 2007. Flood Risk Assessment

No

No No

No No

No

No

No

No No

No

No

No

No

No

$ 1.441 \ 15 \ Analb \ 16 \ Analb \ 16 \ Analb \ 16 \ 16 \ 16 \ 16 \ 16 \ 16 \ 16 \ 1$	H-AM 12	Armadale	Housing	Standhill north	0	292,645	668,624 10/13	Surface water – small part	going through site	Yes	Νο	None Known	Developer requirements mentions "Site susceptible to flooding. Flood Risk Assessment required. Water resilient measures required. Small watercourses flow through site and these should not be culverted." The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	r w ie o
<ul> <li>International and a state of the state of th</li></ul>	H-AM 13	Armadale	Housing	Standhill south		292 662	668 258 10/13	Surface water – small part	going through site	Ves	Νο	None Known	this site (close to the A89) is deemed at risk from pluvial flooding. Flood Risk Assessment required which assesses the flood risk from the small watercourses which flows through the site" The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood	o is
4 M2       Austile       Hearing       Task Am       2658       6.812 3 2013       5.885 (12)       Austile       Ye       Austile	H-AIVI 13	Armadale	Housing	Standnin South		292,662	008,258 10/13	Sunace water – Smail part	going through site	res	NO	None Known		res
Ansale       Nova       New factor       New factor       Solid restruction of the set	H-AM 14	Armadale	Housing	Trees Farm		294.508	667,218 10/13	Surface water – part	on boundary	Yes	majority of this site as part of Armadale Station (PCS104357, PSC106741, 1044/P/08) except for the small western corner which is not part of the masterplan. We removed our objection subject to conditions to be provided at the		Assessment required. Drainage Impact Assessment required". Same as CDA-TF. The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood preventior	<u>5</u>
H-M/25     Amade     Hours, Low Edubrie     234.46     66/30.430/12     Buffatz water pair     pier brough uit						- ,			,					
H-MU125       Annable       Housing       Martield Drive       AM8       253.558       668.222 50/13       Suffice setter - adjoornel       Suffice setter - adjoornel       Suffice setter - adjoornel       Suffice setter - adjoornel       None       Yes         H-MU126       Annable       Housing       Boorneling Fam       253.558       668.222 50/13       Suffice setter - adjoornel       None       Yes       Suffice setter - function file       None       Yes         H-MU126       Annable       Housing       Boorneling Fam       253.558       668.222 50/13       Suffice setter - adjoornel       None       Yes       None	H-AM 15	Armadale	Housing	Lower Bathville		294.448	667.814 10/13	Surface water – part	going through site	Yes	this site as part of Lower Bathville consultations (PCS103067, PCS107089, 0893/P/08) and removed our objection subject to		to flooding. Flood Risk Assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood	
H-M 15       Anade       Houing       Mayled Dive       ABM       23.55       652.20 10/13       Sufface water - adjacent       Yes       Hou reference       Hou reference <t< td=""><td>11710113</td><td>Armadule</td><td>Trousing</td><td></td><td></td><td>234,440</td><td>007,014 10/15</td><td></td><td>Sourte through site</td><td></td><td>conditions.</td><td></td><td>Developer requirements mentions "Drainage</td><td></td></t<>	11710113	Armadule	Trousing			234,440	007,014 10/15		Sourte through site		conditions.		Developer requirements mentions "Drainage	
HAM 17 A Made Housing Drove Road E04:0139 293,73 10/13 Sufface water - angleceri HAM 18 A madele Housing Sterrage Sterage Sterrage Sterrage Sterrage Sterrage Sterrage Sterrage Sterrag	H-AM 16	Armadale	Housing	Mayfield Drive	ARM8	293,958	668,220 10/13		None	Yes	nearby area in 2007. No further details provided and contact with FPO is		surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the	it
H-AM 17       Armadale       Housing       Drove Road       EDI-0139       293,737       10/13       Surface water - small part going through site       Yes       recommended.       None Known       Provide recommended part with the real part going through site       Yes         H-AM 18       Armadale       Housing       Busing       Stonerigg Farm       293,424       667,667       part 10/13       Surface water - adjacent       No       No       No       No       No       No       No       No       Yes											nearby property in 2008. No further details		Assessment required which assesses the flood risk from the Barbauchlaw Burn and the Colin Burn". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to	0
H-AM 18       Armadale       Housing       Stonerigg Farm       293,424       667,667 part 10/13       to       adjacent to site       No       No       None Known       or adjacent to the site.       Yes         Image Inpact Application Interpreted WaterCourses and Investigate Whether Interpreted WaterCourses within Interpreted WaterCourses w	H-AM 17	Armadale	Housing	Drove Road	EOI-0139	293,737	10/13	Surface water – small part	going through site	Yes	with FPO is	None Known	recommended that contact is made with the flood	Yes
same reference. Only one allocation mentioned in Proposed Plan developer requirements. Developer requirements mentions "Flood Risk Assessment required." Drainage Impact Assessment required." FRA should consider the potential risk from nearby watercourses and investigate whether there are any culverted watercourses within	H-AM 18	Armadale	Housing	Stonerigg Farm		293,424	667,667 part 10/13		adjacent to site	Νο	Νο	None Known	same reference. Only one allocation mentioned in Proposed Plan developer requirements. Developer requirements mentions "Flood Risk Assessment required. Drainage Impact Assessment required" The FRA should consider the potential risk from nearby watercourses and investigate whether there are any culverted watercourses within	Yes
Surface water – adjacent there are any culverted watercourses within													same reference. Only one allocation mentioned in Proposed Plan developer requirements. Developer requirements mentions "Flood Risk Assessment required. Drainage Impact Assessment required". The FRA should consider the potential risk from	
	H-AM 18	Armadale	Housing	Stonerigg Farm		293,390	667,583 part 10/13	-	adjacent to site	No	No	None Known	there are any culverted watercourses within	Yes

H-AM 12	Armadale	Housing	Standhill north	0	292,645 668,624 10/13	Surface water – small part going through site	Yes	Νο	None Known	Developer requirements mentions "Site susceptible to flooding. Flood Risk Assessment required. Water resilient measures required. Small watercourses flow through site and these should not be culverted." The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
H-AM 13	Armadale	Housing	Standhill south		292,662 668,258 10/13	Surface water – small part going through site	Yes	Νο	None Known	Developer requirements mentions "A small part of this site (close to the A89) is deemed at risk from pluvial flooding. Flood Risk Assessment required which assesses the flood risk from the small watercourses which flows through the site" The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
H-AIVI 13	Armaŭale	Housing	Standhin South		292,002 008,238 10/13	Sunace water – sman part going through site	Tes	NO	None known	fes	
	Armadalo	Housing	Troos Form		204 509 667 219 10/12	Surface water – part – on boundary	Voc	Have commented on the majority of this site as part of Armadale Station (PCS104357, PSC106741 1044/P/08) except for the small western corne which is not part of the masterplan. We removed our objection subject to conditions to be provided at the	n ″ r	Developer requirements mentions "Flood Risk Assessment required. Drainage Impact Assessment required". Same as CDA-TF. The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer	
H-AM 14	Armadale	Housing	Trees Farm		294,508 667,218 10/13	Surface water – part on boundary	Yes	detailed stage.	None Known	officer. Yes	
H-AM 15	Armadale	Housing	Lower Bathville		294,448 667,814 10/13	Surface water – part going through site	Yes	Commented on areas of this site as part of Lower Bathville consultations (PCS103067, PCS107089 0893/P/08) and remove our objection subject to conditions.	r , d	Developer requirements mentions "Site susceptible to flooding. Flood Risk Assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Yes	
	, i madule				251,110 007,011 10,15					Developer requirements mentions "Drainage	
H-AM 16	Armadale	Housing	Mayfield Drive	ARM8	293,958 668,220 10/13	Surface water – adjacent to None	Yes	Surface water flooding t nearby area in 2007. No further details provided and contact with FPO is recommended.	)	Impact Assessment required." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.Yes	
								Surface water flooding t nearby property in 2008 No further details provided and contact		Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the Barbauchlaw Burn and the Colin Burn". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be investigated further and it is	
H-AM 17	Armadale	Housing	Drove Road	EOI-0139	293,737 10/13	Surface water – small part going through site	Yes	with FPO is recommended.	None Known	recommended that contact is made with the flood prevention officer.	
H-AM 18	Armadale	Housing	Stonerigg Farm		293,424 667,667 part 10/	Surface water – adjacent 13 to adjacent to site	No	No	None Known	Two allocations in Proposed Plan with the same reference. Only one allocation mentioned in Proposed Plan developer requirements. Developer requirements mentions "Flood Risk Assessment required. Drainage Impact Assessment required" The FRA should consider the potential risk from nearby watercourses and investigate whether there are any culverted watercourses within or adjacent to the site. Yes	
										Two allocations in Proposed Plan with the same reference. Only one allocation mentioned in Proposed Plan developer requirements. Developer requirements mentions "Flood Risk Assessment required. Drainage Impact Assessment required". The FRA should consider the potential risk from	
H-AM 18	Armadale	Housing	Stonerigg Farm		293,390 667,583 part 10/	Surface water – adjacent 13 to adjacent to site	No	No	None Known	nearby watercourses and investigate whether there are any culverted watercourses within or adjacent to the site. Yes	

No No

No No

No No No No

No No No No

No No

E-BB 2	Bathgate	Employment	Inchmuir road, whitehill ind est	EBb2	298,433	667,105 10/27	Surface water – adjacent to	culverted through site	Yes	Νο	None Known	Developer requirements mentions "Flood Risk Assessment and Drainage Assessment required." The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	:
E-BG 1	Bathgate	Employment	Easter Inch	EBg2	298,895	667,175 10/27	Surface water – part	None	Yes	Νο	None Known	No FRA required within developer requirements. There is a pond shown on site which may be attributed to SUDS but should be investigated during site design. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes
E-BG 1	Baingate	Employment	Easter inch	ЕВД2	298,895	667,175 10/27	Sunace water – part	None	res	No	None known	No FRA required within developer requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Due to extent of surface water flooding on site, the council may wish to	1
E-BG 2	Bathgate	Employment	Inch wood south	EBg3	299,000	667,643 10/27	Surface water – part	None	Yes	No	None Known	include a DIA in the developer requirements. No FRA required within developer requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention	ı
E-BG 3	Bathgate	Employment	Wester inch	EBg9	297,412	667,085 10/13 and 10/27	Surface water – small par	t None	Yes	No	None Known	officer.	Yes
H-BA 1	Bathgate	Housing	Balmuir Road	2/106	296,291	669,630 10/13	Fluvial - part	on boundary	Yes	Surface water flooding to nearby property in 2001 and 2003. No further details provided and contact with FPO is recommended. FRA provided in 2008 (0128/SRM/08) and we removed our objection subject to conditions. Should we be consulted on a new application for this site we would require the submission o an updated FRA.		Developer requirements mentions "Site susceptible to flooding. Flood Risk Assessment required." The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Site may be constrained due to flood risk.	Yes
												No FRA required within developer requirements. We would require an FRA which assesses the risk from a potential culverted watercourse which flows through the site. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Site may be constrained due to flood risk hence capacity of 70 may not be	
H-BA 2	Bathgate	Housing	Wester inch	2/66(20)	298,400	667,316 10/27	Surface water – part	culverted through site	Yes	No	None Known		No
Н-ВА 3	Bathgate	Housing	Standhill site A	Δ	296 765	667,408 10/13	Surface water – majority	multiple watercourses through site	Yes	FRA undertaken for a larger site (PCS119369) shows that a significant part of the northern half of the site is at fluvial risk. We removed our objection based on the site layout shown. Should the layout differ from 0841/MSC/11 we would require an updated FRA.	None Known	Developer requirements mentions "Flood Risk Assessment required". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Site will likely be constrained due to flood risk.	
C AUTH	Datiigate	nousing		0	230,703	υυτ, του 10/15	Canade water - majointy	anough and	103	αρυαιου ΓΝΑ.			103

-BB 2	Bathgate	Employment	Inchmuir road, whitehill ind est	EBb2	298,433	667,105 10/27	Surface water – adjacent to	culverted through site	Yes	Νο	None Known	Developer requirements mentions "Flood Risk Assessment and Drainage Assessment required." The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	t
-BG 1	Bathgate	Employment	Easter Inch	EBg2	298,895	667,175 10/27	Surface water – part	None	Yes	Νο	None Known	No FRA required within developer requirements. There is a pond shown on site which may be attributed to SUDS but should be investigated during site design. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes
-BG 2	Bathgate	Employment	Inch wood south	EBg3	299,000	667,643 10/27	Surface water – part	None	Yes	Νο	None Known	No FRA required within developer requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Due to extent of surface water flooding on site, the council may wish to include a DIA in the developer requirements. No FRA required within developer	t I
-BG 3	Bathgate	Employment	Wester inch	EBg9	297,412	667,085 10/13 and 10/27	Surface water – small part	None	Yes		None Known	requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	ł
-BA 1	Bathgate	Housing	Balmuir Road	2/106	296,291	669,630 10/13	Fluvial - part	on boundary		Surface water flooding to nearby property in 2001 and 2003. No further details provided and contact with FPO is recommended. FRA provided in 2008 (0128/SRM/08) and we removed our objection subject to conditions. Should we be consulted on a new application for this site we would require the submission of an updated FRA.	None Known	Developer requirements mentions "Site susceptible to flooding. Flood Risk Assessment required." The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Site may be constrained due to flood risk.	Yes
DA 2	Pathgata	Housing	Westerinsh	2/66/20)	208 400	667 216 10/27	Surface water – part	culverted through site	Vac	Νο	Nono Known	No FRA required within developer requirements. We would require an FRA which assesses the risk from a potential culverted watercourse which flows through the site. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Site may be constrained due to flood risk hence capacity of 70 may not be	ı
-BA 2	Bathgate	Housing	Wester inch	2/66(20)	298,400	667,316 10/27	Surface water – part	culverted through site		FRA undertaken for a larger site (PCS119369) shows that a significant part of the northern half of the site is at fluvial risk. We removed our objection based on the site layout shown. Should the layout differ from 0841/MSC/11 we	None Known	achievable. Developer requirements mentions "Flood Risk Assessment required". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the	
-BA 3	Bathgate	Housing	Standhill site A	0	296,765	667,408 10/13	Surface water – majority	multiple watercourses through site	Yes	would require an updated FRA.	None Known	flood prevention officer. Site will likely be constrained due to flood risk .	Yes

E-BB 2	Bathgate	Employment	Inchmuir road, whitehill ind est	EBb2	298,433	667,105 10/27	Surface water – adjacent to	culverted through site	Yes	Νο	None Known	Developer requirements mentions "Flood Ris Assessment and Drainage Assessment required." The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be investigated further and is recommended that contact is made with the flood prevention officer.	it
E-BG 1	Bathgate	Employment	Easter Inch	EBg2	298,895	667,175 10/27	Surface water – part	None	Yes	Νο	None Known	No FRA required within developer requirements. There is a pond shown on site which may be attributed to SUDS but should be investigated during site design. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
E-BG 2	Bathgate	Employment	Inch wood south	EBg3	299,000	667,643 10/27	Surface water – part	None	Yes	No	None Known	No FRA required within developer requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommender that contact is made with the flood prevention officer. Due to extent of surface water flooding on site, the council may wish to include a DIA in the developer requirements. No FRA required within developer	ed on
E-BG 3	Bathgate	Employment	Wester inch	EBg9	297,412	667,085 10/13 and 10/27	Surface water – small pa	rt None	Yes	No	None Known	requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommende that contact is made with the flood preventio officer.	ed
H-BA 1	Bathgate	Housing	Balmuir Road	2/106	296,291	669,630 10/13	Fluvial - part	on boundary	Yes	Surface water flooding to nearby property in 2001 and 2003. No further details provided and contact with FPO is recommended. FRA provided in 2008 (0128/SRM/08) and we removed our objection subject to conditions. Should we be consulted on a new application for this site we would require the submission of an updated FRA.		Developer requirements mentions "Site susceptible to flooding. Flood Risk Assessment required." The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Site may be constrained due to flood risk.	
	Detherts	Ugusing	Worter	2/((/20)	200.400		Surface water port	outworted through site	Ver	Na	Nexes Kreaus	No FRA required within developer requirements. We would require an FRA which assesses the risk from a potential culverted watercourse which flows through the site. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Site may be constrained due to flood risk hence capacity of 70 may not be	e on
H-BA 2	Bathgate	Housing	Wester inch	2/66(20)	298,400	667,316 10/27	Surface water – part	culverted through site	Yes	No FRA undertaken for a larger site (PCS119369) shows that a significant part of the northern half of the site is at fluvial risk. We removed our objection based on the site layout shown. Should the layout differ from 0841/MSC/11 we	None Known	achievable. Developer requirements mentions "Flood Risk Assessment required". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the	ne
H-BA 3	Bathgate	Housing	Standhill site A	C	) 296,765	667,408 10/13	Surface water - majority	multiple watercourses through site	Yes	would require an updated FRA.	None Known	flood prevention officer. Site will likely be constrained due to flood risk .	Yes

<ul> <li>k k</li> <li>k k</li> <li>k k k k</li> <li>k k k</li> <lik k="" k<="" li=""> <li>k k k k</li> <li>k k k</li> <li>k</li></lik></ul>	-	Е-ВВ 2	Bathgate	Employment	Inchmuir road, whitehill ind est	EBb2	298,433	667,105 10/27	Surface water – adjacent to	culverted through site	Yes	Νο	None Known	Developer requirements mentions "Flood Ris Assessment and Drainage Assessment required." The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be investigated further and is recommended that contact is made with the flood prevention officer.	it
<ul> <li>Reg B</li> <li></li></ul>		E-BG 1	Bathgate	Employment	Easter Inch	EBg2	298,895	667,175 10/27	Surface water – part	None	Yes	Νο	None Known	No FRA required within developer requirements. There is a pond shown on site which may be attributed to SUDS but should be investigated during site design. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
$\left[ -16.5 \right] \left[ \log \left[ $		E-BG 2	Bathgate	Employment	Inch wood south	EBg3	299,000	667,643 10/27	Surface water – part	None	Yes	Νο	None Known	requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Due to extent of surface water flooding on site, the council may wish to include a DIA in the developer requirements. No FRA required within developer	ed on
H2A 1 Baltane Hooing H		E-BG 3	Bathgate	Employment	Wester inch	EBg9	297,412	667,085 10/13 and 10/27	Surface water – small par	t None	Yes	Surface water flooding to		in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommende that contact is made with the flood prevention	ed
H-BA 2 Bathgate Housing Wester inch 2/66/201 298,400 667,316 10/27 Surface water - part culverted through sile Yes No Nore Known achievable.		H-BA 1	Bathgate	Housing	Balmuir Road	2/106	296,291	669,630 10/13	Fluvial - part	on boundary	Yes	and 2003. No further details provided and contact with FPO is recommended. FRA provided in 2008 (0128/SRM/08) and we removed our objection subject to conditions. Should we be consulted on a new application for this site we would require the submission of		recommended that contact is made with the flood prevention officer. Site may be constrained due to	
larger site (PCS119369)       shows that a significant         shows that a significant       part of the northern half         of the northern half       beveloper requirements mentions "Flood Rinks"         risk. We removed our       Assessment required". The FRA should cor         objection based on the       any structures, e.g. culverts, which may exa         site layout shown.       flood may show the thur enge befolding         food may show the third of the own own own should there own own should there own own should the investigated       flood may show the thur enge befolding         for own own of Mar(MSC/11 we       within the site. This should be investigated       within the site. This should be investigated         multiple watercourses       would require an       flood prevent own officer. Site will likely be cor		Н-ВА 2	Bathgate	Housing	Wester inch	2/66(20)	298,400	667,316 10/27	Surface water – part	culverted through site	Yes	Νο	None Known	requirements. We would require an FRA which assesses the risk from a potential culverted watercourse which flows through the site. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Site may be constrained due to flood risk hence capacity of 70 may not be	e
H-BA 3 Bathgate Housing Standhill site A 0 296,765 667,408 10/13 Surface water – majority through site Yes updated FRA. None Known due to flood risk .		Н-ВА 3	Bathgate	Housing	Standhill site A	٥	296 765	667 408 10/13	Surface water – majority	multiple watercourses through site	Yes	larger site (PCS119369) shows that a significant part of the northern half of the site is at fluvial risk. We removed our objection based on the site layout shown. Should the layout differ from 0841/MSC/11 we	None Known	Developer requirements mentions "Flood Risk Assessment required". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with th flood prevention officer. Site will likely be constrained due to flood risk.	he

-BB 2	Bathgate	Employment	Inchmuir road, whitehill ind est	EBb2	298,433	667,105 10/27	Surface water – adjacent to	culverted through site	Yes	Νο	None Known	Developer requirements mentions "Flood Risk Assessment and Drainage Assessment required." The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	t
-BG 1	Bathgate	Employment	Easter Inch	EBg2	298,895	667,175 10/27	Surface water – part	None	Yes	Νο	None Known	No FRA required within developer requirements. There is a pond shown on site which may be attributed to SUDS but should be investigated during site design. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes
-BG 2	Bathgate	Employment	Inch wood south	EBg3	299,000	667,643 10/27	Surface water – part	None	Yes	Νο	None Known	No FRA required within developer requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Due to extent of surface water flooding on site, the council may wish to include a DIA in the developer requirements. No FRA required within developer	t I
-BG 3	Bathgate	Employment	Wester inch	EBg9	297,412	667,085 10/13 and 10/27	Surface water – small part	None	Yes		None Known	requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	ł
-BA 1	Bathgate	Housing	Balmuir Road	2/106	296,291	669,630 10/13	Fluvial - part	on boundary		Surface water flooding to nearby property in 2001 and 2003. No further details provided and contact with FPO is recommended. FRA provided in 2008 (0128/SRM/08) and we removed our objection subject to conditions. Should we be consulted on a new application for this site we would require the submission of an updated FRA.	None Known	Developer requirements mentions "Site susceptible to flooding. Flood Risk Assessment required." The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Site may be constrained due to flood risk.	Yes
DA 2	Pathgata	Housing	Westerinsh	2/66/20)	208 400	667 216 10/27	Surface water – part	culverted through site	Vac	Νο	Nono Known	No FRA required within developer requirements. We would require an FRA which assesses the risk from a potential culverted watercourse which flows through the site. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Site may be constrained due to flood risk hence capacity of 70 may not be	ı
-BA 2	Bathgate	Housing	Wester inch	2/66(20)	298,400	667,316 10/27	Surface water – part	culverted through site		FRA undertaken for a larger site (PCS119369) shows that a significant part of the northern half of the site is at fluvial risk. We removed our objection based on the site layout shown. Should the layout differ from 0841/MSC/11 we	None Known	achievable. Developer requirements mentions "Flood Risk Assessment required". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the	
-BA 3	Bathgate	Housing	Standhill site A	0	296,765	667,408 10/13	Surface water – majority	multiple watercourses through site	Yes	would require an updated FRA.	None Known	flood prevention officer. Site will likely be constrained due to flood risk .	Yes

H-BA 3	Bathgate	Housing	Standhill site A	0	296,765	667,408 10/13	Surface v

No No

# No No

No No No

No No

No Yes

										Previous FRA undertaken			
										for part of this site			
										mentions flooding problems associated with			
										a culvert. Significant			
										flooding was witnessed			
										associated with the			
										smaller watercourse in			
										the development site.			
										Ponding to a depth of 2m			
										was experienced on part of the development site			
										with a flood level of			
										147.0mAOD. It is		Developer requirements mentions "Flood Ris	k
										explained within the FRA		Assessment required". The FRA should	
										that this was due to the		consider any structures, e.g. culverts, which	
										culvert inlet for this small		may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows	
										watercourse being blocked which resulted in		that there may be flooding issues within the	
										floodwater backing up		site. This should be investigated further and	it
										causing significant		is recommended that contact is made with th	
H-BA 4	Bathgate	Housing	Standhill site B		296,948	667,051 10/13	Surface water – part	going through site	Yes	Ũ	None Known	flood prevention officer.	Yes
										Surface water flooding to		Developer requirements mentions "There is a histor	ry
										nearby property in 1999. No further details		of flooding. Flood Risk Assessment required.	
										provided and contact		Drainage Impact Assessment required to assess th impact of development on the local network". The	ne
				HBg24 & EOI-						with FPO is		FRA should consider any structures, e.g. culverts,	
H-BA 5	Bathgate	Housing	Napier Ave	0163	298,147	668,732 10/13 and 10/27	No	on boundary	Yes	recommended.	None Known	which may exacerbate flooding.	Yes
												Developer requirements mentions "Site susceptible	9
										Basic FRA submitted for part of site (PCS133426)		to flooding. Flood Risk Assessment required which	
										mentions risk from		assesses the flood risk from the Bathgate Water which flows along the eastern and northern	
										adjacent culverted		boundary of the site. Drainage Impact Assessment	
										watercourse. 2004		required to assess the impact of development on the local network." Commented on small part of site and	
										response for this site		objected due to a lack of information. FRA should	u
	Dathaata	Housing	Faster Dead Delmuin Dead	110-20	206 724		Surface water / fluvial –	adia aant ta sita	Vec	requested additional	None Known	also consider the risk from adjacent small	Vec
H-BA 6	Bathgate	Housing	Easton Road Balmuir Road	HBg29	296,724	669,358 10/13	small part	adjacent to site	Yes	modelling as well.	None Known	watercourse as well.	Yes
												Developer requirements mentions "Flood Risk Assessment required. Drainage Impact Assessmer	nt
												required. High level of SUDS required since low	
												dilution. There is a history of nearby flooding from obstructed culvert. There is a possible risk from	
												adjacent bodies of water in nature park". We have	
												and fourth and information and flaged with the second state	
												no further information on flood risk. The comments	6
												we previously provided were for the larger site (HBg30) which this site is part of. The council may	
	Detherate	Usurisa		HBg30(remainin	206 242		Surface water – adjacent	Nega		Na		we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain	,
H-BA 7	Bathgate	Housing	Little boghead remainder	HBg30(remainin g)	296,243	667,807 10/13	Surface water – adjacent to	None	No	Νο	None Known	we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.	
H-BA 7	Bathgate	Housing	Little boghead remainder		296,243	667,807 10/13		None	No	No	None Known	we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable. Developer requirements mentions "Flood Risk	Yes
H-BA 7	Bathgate	Housing	Little boghead remainder		296,243	667,807 10/13		None	No	No	None Known	<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and</li> </ul>	Yes
H-BA 7	Bathgate	Housing	Little boghead remainder		296,243	667,807 10/13		None	No	No	None Known	<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration."</li> </ul>	Yes
H-BA 7	Bathgate	Housing	Little boghead remainder		296,243	667,807 10/13		None	No	No	None Known	<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme tha has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the</li> </ul>	y Yes at
H-BA 7	Bathgate	Housing	Little boghead remainder		296,243	667,807 10/13		None	No	No	None Known	<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme tha has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is</li> </ul>	y Yes at
H-BA 7	Bathgate	Housing	Little boghead remainder		296,243	667,807 10/13		None	No	No	None Known	<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The comments previously</li> </ul>	y Yes at
H-BA 7	Bathgate	Housing	Little boghead remainder		296,243	667,807 10/13		None	No	No	None Known	<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The comments previously provided were for a larger site allocation (HBg39).</li> </ul>	y Yes at
				g)			to					<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The comments previously</li> </ul>	y Yes at
H-BA 7 H-BA 8	Bathgate	Housing	Little boghead remainder Wester Inch Area S		296,243 297,329	667,807 10/13 667,527 10/13 and 10/27		None	No Yes		None Known	<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk</li> </ul>	Yes Yes Yes
				g)			to					<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that</li> </ul>	Yes Yes Yes
				g)			to					<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk</li> </ul>	Yes at Yes
			Wester Inch Area S	g)			to					<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The comments previously provided were for a larger site</li> </ul>	Yes at Yes
H-BA 8	Bathgate	Housing	Wester Inch Area S Wester Inch area x y z aa, wester	g) 2/66(15)	297,329	667,527 10/13 and 10/27	to Surface water – part	None	Yes	No	None Known	<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The</li> </ul>	Yes At Yes
			Wester Inch Area S	g)			to	None		No		<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> </ul>	Yes at Yes
H-BA 8	Bathgate	Housing	Wester Inch Area S Wester Inch area x y z aa, wester	g) 2/66(15)	297,329	667,527 10/13 and 10/27	to Surface water – part	None	Yes	No	None Known	<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk</li> </ul>	Yes Yes Yes Yes
H-BA 8	Bathgate	Housing	Wester Inch Area S Wester Inch area x y z aa, wester	g) 2/66(15)	297,329	667,527 10/13 and 10/27	to Surface water – part	None	Yes	No	None Known	<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and</li> </ul>	Yes Yes Yes Yes
H-BA 8	Bathgate	Housing	Wester Inch Area S Wester Inch area x y z aa, wester	g) 2/66(15)	297,329	667,527 10/13 and 10/27	to Surface water – part	None	Yes	No	None Known	<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration".</li> </ul>	Yes At Yes Yes At
H-BA 8	Bathgate	Housing	Wester Inch Area S Wester Inch area x y z aa, wester	g) 2/66(15)	297,329	667,527 10/13 and 10/27	to Surface water – part	None	Yes	No	None Known	<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and</li> </ul>	Yes At Yes Yes At Yes
H-BA 8	Bathgate	Housing	Wester Inch Area S Wester Inch area x y z aa, wester	g) 2/66(15)	297,329	667,527 10/13 and 10/27	to Surface water – part	None	Yes	No	None Known	<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration".</li> <li>Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is</li> </ul>	Yes At Yes Yes At Yes
H-BA 8	Bathgate	Housing	Wester Inch Area S Wester Inch area x y z aa, wester	g) 2/66(15)	297,329	667,527 10/13 and 10/27	to Surface water – part	None	Yes	No	None Known	<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood</li> </ul>	Yes At Yes Yes At Yes
H-BA 8	Bathgate	Housing	Wester Inch Area S Wester Inch area x y z aa, wester	g) 2/66(15)	297,329 297,132	667,527 10/13 and 10/27	to Surface water – part	None	Yes	No	None Known	<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration".</li> <li>Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is</li> </ul>	Yes At Yes Yes At Yes
H-BA 8 H-BA 9	Bathgate	Housing	Wester Inch Area S Wester Inch area x y z aa, wester grove	g) 2/66(15)	297,329 297,132	667,527 10/13 and 10/27	to Surface water – part Surface water – small par	None t None	Yes	No	None Known None Known	<ul> <li>we previously provided were for the larger site (HBg30) which this site is part of. The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration." Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". The comments previously provided were for a larger site allocation (HBg39). The council may wish to consider whether these comments remain applicable.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Flood alleviation scheme that has been developed needs taken account of and protected. SUDs needs careful consideration". Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Site may be constrained due to</li> </ul>	Yes Ati Yes Yes Yes Ati

No No No

No No

No

No No No No

No No

										We commented on this			
										site during the approval of matters (0589/MSC/1			
										for 0972/P/01) and an	.4		
										FRA was submitted. The	2		
										FRA demonstrates that			
										the eastern edge is at ri	sk		
										of flooding. Should the			
										application differ from			
										what has been approved		No developer requirements for an EDA The	
										already we would requi an updated FRA which	re	No developer requirements for an FRA. The FRA should assess the risk from the Boghead	
										assesses the risk from th	ie.	Burn and small watercourses. The FRA should	1
										Boghead Burn and smal		consider any structures, e.g. culverts, which	
H-BA 11	Bathgate	Housing	Wester Inch phase 3	2/66(19)	296,904	667,704 10/13	Fluvial - small part	adjacent to site	Yes	watercourse.	None Known	may exacerbate flooding.	No
							Surface water – adjacent					Developer requirements mentions "Drainage Impac	t
H-BA 12	Bathgate	Housing	Main st	HBg43b	297,527	669,180 10/13	to	None	No	No	None Known	Assessment required to assess the impact of development on the local network".	Yes
	-	-		-									
										We commented on site		Developer requirements mentions "Drainage Impac	t
										and did not identify a		Assessment required to assess the impact of	
					207 400					flood risk (PCS142424,	<b>N</b> <i>V</i>	development on the local network".	
H-BA 13	Bathgate	Housing	Jarvey St	HBg45	297,483	669,084 10/13	No	None	No	0645/FUL/15)	None Known		Yes
												Developer requirements mentions "This site include a low area at risk of pluvial flooding. Flood Risk	es
												A low area at risk of pluvial flooding. Flood Risk Assessment required". We require an FRA which	
										Surface water flooding t	0	assesses the risk from a potentially culverted	
										nearby property in 2007	<b>'</b> .	watercourses within or immediately adjacent to the site. Review of the surface water 1 in 200 year flood	
										No further details		map shows that there may be flooding issues within	
										provided and contact		the site. This should be investigated further and it i	
	Dathgata	Housing	Minduknowe east		206.022	669 660 10/12	Surface water – small par	rt on houndary	Vac	with FPO is	None Known	recommended that contact is made with the flood prevention officer.	Vac
H-BA 14	Bathgate	Housing	Windyknowe east	HBg47a	296,022	668,660 10/13	Sunace water – Sman par	It off boundary	Yes	recommended.	None Known		Yes
												Developer requirements mentions "Flood risk	< Comparison of the second sec
												assessment required". Review of the surface	
												water 1 in 200 year flood map shows that	
												there may be flooding issues within the site.	
												This should be investigated further and it is	
												recommended that contact is made with the	
												flood prevention officer. We do not have any	
												additional flood risk information. The comments previously provided were for a	
												larger site allocation (HBg47). The council	
												may wish to consider whether these	
H-BA 15	Bathgate	Housing	windyknowe west	HBg47b	295,872	668,671 10/13	Surface water - part	None	Yes	No	None Known	comments remain applicable.	Yes
	-	-		-									
										We have records of		Developer requirements mentions "Flood risk	
										commenting on the		assessment required". The FRA should	
										larger site which		consider the upstream storage structures. We	
	Dathaata	Heusing	M/bithuma Del Cita A		0 207 220	CC0 174 10/12	Surface water / fluvial –	adia aant ta sita	Vac	surrounds this one		have only commented on the larger site	Yes
H-BA 16	Bathgate	Housing	Whitburn Rd Site A		0 297,338	668,174 10/13	adjacent to	adjacent to site	Yes	(PCS125775, PCS120983	). None known	previously.	165
										We commented on this		Developer requirements mentions "Flood risk	ĸ
										site (PCS125775,		assessment required". Should the	
										PCS120983,		development differ from what was previously	1
										0070/MSC/12). The		agreed we would require the submission of a	n
										council confirmed that		updated FRA which considers the upstream	
										the council maintain the	2	storage areas and small watercourses,	
										upstream storage areas A study undertaken by		including any culverted watercourses which may exacerbate flooding. Review of the	
										Entec for the council an	d	surface water 1 in 200 year flood map shows	
										provides a flood outline		that there may be flooding issues within the	
										adjacent to the western		site. This should be investigated further and i	it
							Surface water / fluvial –			perimeter of the		is recommended that contact is made with the	
H-BA 17	Bathgate	Housing	Whitburn Rd Site B		0 297,378	668,067 10/13	small part	going through site	Yes	allocation.	None Known	flood prevention officer.	Yes
												map shows that there may be extensive	1
												flooding issues within the site. This should be	
												investigated further and it is recommended that	t
												contact is made with the flood prevention officer. Would recommend that a DIA is	
												included within the developer requirements.	
												Site may be constrained due to surface water	
H-BA 18	Bathgate	Housing	9 Hardhill Road	2/109	296,490	668,670 10/13	Surface water – majority	None	Yes	No	None Known	flood risk issues.	No
												Developer receiver and the light	
												Developer requirements mentions "SUDs scheme required". Review of the surface	
												water 1 in 200 year flood map shows that	
												there may be flooding issues adjacent to the	
												site. This should be investigated further and i	it
							Surface water – adjacent					is recommended that contact is made with the	
H-BA 19	Bathgate	Housing	Bloomfield Place	2/110	297,539	668,779 10/13	to	None	Yes	No	None Known	flood prevention officer.	Yes
	Dathaata	Housing	Mid Ctroot		207 692	660 702 10/12	No	Nono	No	No	Nono Known	No FRA requested in doublener requirements	Vec
H-BA 20	Bathgate	Housing	Mid Street	EOI-0056	297,682	668,703 10/13	No	None	No	No	None Known	No FRA requested in developer requirements	Yes

No Yes No No

No No

No

No No

No No No Yes

No No No No

No No

No

	Developer requirements mentions "Site is at medium to high risk of fluvial flooding. Flood Risk Assessment required. Water resilient measures also required for this site". Should the proposal differ
We commented on this site (PCS113883, 0093/FUL/08 & Surface water / fluvial - H-BA 21 Bathgate Housing Meadowpark 13 - 15 Glasgow Rd EOI-0162 296,960 668,826 10/13 part adjacent to site Yes larger site. Non	from what was previously agreed we would require an FRA which assess the risk from the Boghead Burn and the small watercourse. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Yes
H-BA 22 Bathgate Housing Bathgate Commediucation COU23 297,732 668,875 10/13 No None No No Non	one Known No FRA requested in developer requirements Yes
Surface water / fluvial -	Developer requirements mentions "Site susceptible to pluvial and fluvial flooding. Flood Risk Assessment required". The FRA should assess the risk from the Boghead Burn and tributaries. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Site may be constrained due to
H-BA 23 Bathgate Housing Wester inch EOI-0182 297,039 667,955 10/13 part adjacent to site Yes No Non	one Known flood risk. Yes
H-BA 24 Bathgate Housing Guildiehaugh Depot EOI-0153 298,424 667,948 10/27 Surface water – part None Yes No Non	Developer requirements mentions "Site susceptible to pluvial flooding. Flood risk assessment required. Drainage Impact Assessment required to assess the impact of development on the local network". Previous comments from SEPA mentioned we did not require an FRA but the FPO has requested an FRA to address the pluvial flood risk. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.
	Developer requirements mentions "Part of the site is
H-BA 25 Bathgate Housing Waverley St depot EOI-0094 297,267 669,138 10/13 No None No No Non	Developer requirements mentions       Part of the site is susceptible to pluvial flooding. Flood Risk assessment required. Drainage Impact Assessment required to assess the impact of development on the local network". We have no additional information on the flood risk to the site. We previously stated this.         one Known       Yes
	Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the Bog Burn which flows through the site". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Site may be constrained as we would not support development over or immediately adjacent to a
	One known       res         Developer requirements mentions "Flood Risk       Assessment required to determine the full extent of land capable of being developed". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that
H-BA 27 Bathgate Housing Whitburn Road LATE-0014 296,325 667,385 10/13 Surface water – part going through site Yes No Non	one Known contact is made with the flood prevention officer. Yes Developer requirements mentions "Drainage Impact Assessment required to assess the impact of
H-BA 28 Bathgate Housing Mid Street former swimming pool MIRQLATE4 297,729 668,742 10/13 Surface water – small part None Yes No Non	one Known development on the local network". No further Yes
	Developer requirements mentions "Flood Risk Assessment required". Should the proposal differ from what was previously agreed we would require an FRA which assesses the risk from the Boghead Burn. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Yes
Surface water / fluvial –	
	one Known Site not within Proposed Plan. Iow vulnerability use. Not within Proposed one Known Plan
Flooding of garden	Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the small watercourse which flows along the south-eastern corner of the site. Water resilient measures are required". Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention

Surface water – small part on boundary

Yes

H-SB 4 Bents BEN1 297,126 662,273 No Burnlea Place Housing

Flooding of garden ground from field surface water (Nov 2009) None Known

Yes

that contact is made with the flood prevention

officer. Looks to be built already.

No No No No No No

No No No No

No No No No No

No No

No No

No

E-BB 5c	Blackburn	Employment			296,748	666,362 10/13 and 10/27	Surface water – small par	t on boundary	Yes	A basic FRA was produced in 2007 by WSP for the larger site. No risk identified. The FRA produced does not appear to consider the risk from small watercourses which were out with the SEPA flood map (i.e. <3km2)	None Known	No FRA in developer requirements. Historic maps indicate there may be a small watercourse in the vicinity of the site. This should be considered during site investigations. We have no further flood risk information. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
												Developer requirements mentions "Flood Risk Assessment and Drainage Assessment required". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the	
E-BB 1	Blackburn	Employment		EBb1	297,611	666,485 10/27	Surface water – part	on boundary	Yes	No	None Known	flood prevention officer. No FRA in developer requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is	Yes
E-BB 3	Blackburn	Employment		EBb4		666,345 part 10/27	Surface water – small par		Yes	No	None Known	made with the flood prevention officer. NO FRA requested within developer requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention	
E-BB 4	Blackburn	Employment		EBb5	298,264	666,528 part 10/27	Surface water – part	None	Yes	No A basic FRA was produced in 2007 by WSP for the larger site. No risk identified. The FRA produced does not appear to consider the risk from small watercourses which were	None Known	No FRA in developer requirements. Historic maps indicate there may be a small watercourse in the vicinity of the site. This should be considered during site	Yes
E-BB 5a	Blackburn	Employment			296,414	666,482 10/13	Surface water – part	adjacent to site	Yes	out with the SEPA flood map (i.e. <3km2) A basic FRA was produced in 2007 by WSP for the larger site. No risk identified. The FRA produced does not appear to consider the risk from small watercourses which were out with the SEPA flood	None Known	<ul> <li>investigations. We have no further flood risk information.</li> <li>No FRA in developer requirements. We require an FRA which assesses the risk from the small watercourses which flow through/adjacent to the site. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the</li> </ul>	Yes
E-BB 5b	Blackburn	Employment			297,224	666,817 10/13 and 10/27	Surface water – part	going through site	Yes	A basic FRA was produced in 2007 by WSP for the larger site. No risk identified. The FRA produced does not appear to consider the risk from small watercourses which were out with the SEPA flood	None Known	flood prevention officer. No FRA in developer requirements. We require an FRA which assesses the risk from the small watercourses which flow through/ adjacent to the site. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the	No
E-BB 5d	Blackburn	Employment			296,819	666,074 part 10/27	Surface water – part Surface water – adjacent	through site	Yes	map (i.e. <3km2)	None Known	flood prevention officer. Developer requirements mentions "Flood Risk and Drainage Assessment required, stand-off also required to be agreed with SEPA to Latch Burn south of the site." The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be investigated further and it is recommended that contact is made	No
E-BB 6	Blackburn	Employment	West Main St	BLA3	297,778	665,320 No	to Surface water – adjacent	on boundary	Yes	No Surface water flooding experienced in general	None Known		Yes
H-BB 1	Blackburn	Housing	daisyhill road	HBb2	298,699	665,533 No	to	None	Yes	area.	None Known	issues at this site.	Yes

No No

No No

No No No No

No

No

No Yes No Yes

No No No No

Н-ВВ 2	Blackburn	Housing	riddochhill road	HBb6	297,994	665,567 No	Fluvial - part	on boundary	Yes	Νο	None Known	Developer requirements mentions "Part of the site susceptible to pluvial flooding. Flood risk assessment required which assesses the flood risk from the River Almond which is immediately to the west of the site. Drainage Impact Assessment required and to determine the extent to which the site is capable of being developed". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Site will likely be constrained due to flood risk.	k ,
Н-ВВ 3	Blackburn	Housing	west main st west	HBb10		665,435 No	Fluvial - adjacent to	None	Yes	No	None Known	Developer requirements mentions "There is recent history of flooding adjacent to the site. Flood Risk Assessment required. Drainage Impact Assessme required to assess the impact of development on t local network". We previously did not request an FRA and have no further information on flooding.	ent
							Surface water / fluvial –					Developer requirements mentions "There is recent history of flooding. Flood Risk Assessment require Drainage Impact Assessment required to assess t impact of development on the local network". We previously did not request an FRA and have no further information on flooding. Review of the surfa water 1 in 200 year flood map shows that there ma be flooding issues adjacent to the site. This shoul be investigated further and it is recommended that contact is made with the flood prevention officer.	ed. he ace ay d
H-BB 4	Blackburn	Housing	west main st east	HBb11	298,440	665,431 No	adjacent to	None	Yes	No	None Known	Developer requirements mentions "Drainage	Yes
H-BB 5	Blackburn	Housing	16 bathgate road	HBb18	298,554	665,559 No	No	None	No	No	None Known	Impact Assessment required".	Yes
Н-ВВ б	Blackburn	Housing	11 east main st	EM1	298,695	665,423 No	Surface water – adjacent to	None	Yes	Νο	None Known	No developer requirements requested. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. As adjacent to a potential flood risk issue may wish to consider during design.	
										We commented on a larger site (PCS136305, 1695/FUL/14) with the boundary following the River Almond. Housing was set back and elevated above river by a minimum of 5m. We had no objection subject to		"The site is susceptible to flooding. Flood Risk Assessment required. Development will only be permitted in that part of the site deemed to be out with the fluvial flood zone". The current allocation slightly smaller than what was previously commented upon. The council may wish to consid whether these comments remain applicable.	is
H-BB 7	Blackburn	Housing	redhouse west	EOI-0095	299,268	665,324 No	Surface water – small par	t None	Yes	conditions.	None Known		Yes
												Developer requirements mentions "Nearby surface water/water ponding issues recorded in 2008 and 2009." No FRA or DIA mentione	
H-BB 8 H-BB 9	Blackburn Blackburn	Housing Housing	west main street ash grove site a	BLA31 EOI-0185a	298,861 298,664	665,492 No 665,734 No	No No	None None	No No	No No	None Known None Known	in developer requirements. No developer requirements.	Yes Yes
H-BB 10	Blackburn	Housing	ash grove site b	EOI-0185b	298,743	665,741 No	No	None	No	No	None Known	No developer requirements.	Yes
H-BB 11	Blackburn Blackburn	Housing Retail		HBb16 BLA7	298,760 298,705	666,331 10/27 665,790 No	Surface water – part No	None None	Yes No	No No	None Known None Known	Not in proposed plan. Not in proposed plan.	
E-BL 1	Blackridge	Employment	sibbald training centre 1	EOI-0007	291,434	667,675 10/13	Surface water – small par	t culverted through site	Yes	Νο	None Known	No developer requirements. We require an FRA which assesses the risk from the small watercourse which potentially flows through the site. Historic maps indicate the presence of a watercourse within the site. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and is recommended that contact is made with the flood prevention officer.	ne it
E-BL2	Blackridge	Employment	sibbald trainaing centre 2	EOI-0008	291,464	667,385 10/13	Surface water – part	None	Yes	No	None Known	No developer requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and is recommended that contact is made with th flood prevention officer. The council may wis to consider including the surface water risk in the developer requirements. Developer requirements mentions "Flood Risk Assessment required which assesses the flood ris	it he sh n Yes
H-BL 1		Housing	allison gdns site a	HBr5a		666,902 10/13	Surface water / fluvial – small part	None		Νο	None Known	from the Barbauchlaw Burn which flows through the site". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review o the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Over half built already.	ne j. f

No No No No No No

No No No No No No No No No No

No Yes

					200.077		Surface water – adjacent		Maria	Nie		Assessment required which assesses the flood risk from the Barbauchlaw Burn which flows through the site". Burn does not flow through the site but adjacent to. Our previous comments were for the larger site. May wish to consider a flow path should the burn flow onto the road as potentially indicated by the surface water flow path.	Y.
H-BL 2	Blackridge	Housing	allison gdns site b	HBr5d	289,877	666,823 10/13	to	None	Yes	No FRA undertaken in 2005 which mentions flooding on site and to adjacent property. Investigated a small ditch along the	None Known	Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the Barbauchlaw Burn". Burn does not flow through the site but adjacent to. Our previous comments were for the larger site. May wish to consider a flow path should the burn flow onto the road as potentially indicated by the surface water flow path. There is a small watercourse which was	Yes
H-BL 3	Blackridge	Housing	westcraigs road south of railway	HBr5c	290,026	666,792 10/13	Surface water – part	on boundary	Yes	southern boundary and associated flood extent.	None Known	investigated as part of a previous FRA and is a	No
							Surface water / fluvial -			We have an outstanding objection (PCS/133219, 0285/FUL/06) due to the requirement for an updated FRA to take account of the current		Developer requirements mentions "There is a significant risk of flooding from out of bank flows in the watercourse and potential backing up upstream of structures in the watercourse. Flood Risk Assessment required which assesses the flood risk from the Barbauchlaw Burn which flows west – east through the site". An updated FRA would be required for this site as the Westrigg Way road has	
H-BL 4	Blackridge	Housing	craiginn terrace	HBr8	290,249	667,090 10/13	part	going through site	Yes	situation.		modified the flooding in this area. Developer requirements mentions "Flood Risk	Yes
H-BL 5	Blackridge	Housing	woodhill rd	HBr9	288,974	667,238 10/13	No	None	No	No	None Known	010.	Yes
H-BL 6	Blackridge	Housing	south of craiginn terrace part of H bl 4	EOI-0063	290,020	667,104 10/13	Surface water / fluvial – adjacent to	None	No	No	None Known	Developer requirements mentions "Flood Risk	Yes
H-BR 1	Breich	Housing	rashiehill cres	HBc3	296,774	660,942 No	Surface water / fluvial – adjacent to	None	No	No	None Known	Assessment required". As stated previously we are not aware of the flood risk issues associated with the site.	Yes
H-BR 2	Breich	Housing	woodmuir road west	HBc5	296,281	660,646 No	Surface water – small pa	rt None	Νο	Νο	None Known	No FRA in developer requirements. Only 3 plots left, rest built. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes
							Surface water / fluvial -			We previously commented on this site (PCS117842, PCS139794, LIVE/0203/FUL/15) and removed our objection		Developer requirements mentions "There is a significant risk of flooding from out of bank flows in the watercourse. Flood Risk Assessment required". Should the application differ from what was previously agreed we would require an updated FRA. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding.	
H-BR 3	Breich	Housing	woodmuir road east	HBc6	296,516	660,647 No	part	None	Yes	subject to conditions	None Known	No FRA required within developer	Yes
H-BR 4	Breich	Housing	woodmuir community hall	MUB1	296,331	660,817 No	No	None	No	No	None Known	requirements No FRA required within developer	Yes
H-BR 5	Breich	Housing	former woodmuir primary sch	MUB2	296,264	660,751 No	No	None	No	No	None Known	requirements	Yes
H-BR 6	Breich	Housing	blackhill farm	EOI-0190	296,426	660,492 No	Surface water / fluvial - part	None	Yes	Νο	None Known	Developer requirements mentions "Parts of the site are susceptible to pluvial flooding. Flood Risk Assessment required which assesses the flood risk from the Woodmuir Burn". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Consideration should also be given to the pond on-site. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes
				24/5	205 400		Surface water – adjacent					No FRA required within developer requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. May wish to consider including this within the developer	
H-LW 3	Breich	Housing	site of former briech in by briech	21/6	295,489	660,524 No	to	None	No	No	None Known	requirements. Developer requirements mentions "Flood Risk Assessment required." The FRA should assess the risk from the Haugh Burn and any small watercourses within or adjacent to the site. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Consideration should also be given to the	Yes
E-BD 1	Bridgend	Employment	bridgend bing	EBd1	303,758	675,847 10/14	Fluvial - part	on boundary	Yes	No	None Known	pond on-site. Developer requirements mentions "Flood Risk Assessment required". As stated in previous	Yes
H-BD 1	Bridgend	Housing	willodean site a	EOI-0011	304,075	675,480 10/14	No	None	No	No	None Known		Yes
						675,228 10/14						No developer requirements for an FRA. Historic maps show the small watercourse	

lo	No	

Yes

No

Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk

No	No
No	No

0	No

No	No
No	No
No	No

No	No

No	No

0	No

No	No
No	No
No	No

H-BD 3	Bridgend	Housing	willowdean bridgend golf course	EOI-0010	303,977	675,480 10/14	No	on boundary	Yes	No	None Known	Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the Riccarton Burn which flows along the southern and western boundary of the site". Yes
H-BD 4	Bridgend	Housing	auldhill	COU3	304,420	675,625 10/14	Νο	culverted through site	Yes	Νο	None Known	Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the small watercourse which flows along the eastern boundary of the site and potentially culverted through the site". Site will likely be constrained due to flood risk as we would not accept built development on top or immediately adjacent to any culverted watercourse. Yes
												Not in proposed plan. We require an FRA which assesses the risk from the small watercourse which flows on the boundary of the site. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Consideration should also be given to the pond on-site. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is
H-BD 5	Bridgend Broxburn Broxburn	Housing CDA CDA	bridgend farm	CDA-WW EOI-0138c	304,409 309,694 307,717	675,876 10/14 673,296 673,183	Surface water – small pa	rt on boundary	Yes	No	None Known	made with the flood prevention officer. No Same as H-BU 10 Same as H-BU 08
	Broxburn Broxburn	CDA CDA		CDA-GI CDA-GE		672,793 10/27 673,340	Surface water – small pa	rt None	Yes	Νο	Broxburn FPS (2007) not relevant to site. We would note that we do not have full details on the parts that are completed.	No developer requirements provided for CDAs but this allocation not within any other reference either. The canal flows along the southern boundary of the site and consultation with Scottish Canals is recommended, though it appears to be elevated above the canal. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Same as H-BU 09
	Broxburn	CDA		CDA-CW	308,020	672,620 10/27	Surface water – part	None	Yes	Νο	relevant to site. We	No developer requirements provided for CDAs but this allocation not within any other reference either. The canal flows along the southern boundary of the site and consultation with Scottish Canals is recommended, though it appears to be elevated above the canal. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.
	Broxburn	CDA		EOI-0138g		673,238 10/27	Surface water – small pa		Yes	Νο	Broxburn FPS (2007) unable to comment whether this is part of the scheme Broxburn FPS (2007) not	No developer requirements provided for CDAs but this allocation not within any other reference either. We require an FRA which assesses the risk from the small watercourse which flows along the eastern boundary of the site. Also the canal flows along the northern boundary of the site and consultation with Scottish Canals is recommended. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.
											relevant to site. We would note that we do not have full details on the parts that are	No developer requirements provided for CDAs but this allocation forms part of the larger H- BU 04. Consideration should be given to the
	Broxburn	CDA		EOI-0138e	308,362	673,155 10/27	Surface water – small pa	rt None	No	No	completed. Broxburn FPS (2007) not relevant to site. We	pond on-site. Developer requirements mentions "Attenuation and run-off required to SEPA
E-BU 1	Broxburn	Employment	youngs road south	EUB1	309,039	672,809 10/27	No	None	No	No	would note that we do not have full details on the parts that are completed. Broxburn FPS (2007) not relevant to site. We	requirements." Site is close to the canal and would recommend that contact is made with Scottish Canals. Water resilient materials mentioned for nearby sites but not here. Yes Developer requirements mentions "Water resilient measures are required." Site is close to the canal and would recommend that contact is made with Scottish Canals (assume
E-BU 2	Broxburn	Employment	clifton view	EUB5	308,980	672,955 10/27	No	None	No	No	the parts that are completed.	that's why water resilient measures are required).

No No

No Yes

No No

No No

No Yes

No No

											Broxburn FPS (2007) not relevant to site. We would note that we do not have full details on	No FRA in developer requirements. Site is close to the canal and would recommend that contact is made with Scottish Canals. Water	
E-BU 3	Broxburn	Employment	clifton view ent area	EUB6	309,106	673,083 10/27	No	None	No	No	the parts that are completed. Broxburn FPS (2007) not	resilient materials mentioned for nearby sites but not here.	Yes
											relevant to site. We would note that we do not have full details on	No FRA in developer requirements. Site is close to the canal and would recommend that contact is made with Scottish Canals. Water	
E-BU 4	Broxburn	Employment	youngs road north enterprise area	EUB7	309,220	672,983 10/27	No	None	No	No	the parts that are completed.	resilient materials mentioned for nearby sites but not here.	Yes
												Developer requirements mentions "Flood Risk Assessment required." The FRA should assess the risk from the Brox Burn and the small watercourse which flows along the western perimeter. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. The development should compliment any existing or proposed flood protection works. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should	; d
							Surface water / fluvial -				Broxburn FPS (2007) unable to comment whether this is part of	be investigated further and it is recommended that contact is made with the flood preventior officer. Site may be constrained due to flood	
E-BU 5	Broxburn	Employment	east mains enterprise area	CDA-EM	310,318	672,632 10/27	part	on boundary	Yes	No	the scheme Broxburn FPS (2007) not relevant to site. We would note that we do	risk.	Yes
E-BU 6	Broxburn	Employment	greendykes house, greendykes road	EOI-0064	308,187	672,801 10/27	No	None	No	No	not have full details on the parts that are completed.	No FRA in developer requirements. Site is close to the canal but would appear to be elevated above it.	Yes
L-50 0	Broxburn	Linployment	greendykes nouse, greendykes road	201-0004	508,187	072,801 10/27		None			Broxburn FPS (2007) not relevant to site. We would note that we do not have full details on the parts that are	"Flood Risk Assessment required. Consideration should be given to the flood risk from the Union Canal and flood mitigation measures and early engagement with Scottish Canals is recommended. Water resilient measures are required on this site". Council previously requested an FRA when we provided previous comments. Site would appear to	
H-BU 1	Broxburn	Housing	Greendykes road	HUB12	308,293	672,889 10/27	Surface water – part	None	Yes	No	completed.	be elevated above adjacent canal.	Yes
							Surface water /fluvial -			Halcrow undertook a study for the council after the flooding in 2008. Significant flooding on the Brox Burn in August 2008. A property on Badgers Park located to the south of the site was subjected to		Developer requirements mentions "There is a significant risk of flooding from out of bank flows in the watercourse. There is a flood prevention scheme proposed for Broxburn but completion date is unknown. Flood Risk Assessment required which assesses the flood risk from the Brox Burn". Site wi need to take into consideration the Broxburn FPS and current SEPA guidance on development behind flood defences.	ill
H-BU 2	Broxburn	Housing	holmes north site b	HUB13	307,017	671,848 10/27	majority	None	Yes	significant flooding.	the scheme	Developer requirements mentions "There is a	Yes
H-BU 3	Broxburn	Housing	holmes north site c	HUB29	306,935	671,946 10/27	Surface water / fluvial – adjacent to	None	Νο	Halcrow undertook a study for the council after the flooding in 2008.	Broxburn FPS (2007) unable to comment whether this is part of the scheme	significant risk of flooding from out of bank flows in the watercourse. There is a flood prevention scheme proposed for Broxburn but completion date is unknown. Flood Risk Assessment required which assesses the flood risk from the Brox Burn". We previously mentioned that Halcrow flood study showed this site to be out with the 1:200 year flood extent.	
H-RII A	Broyburn	Housing	albun		208 565	672 082 10/27	Surface water – part	None	Ves	site (PCS137796, 097/P/14) and did not	Broxburn FPS (2007) not relevant to site. We would note that we do not have full details on the parts that are completed	Developer requirements mentions "Flood Risk Assessment required. Consideration should be given to the flood risk from the Union Canal and flood mitigation measures and early engagement with Scottish Canals is recommended. Water resilient measures are required on this site". We previously noted that the council required an FRA. The canal flows along the southern boundary of the site and consultation with Scottish Canals is recommended, though it appears to be elevated above the canal. Any ponds on-site should be considered. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
H-BU 4	Broxburn	Housing	albyn	HUB15	308,565	673,083 10/27	Surface water – part	None	Yes	object. Our understanding is that water can back up at the		Developer requirements mentions "Flood Risk Assessment required. Drainage Impact Assessmen required to assess the impact of development on the local network". The FRA should consider any FPS works built or proposed and any culverts which may exacerbate flooding. The canal flows along the southern boundary of the site and consultation with Scottish Canals is recommended, though it appears to be elevated above the canal. Review of the surface water 1 in 200 year flood map shows that	e ,
	Drovburg	Housing	candlowerke		207 020	673 521 10/27	Surface water and	on houndary	Vor	culvert inlet and cause flooding either on site or	unable to comment whether this is part of	there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Vac
H-BU 5	Broxburn	Housing	candleworks	HUB17	307,939	672,531 10/27	Surface water – part	on boundary	Yes	immediately adjacent.	the scheme		Yes

No	No	
No	Na	
No	No	
No	No	
No	No	
No	No	

No No

No No

No No

H-BU 7	Broxburn	Housing	west main st former brox primary school	BRO3	307,980	672,252 10/27	Surface water – adjacent to	adjacent to site	No	Information provided as part of the FPS indicates that the Liggat Syke is culverted to the north of the site but then flows eastwards away from the site.	Broxburn FPS (2007) unable to comment whether this is part of the scheme Broxburn FPS (2007) unable to comment	No FRA in developer requirements. We previously requested an FRA to take into account flow paths from the culvert to the north. This has not been included in the developer requirements. We note that completion is meant to be 2015. Developer requirements mentions "Flood Risk Assessment required". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. The development should compliment any existing or proposed flood protection works. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood	
H-BU 8	Broxburn	Housing	greendykes road west		307,718	673,184 10/27	Surface water – small part	going through site	Yes	No	the scheme Broxburn FPS (2007)	prevention officer. Developer requirements mentions "Flood Risk	Yes
H-BU 9	Broxburn	Housing	greendykes road east		308,328	673,342 10/27	Surface water – small part	None	No	No	whether this is part of	Assessment required". We previously didn't request an FRA. We are unaware of the flood risk issues on site. Same as CDA-GE.	
H-BU 10	Broxburn	Housing	west wood		309,694	673,298 10/27	Surface water – part	on boundary	Yes	No	Broxburn FPS (2007) unable to comment whether this is part of the scheme Broxburn FPS (2007)	No flood risk developer requirements included within proposed plan. The canal flows to the north of the site and consultation with Scottish Canals is recommended. The site appears to sit below the canal. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be	)
H-BU 11	Broxburn	Housing	church street depot	BRO6	308,552	672,576 10/27	Surface water – adjacent to	None	Yes	No	whether this is part of	investigated further and it is recommended that contact is made with the flood prevention officer.	
H-BU 12	Broxburn	Housing	hillview ave	EOI-0085		672,575 10/27	No	None	No	No	Broxburn FPS (2007) unable to comment whether this is part of the scheme	Developer requirements mentions "Flood Risk Assessment required. Mining issues causing issues with water quality and flooding in Uphall generally. A study for the north end of Uphall is being	
H-BU 13	Broxburn	Housing	kirkhill north	EOI-0144	306,560	672,585 10/27	Surface water – part	None	Yes	No	Broxburn FPS (2007) unable to comment whether this is part of the scheme		Yes
H-BU 14	Broxburn	Housing	east main st former vion	РЈ-0008	308,882	672,100 10/27	Surface water – part	on boundary	Yes	Flood outlines provided as part of the FPS study indicates that the opposite bank will preferentially flood.	Broxburn FPS (2007) unable to comment what has been done along this reach.	investigated further and it is recommended that contact is made with the flood prevention officer.	Yes
H-DE 1	Dechmont	Housing	bangour village hosp	HBn1 & EOI- 0034	303,113	670,757 10/27	Surface water / fluvial - part	None	Yes	Commented on this site (PCS142207, 0607/P/15) and had no objection subject to the submission of an FRA at the detailed stage.	Broxburn FPS (2007) not relevant to site. We would note that we do not have full details on the parts that are	Developer requirements mentions "The site is susceptible to flooding. Flood Risk Assessment required to assess the flood risk from the Brox Burn, and tributaries". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
H-DE 2	Dechmont	Housing	main st	EOI-0166	304,402	670,926 10/27	Surface water – small part	on boundary	Yes	Surface water flooding recorded nearby in 2001. No further details provided and contact with FPO is recommended.		Developer requirements mentions "Parts of site subject to Pluvial flooding. Flood Risk Assessment required which assesses the flood risk from the Beugh Burn tributary". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	e Yes

H-BU 7	Broxburn	Housing		BRO3		672,252 10/27			No		Broxburn FPS (2007) unable to comment whether this is part of the scheme Broxburn FPS (2007) unable to comment whether this is part of	No FRA in developer requirements. We previously requested an FRA to take into account flow paths from the culvert to the north. This has not been included in the developer requirements. We note that completion is meant to be 2015. Developer requirements mentions "Flood Risk Assessment required". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. The development should compliment any existing or proposed flood protection works. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood	
H-BU 8	Broxburn	Housing	greendykes road west		307,718	673,184 10/27	Surface water – small part	going through site	Yes	No	Broxburn FPS (2007) unable to comment	prevention officer. Developer requirements mentions "Flood Risk Assessment required". We previously didn't request an FRA. We are unaware of the flood	
H-BU 9	Broxburn	Housing	greendykes road east		308,328	673,342 10/27	Surface water – small part	None	No	No	the scheme	risk issues on site. Same as CDA-GE.	
H-BU 10	Broxburn	Housing	west wood		309,694	673,298 10/27	Surface water – part	on boundary	Yes	Νο	Broxburn FPS (2007) unable to comment whether this is part of the scheme	Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the small watercourse which flows through the site". The canal flows along the northern boundary of the site and consultation with Scottish Canals is recommended. The site appears to sit below the canal. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Same as CDA WW No flood risk developer requirements included within proposed plan. The canal flows to the north of the site and consultation	) Yes
H-BU 11	Broxburn	Housing	church street depot	BRO6	308,552	672,576 10/27	Surface water – adjacent to	None	Yes	No	Broxburn FPS (2007) unable to comment whether this is part of the scheme Broxburn FPS (2007)	with Scottish Canals is recommended. The site appears to sit below the canal. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Developer requirements mentions "Flood Risk Assessment required. Consideration should be given to surface runoff issues to ensure adequate	
H-BU 12 H-BU 13	Broxburn Broxburn	Housing		EOI-0085 EOI-0144		672,575 10/27 672,585 10/27		None		No	whether this is part of the scheme Broxburn FPS (2007) unable to comment whether this is part of	mitigation is implemented". We previously didn't request an FRA. We are unaware of the flood risk issues on site. Developer requirements mentions "Flood Risk Assessment required. Mining issues causing issues with water quality and flooding in Uphall generally. A study for the north end of Uphall is being considered. Consideration should be given to surface runoff issues to ensure adequate mitigation is implemented". We are not aware of historic mining issue at this location so are reliant on the	
H-BU 14	Broxburn	Housing	east main st former vion	РЈ-0008	308,882	672,100 10/27	Surface water – part	on boundary		Flood outlines provided as part of the FPS study indicates that the opposite bank will preferentially flood.	Broxburn FPS (2007) unable to comment what has been done along this reach.		6
H-DE 1	Dechmont	Housing		HBn1 & EOI- 0034	303,113	670,757 10/27	Surface water / fluvial - part	None		Commented on this site (PCS142207, 0607/P/15) and had no objection subject to the submission of an FRA at the detailed stage.	Broxburn FPS (2007) not relevant to site. We would note that we do not have full details on the parts that are completed.	Developer requirements mentions "The site is susceptible to flooding. Flood Risk Assessment required to assess the flood risk from the Brox Burn, and tributaries". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Developer requirements mentions "Parts of site	
H-DE 2	Dechmont	Housing	main st	EOI-0166	304,402	670,926 10/27	Surface water – small part	on boundary		Surface water flooding recorded nearby in 2001. No further details provided and contact with FPO is recommended.		subject to Pluvial flooding. Flood Risk Assessment required which assesses the flood risk from the Beugh Burn tributary". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the	

H-BU 7	Broxburn	Housing	west main st former brox primary school	BRO3	307,980	672,252 10/27	Surface water – adjacent to	adjacent to site	No	Information provided as part of the FPS indicates that the Liggat Syke is culverted to the north of the site but then flows eastwards away from the site.	Broxburn FPS (2007) unable to comment whether this is part of the scheme Broxburn FPS (2007) unable to comment	No FRA in developer requirements. We previously requested an FRA to take into account flow paths from the culvert to the north. This has not been included in the developer requirements. We note that completion is meant to be 2015. Developer requirements mentions "Flood Risk Assessment required". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. The development should compliment any existing or proposed flood protection works. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood	
H-BU 8	Broxburn	Housing	greendykes road west		307,718	673,184 10/27	Surface water – small part	going through site	Yes	No	the scheme Broxburn FPS (2007)		Yes
H-BU 9	Broxburn	Housing	greendykes road east		308,328	673,342 10/27	Surface water – small part	None	No	No	whether this is part of	request an FRA. We are unaware of the flood risk issues on site. Same as CDA-GE.	
H-BU 10	Broxburn	Housing	west wood		309,694	673,298 10/27	Surface water – part	on boundary	Yes	No	Broxburn FPS (2007) unable to comment whether this is part of the scheme Broxburn FPS (2007)	No flood risk developer requirements included within proposed plan. The canal flows to the north of the site and consultation with Scottish Canals is recommended. The site appears to sit below the canal. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be	) Yes
H-BU 11	Broxburn	Housing	church street depot	BRO6	308,552	672,576 10/27	Surface water – adjacent to	None	Yes	No	whether this is part of the scheme	investigated further and it is recommended that contact is made with the flood prevention officer.	1
H-BU 12	Broxburn	Housing	hillview ave	EOI-0085	308,855	672,575 10/27	No	None	No	No	Broxburn FPS (2007) unable to comment whether this is part of the scheme Broxburn FPS (2007) unable to comment	Developer requirements mentions "Flood Risk Assessment required. Consideration should be given to surface runoff issues to ensure adequate mitigation is implemented". We previously didn't request an FRA. We are unaware of the flood risk issues on site. Developer requirements mentions "Flood Risk Assessment required. Mining issues causing issues with water quality and flooding in Uphall generally. A study for the north end of Uphall is being considered. Consideration should be given to surface runoff issues to ensure adequate mitigation is implemented". We are not aware of historic mining issue at this location so are reliant on the	N .
H-BU 13	Broxburn	Housing	kirkhill north	EOI-0144	306,560	672,585 10/27	Surface water – part	None	Yes	No		council information. Developer requirements mentions "High probability	Yes
H-BU 14	Broxburn	Housing	east main st former vion	РЈ-0008	308,882	672,100 10/27	Surface water – part	on boundary	Yes	Flood outlines provided as part of the FPS study indicates that the opposite bank will preferentially flood.	Broxburn FPS (2007) unable to comment what has been done along this reach.	Developer requirements mentions "The site is	3
H-DE 1	Dechmont	Housing	bangour village hosp	HBn1 & EOI- 0034	303,113	670,757 10/27	Surface water / fluvial - part	None	Yes	(PCS142207, 0607/P/15)	Broxburn FPS (2007) not relevant to site. We would note that we do not have full details on the parts that are completed.		
H-DE 2	Dechmont	Housing	main st	EOI-0166	304,402	670,926 10/27	Surface water – small part	on boundary	Yes	Surface water flooding recorded nearby in 2001. No further details provided and contact with FPO is recommended.		Developer requirements mentions "Parts of site subject to Pluvial flooding. Flood Risk Assessment required which assesses the flood risk from the Beugh Burn tributary". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	

H-BU 7	Broxburn	Housing	west main st former brox primary school	BRO3	307,980	672,252 10/27	Surface water – adjacent to	adjacent to site		Information provided as part of the FPS indicates that the Liggat Syke is culverted to the north of the site but then flows eastwards away from the site.	Broxburn FPS (2007) unable to comment whether this is part of the scheme Broxburn FPS (2007) unable to comment	No FRA in developer requirements. We previously requested an FRA to take into account flow paths from the culvert to the north. This has not been included in the developer requirements. We note that completion is meant to be 2015. Developer requirements mentions "Flood Risk Assessment required". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. The development should compliment any existing or proposed flood protection works. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is	
H-BU 8	Broxburn	Housing	greendykes road west		307,718	673,184 10/27	Surface water – small part	going through site	Yes	No	the scheme	recommended that contact is made with the flood prevention officer. Developer requirements mentions "Flood Risk	Yes
H-BU 9	Broxburn	Housing	greendykes road east		308,328	673,342 10/27	Surface water – small part	None	No	No	whether this is part of	Assessment required". We previously didn't request an FRA. We are unaware of the flood risk issues on site. Same as CDA-GE.	
H-BU 10	Broxburn	Housing	west wood		309,694	673,298 10/27	Surface water – part	on boundary	Yes	No	Broxburn FPS (2007) unable to comment whether this is part of the scheme Broxburn FPS (2007)	No flood risk developer requirements included within proposed plan. The canal flows to the north of the site and consultation with Scottish Canals is recommended. The site appears to sit below the canal. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be	
H-BU 11	Broxburn	Housing	church street depot	BRO6	308,552	672,576 10/27	Surface water – adjacent to	None	Yes	No	whether this is part of the scheme	investigated further and it is recommended that contact is made with the flood prevention officer. Developer requirements mentions "Flood Risk	
H-BU 12	Broxburn	Housing	hillview ave	EOI-0085	308,855	672,575 10/27	No	None	No	No	Broxburn FPS (2007) unable to comment whether this is part of the scheme	Assessment required. Consideration should be given to surface runoff issues to ensure adequate mitigation is implemented". We previously didn't request an FRA. We are unaware of the flood risk issues on site. Developer requirements mentions "Flood Risk Assessment required. Mining issues causing issues with water quality and flooding in Uphall generally. A study for the north end of Uphall is being considered. Consideration should be given to	Yes
H-BU 13	Broxburn	Housing	kirkhill north	EOI-0144	306,560	672,585 10/27	Surface water – part	None	Yes	No	unable to comment whether this is part of	surface runoff issues to ensure adequate mitigation is implemented". We are not aware of historic mining issue at this location so are reliant on the council information.	Yes
H-BU 14	Broxburn	Housing	east main st former vion	PJ-0008	308,882	672,100 10/27	Surface water – part	on boundary		Flood outlines provided as part of the FPS study indicates that the opposite bank will preferentially flood.	Broxburn FPS (2007) unable to comment what has been done along this reach.	Developer requirements mentions "High probability of flooding from adjacent Liggat Syke. There is also a history of surface water being discharged from this site onto the A89. Flood Risk Assessment required to determine the extent of the land capable of being developed". FRA should consider the existing and proposed FPS and any culverts/ bridges that may exacerbate flood risk. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes
H-DE 1	Dechmont	Housing	bangour village hosp	HBn1 & EOI- 0034	303,113	670,757 10/27	Surface water / fluvial - part	None		Commented on this site (PCS142207, 0607/P/15) and had no objection subject to the submission of an FRA at the detailed stage.	Broxburn FPS (2007) not relevant to site. We would note that we do not have full details on the parts that are completed.	susceptible to flooding. Flood Risk Assessment required to assess the flood risk from the Brox Burn, and tributaries". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes
H-DE 2	Dechmont	Housing	main st	EOI-0166	304,402	670,926 10/27	Surface water – small part	on boundary		Surface water flooding recorded nearby in 2001. No further details provided and contact with FPO is recommended.		Developer requirements mentions "Parts of site subject to Pluvial flooding. Flood Risk Assessment required which assesses the flood risk from the Beugh Burn tributary". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes

										Information provided as			
H-BU 7	Broxburn	Housing	west main st former brox primary school	BRO3	307,980	672,252 10/27	Surface water – adjacent to	adjacent to site	No	part of the FPS indicates that the Liggat Syke is culverted to the north of the site but then flows eastwards away from the site.	Broxburn FPS (2007) unable to comment	No FRA in developer requirements. We previously requested an FRA to take into account flow paths from the culvert to the north. This has not been included in the developer requirements. We note that completion is meant to be 2015.	
											Browburn EDS (2007)	Developer requirements mentions "Flood Risk Assessment required". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. The development should compliment any existing or proposed flood protection works. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is	
H-BU 8	Broxburn	Housing	greendykes road west		307,718	673,184 10/27	Surface water – small part	going through site	Yes	No	the scheme	recommended that contact is made with the flood prevention officer.	Yes
H-BU 9	Broxburn	Housing	greendykes road east		308,328	673,342 10/27	Surface water – small part	None	No	No	unable to comment whether this is part of	Developer requirements mentions "Flood Risk Assessment required". We previously didn't request an FRA. We are unaware of the flood risk issues on site. Same as CDA-GE.	
												Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the small watercourse which flows through the site". The canal flows along the northern boundary of the site and consultation with Scottish Canals is recommended. The site appears to sit below the canal. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended	
H-BU 10	Broxburn	Housing	west wood		309,694	673,298 10/27	Surface water – part	on boundary	Yes	No	whether this is part of	that contact is made with the flood prevention	Yes
												No flood risk developer requirements included within proposed plan. The canal flows to the north of the site and consultation with Scottish Canals is recommended. The site appears to sit below the canal. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be investigated further and it is recommended	
H-BU 11	Broxburn	Housing	church street depot	BRO6	308,552	672,576 10/27	Surface water – adjacent to	None	Yes	No	whether this is part of the scheme	that contact is made with the flood prevention officer. Developer requirements mentions "Flood Risk	
H-BU 12	Broxburn	Housing	hillview ave	EOI-0085	308,855	672,575 10/27	Νο	None	No	No	whether this is part of the scheme	155065 011 516.	Yes
H-BU 13	Broxburn	Housing	kirkhill north	E0I-0144	306,560	672,585 10/27	Surface water – part	None	Yes	No	Broxburn FPS (2007) unable to comment whether this is part of	Developer requirements mentions "Flood Risk Assessment required. Mining issues causing issues with water quality and flooding in Uphall generally. A study for the north end of Uphall is being considered. Consideration should be given to surface runoff issues to ensure adequate mitigation is implemented". We are not aware of historic mining issue at this location so are reliant on the council information.	Yes
										Flood outlines provided		Developer requirements mentions "High probability of flooding from adjacent Liggat Syke. There is also a history of surface water being discharged from this site onto the A89. Flood Risk Assessment required to determine the extent of the land capable of being developed". FRA should consider the existing and proposed FPS and any culverts/ bridges that may exacerbate flood risk. Review of the surface water 1	
H-BU 14	Broxburn	Housing	east main st former vion	PJ-0008	308,882	672,100 10/27	Surface water – part	on boundary	Yes	as part of the FPS study indicates that the opposite bank will preferentially flood.	unable to comment what has been done along this reach.		Yes
H-DE 1	Dechmont	Housing	bangour village hosp	HBn1 & EOI- 0034	303,113	670,757 10/27	Surface water / fluvial - part	None	Yes	Commented on this site (PCS142207, 0607/P/15) and had no objection subject to the submission of an FRA at the detailed stage.	Broxburn FPS (2007) not relevant to site. We would note that we do not have full details on the parts that are	Developer requirements mentions "The site is susceptible to flooding. Flood Risk Assessment required to assess the flood risk from the Brox Burn, and tributaries". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes
		-	_ ·							Surface water flooding recorded nearby in 2001. No further details provided and contact		Developer requirements mentions "Parts of site subject to Pluvial flooding. Flood Risk Assessment required which assesses the flood risk from the Beugh Burn tributary". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further	
H-DE 2	Dechmont	Housing	main st	EOI-0166	304,402	670,926 10/27	Surface water – small part	on boundary	Yes	with FPO is recommended.		and it is recommended that contact is made with the	Yes

H-BU 7	Broxburn	Housing	west main st former brox primary school	BRO3	307,980	672,252 10/27	Surface water – adjacent to	adjacent to site	No	Information provided as part of the FPS indicates that the Liggat Syke is culverted to the north of the site but then flows eastwards away from the site.	Broxburn FPS (2007) unable to comment whether this is part of the scheme	No FRA in developer requirements. We previously requested an FRA to take into account flow paths from the culvert to the north. This has not been included in the developer requirements. We note that completion is meant to be 2015. Developer requirements mentions "Flood Risk Assessment required". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. The development should compliment any existing or proposed flood protection works. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is	
H-BU 8	Broxburn	Housing	greendykes road west		307,718	673,184 10/27	Surface water – small par	t going through site	Yes	No	whether this is part of the scheme	recommended that contact is made with the flood	Yes
H-BU 9	Broxburn	Housing	greendykes road east		308,328	673,342 10/27	Surface water – small par	t None	No	No	unable to comment whether this is part of	Assessment required". We previously didn't request an FRA. We are unaware of the flood risk issues on site. Same as CDA-GE.	
H-BU 10	Broxburn	Housing	west wood		309,694	673,298 10/27	Surface water – part	on boundary	Yes	No	Broxburn FPS (2007) unable to comment whether this is part of the scheme	Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the small watercourse which flows through the site". The canal flows along the northern boundary of the site and consultation with Scottish Canals is recommended. The site appears to sit below the canal. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Same as CDA WW No flood risk developer requirements included within proposed plan. The canal flows to the north of the site and consultation with Scottish Canals is recommended. The site appears to sit below the canal. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues	) Yes
H-BU 11	Broxburn	Housing	church street depot	BRO6	308,552	672,576 10/27	Surface water – adjacent	None	Yes	No	Broxburn FPS (2007) unable to comment whether this is part of the scheme	adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	ì
H-BU 12	Broxburn	Housing	hillview ave			672,575 10/27	No	None	No	No	Broxburn FPS (2007) unable to comment whether this is part of the scheme	Developer requirements mentions "Flood Risk Assessment required. Consideration should be given to surface runoff issues to ensure adequate mitigation is implemented". We previously didn't request an FRA. We are unaware of the flood risk	Yes
H-BU 13	Broxburn	Housing	kirkhill north	EOI-0144	306,560	672,585 10/27	Surface water – part	None	Yes	Νο	Broxburn FPS (2007) unable to comment whether this is part of	Assessment required. Mining issues causing issues with water quality and flooding in Uphall generally. A study for the north end of Uphall is being considered. Consideration should be given to surface runoff issues to ensure adequate mitigation is implemented". We are not aware of historic mining issue at this location so are reliant on the	
H-BU 14	Broxburn	Housing	east main st former vion	РЈ-0008	308,882	672,100 10/27	Surface water – part	on boundary	Yes	Flood outlines provided as part of the FPS study indicates that the opposite bank will preferentially flood.	Broxburn FPS (2007) unable to comment what	Developer requirements mentions "High probability of flooding from adjacent Liggat Syke. There is also a history of surface water being discharged from this site onto the A89. Flood Risk Assessment required to determine the extent of the land capable of being developed". FRA should consider the existing and proposed FPS and any culverts/ bridges that may exacerbate flood risk. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	5
H-DE 1	Dechmont	Housing	bangour village hosp	HBn1 & EOI- 0034	303,113	670,757 10/27	Surface water / fluvial - part	None	Yes	Commented on this site (PCS142207, 0607/P/15) and had no objection subject to the submission of an FRA at the detailed stage.	Broxburn FPS (2007) not relevant to site. We would note that we do not have full details on the parts that are	Developer requirements mentions "The site is susceptible to flooding. Flood Risk Assessment required to assess the flood risk from the Brox Burn, and tributaries". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
H-DE 2	Dechmont	Housing	main st	EOI-0166	304,402	670,926 10/27	Surface water – small part	t on boundary	Yes	Surface water flooding recorded nearby in 2001. No further details provided and contact with FPO is recommended.		Developer requirements mentions "Parts of site subject to Pluvial flooding. Flood Risk Assessment required which assesses the flood risk from the Beugh Burn tributary". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	

No No No No

No No

No

No

No

No No No No

No No

No No No No

H-DE 3	Dechmont	Housing	reserve site only needed if required to support delivery of bangour villag hops site H DE 1	e PJ-0006	303,842 671,071 10/27	Surface water / fluvial - part	None	Yes	Νο	None Known	Developer requirements mentions "A significant part of this site is at serious risk of flooding. Flood Risk Assessment required which assesses the flood risk from the Brox Burn which flows along the southern extent of the site. Drainage Impact Assessment required to assess the impact of development on the local network. Water Impact Assessment required". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.
							multiple watercourses		Surface water flooding recorded nearby in 2005. No further details provided and contact with FPO is		No developer requirements provided for CDAs but parts of this allocation not within any other reference either. We require an FRA which assesses the risk from small watercourses which flow through/ adjacent to the site. The site would appear to be sufficiently elevated above the River Almond. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention
	East Calder	CDA		CDA-AD	309,654 668,721 10/27	Surface water – part	through site	Yes	recommended. Surface water flooding recorded nearby in 2008. No further details provided and contact with FPO is recommended. We commented on a small part of the site (PCS142214, PCS139379) and did not object as it was located away from small watercourse. We also commented on a CDA which was far larger than this one (PCS102207 and 0524/P/09) and objected due to a lack of		officer. No developer requirements provided for CDAs but parts of this allocation not within any other reference either. We require an FRA which assesses the risk from small watercourses which flow through/ adjacent to the site. The site would appear to be sufficiently elevated above the River Almond. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention
	East Calder	CDA		CDA-RW	309,256 667,732 10/27	Surface water – part	going through site	Yes	•	None Known	Developer requirements mentions "Flood Risk and Drainage Assessments required." The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it
E-EC 1	East Calder	Employment	camps ind estate expansion	CDA-CE	310,475 668,030 10/27	Surface water / fluvial - part	None	Yes	No Commented on this site previously as part of the LDP (PCS124390) and	None Known	<ul> <li>is recommended that contact is made with the flood prevention officer. The site will likely be constrained due to flood risk.</li> <li>Developer requirements mentions "This site is deemed to be at risk from out of bank flows in the watercourse Flood Risk Assessment required which assesses the flood risk from the small watercourse which flows through the site. Consideration should be given to any culverts along this reach". Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is</li> </ul>
H-EC 1	East Calder	Housing	millbank depot	HEc4	308,436 668,100 10/27	Surface water – part	going through site	Yes	was satisfied with the draft planning guidelines	None Known	<ul> <li>This should be investigated further and it is recommended that contact is made with the flood prevention officer.</li> <li>Developer requirements mentions "Site susceptible to flooding. Flood Risk Assessment required.</li> <li>Drainage Impact Assessment required". We have commented on larger Camps Industrial Estate but cannot find our comments for this smaller site. Not aware of the flood risk associated with this site. The council may wish to consider whether these</li> </ul>
H-EC 2	East Calder	Housing	camps cottage	HEc5	310,332 668,390 10/27	Surface water – small par	rt None	Yes	No	None Known	<ul> <li>comments remain applicable.</li> <li>"The Linhouse Water is some 150m to the west of the site and the River Almond is some 200m north of the site. Flood Risk Assessment required Drainage Impact Assessment required to assess the impact of development on the local network". Not aware of flood risk associated with the site. Adjacent FRA indicates site is free from flood risk from the</li> </ul>
H-EC 3 H-EC 4	East Calder East Calder	Housing Housing	broom park farm raw holdings west (seven wells)	HEc6	308,016 667,832 10/27 308,789 667,378 10/27	Surface water – small par Surface water – small par		Yes	No	None Known None Known	Linhouse Water. NO FRA IN developer requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Yes
		-	,								

No No

No Yes

No

No

No

No No

No No

Yes

No

No No

No

											No developer requirements provided for this site. We require an FRA which assesses the risk from the small watercourse which flows through the site. The FRA should consider any structures, e.g. culverts, which may	
									Surface water flooding recorded nearby in 2008. No further details provided		exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is	
H-EC 5	East Calder Housing	raw holdings remainder		309,373	667,759 10/27	Surface water – part goin	g through site		and contact with FPO is	None Known	recommended that contact is made with the flood prevention officer. No FRA in developer requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues	No
H-EC 6	East Calder Housing	almondell phase 1 sites mwc mwd mwf mwe Ika Ikb		309,443	668,526 10/27	Surface water – small part Non	e	Νο	No	None Known	within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention	Yes
											No FRA in developer requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention	
H-EC 7	East Calder Housing	almondell phase 1 sites lka lkc		309,295	668,565 10/27	Surface water – small part Non	e	No	No	None Known	No FRA in developer requirements. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended	Yes
H-EC 8	East Calder Housing	almondell phase 2 sites mwf lkb		309,146	668,370 10/27	Surface water – small part Non	e	No	No	None Known	that contact is made with the flood prevention officer.	Yes
									Surface water flooding recorded nearby in 2005. No further details provided and contact		No developer requirements FRA requested for this site. We require an FRA which assesses the risk from small watercourses which flow through/ adjacent to the site. The site would appear to be sufficiently elevated above the River Almond. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is	
H-EC 9	East Calder Housing	almondell remainder		309,708	668,783 10/27	Surface water – part goin	g through site		with FPO is recommended.	None Known		No
									We commented on this site previously (PCS120660, 0117/P/08) and have been in discussion with the developer regarding the FRA and an acoustic		Developer requirements mentions that a FRA is required. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the	
E-EW 1	East Whitburn Employment	whitrigg north east	EEw2	296,762	665,154 No	Surface water – part goin	g through site			None Known		Yes
E-EW 2	East Whitburn Employment	whitrigg south west	EEw3	296,667	664,856 No	Surface water – small part on b	oundary		We previously commented on this site (PCS111344, 0460/FUL/09) and did not object due to the low sensitivity of use.	None Known	is required. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes
											Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the small watercourse which flows through the site. Drainage Impact Assessment required to assess the impact of development on the local network". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made	
H-FA 1	Fauldhouse Housing	eastwood park east	HFh7	293,776	661,242 No	Surface water – small part goin	g through site	Yes	No Nearby surface water	None Known	with the flood prevention officer.	Yes
						Surface water – adjacent			flooding recorded in 2001 and 2007. No further details provided and contact with FPO is		Assessment required". Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
H-FA 2	Fauldhouse Housing	meadow cresc	HFh8	293,293	660,408 No	to adja	cent to site	No	recommended.	None Known		Yes

No developer requirements provided for this

No Yes

No No

No No

No Yes

No No

No No

								Adjacent surface water flooding recorded in 2007. No further details provided and contact		Developer requirements mentions "Potential significant flood risk issues from agricultural land, very wet site also, drainage ditches throughout the site. Flood Risk Assessment required which assesses the flood risk from the small watercourses which transect the site. Consideration should be given to any culverted structures within or nearby the site which may exacerbate flood risk. Drainage Impact Assessment required. A water impact assessment (WIA) would be required". If this is considered a wet site and was a former colliery then	
H-FA 3	Fauldhouse	Housing	former victoria park colliery	HFh10	293,208 661,150 No	Surface water – small part on boundary	Yes	with FPO is recommended.	None Known	the council may wish to consider removing this allocation as it may not be suitable for housing. Developer requirements mentions "Flood Risk Assessment required. Drainage Impact Assessment	Yes
H-FA 4	Fauldhouse	Housing	shotts road	HFh11	292,218 660,057 No	Surface water – adjacent to None	No	No	None Known	required". Council have highlighted surface water runoff from this site hence we support the requirement.	Yes
										Developer requirements mentions "Flood Risk Assessment required". Council have requested this previously and may be to do with the small watercourse adjacent to the site. We do not have any additional information on flood	ł
H-FA 5	Fauldhouse	Housing	briech water place	HFh15	294,286 660,849 No	Surface water – small part adjacent to site	No	No	None Known	Developer requirements mentions "A very small area of this site is at risk from pluvial flooding. Flood Risk Assessment required which assesses the flood risk from the small watercourses which flow through the site. Consideration should be given to any culverts along this reach. Drainage Impact Assessment required". Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the	
H-FA 6	Fauldhouse	Housing	sheephousehill north	HFh19	294,016 660,955 No	Surface water – small part going through site	Yes	No	None Known	flood prevention officer. Developer requirements mentions "Flood Risk Assessment required. Drainage Impact Assessment required". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood	
H-FA 7	Fauldhouse	Housing	lanrigg road 3	HFh20	293,782 661,481 No	Surface water – part going through site	Yes	No Adjacent surface water flooding recorded in 2007. No further details provided and contact with FPO is	None Known	prevention officer. Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the small watercourse which flow along the northeast boundary". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the	e
H-FA 8	Fauldhouse	Housing	eldrick ave	FAU4	292,998 660,424 No	Surface water – part on boundary	Yes	recommended. Adjacent surface water flooding recorded in 2007. No further details provided and contact with FPO is	None Known	flood prevention officer. Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the small watercourse which flows along the southern boundary. There are upstream/ downstream culverts which may exacerbate flood risk to the site". Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
H-FA 9	Fauldhouse	Housing	main street former cinema	FAU11	292,951 660,496 No	Surface water – small part on boundary	Yes	recommended. We commented on the draft planning guidelines (PCS/125219) which was for the larger area and noted that pitches were proposed immediately adjacent to the burn which is not included (access was immediately	None Known	Developer requirements mentions "Flood Risk	Yes
H-FA 10	Fauldhouse	Housing	eastfield rec ground	FAU12	293,799 661,045 No	Surface water – adjacent to adjacent to site	No	adjacent to the burn as well) hence we required an FRA.	None Known	<ul> <li>Assessment required". We previously request an FRA but site allocation was reduced in size and no FRA was requested.</li> <li>Developer requirements mentions "Flood Risk Assessment required. Drainage Impact Assessment required". The FRA should consider any structures, e.g. culverts, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood</li> </ul>	
H-FA 11	Fauldhouse	Housing	croftfoot farm	EOI-0124	293,753 661,401 No	Surface water – part going through site	Yes	No	None Known	prevention officer. No flood risk developer requirements included within proposed plan. Majority built. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be investigated further and it is recommended	
H-KN 1	Kirknewton	Housing	braekirk gdns	HKn2	310,834 667,136 10/27	Surface water – adjacent to None	No	Νο	None Known	that contact is made with the flood prevention officer.	Yes

No No

No No

No No

No No

No No

No No

No No No No

H-KN 2	Kirknewton	Housing	station rd east	HKn7	311,116	667,228 10/27	Surface water – small pa	rt None	No	No	None Known	"A very small area of this site is at risk from pluvial flooding. Flood Risk Assessment required". As previously noted, we are unaware of the flood risk issues on site.	Yes
										Adjacent surface water flooding recorded in 2009. No further details provided and contact with FPO is		"Flood Risk Assessment required. Drainage Impact Assessment required". Previous note (May 2012) suggests this is under construction and we did not require an FRA as part of the developer requirements.	
H-KN 3	Kirknewton	Housing	camps junction east	HKn8(1)	311,880	667,326 10/27	No	None	No	recommended.	None Known	"Flood Risk Assessment required. Drainage Impact Assessment required to assess the impact of development on the local network". We previously	Yes
Н-КN 4	Kirknewton	Housing	station rd south extension	HKn10 & EOI- 0090	310,713	666,887 10/27	Surface water – adjacent to	None	No	We may have commented on this site (PCS/135046) and did not object	None Known	did not request an FRA be submitted. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	e Yes
												Not in proposed plan. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the site. This should be investigated further and it is recommended that contact is made with the	
	Kirknewton	Other		EOI-0171	310,506	667,274 10/27	Surface water – small pa	rt None	No	No	None Known	flood prevention officer.	
H-LW 2	Landward	Crofts	craigengall farm lowland crofts	1/37	292,592	671,223 10/13	Surface water – small par	rt going through site	Yes	N/A	None known	Developer requirements mentions "Small part of site subject to fluvial flooding. Flood Risk Assessment required". We would require an FRA which assesses the risk from the small watercourse which flows through the site. The FRA should consider any structures, e.g. culverts, which may exacerbate flooding.	Yes
										A FRA was carried out for Rusha quarry in 2008 (carried out by Entec Consultants) and included information on realignment of the		No developer requirements mentioned. We would require a FRA to determine the flood risk from the small watercourses that run through and adjacent to the site, including the Longhill Burn/West Calder Burn and tributary of Harwood Water. It is likely the majority of	
H-LW 4	Landward	Crofts	west mains farm		299,805	660,718 No	Surface water / fluvial – small part	multiple watercourses through site	Yes	Longhill Burn which runs through part of this site	None known	the site is developable and site layout and topographic information may be sufficient.	No
H-LW 5	Landward	Crofts	longford farm		298,052	660,785 No	Surface water / fluvial – small part	going through site	Yes	A FRA was carried out for Rusha quarry in 2008 (carried out by Entec Consultants) and included information on the Longford Burn which runs through the site	None known	No developer requirements mentioned. We would require a FRA should the proposals change from 0877/MSC/09 to locate buildings to low lying areas adjacent to watercourses.	
			newton north newton by south									No developer requirements mentioned. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Consideration should also be given to flood risk from the pond on the site and we would recommend raised floor levels to	
E-LW 1	Landward	Employment	queensferry	ENn1	310,559	678,390 10/15	Surface water – part	adjacent to site	Yes	N/A	None known	reduce any flood risk.	Yes
H-LW 6	Landward	Housing	former freeport retail village	EOI-0161	300,368	663,821 No	No	None	No	N/A	None known	Developer requirements mentions "Parts of site are at risk from pluvial flooding. Flood Risk Assessment required". We have no further information on flood risk at this location.	Yes
												Assumed to be part of H-LW6 as no site reference: Developer requirements mentions "Parts of site are at risk from pluvial flooding. Flood Risk Assessment required". We would require the FRA to also assess risk to site from small watercourse on southeast boundary, which may be culverted through the site. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood preventior	
	Landward	Other		EOI-0161	300,308	663,626 No	Surface water – small pa	rt adjacent to site	Yes		None known	officer. No developer requirements mentioned. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be	Yes
E-LL 1	Linlithgow	Employment	mill rd ind est linlithgow bridge	ELI4	298,605	677,626 10/13	Surface water – part	None	Yes	FRA was carried out (Envirocentre, April 2015) for adjacent site	None known	investigated further and it is recommended that contact is made with the flood preventior officer.	Yes
		Employment			230,003	5,,,020 10/13				.or adjucent site			100

No	No
No	No
No	Yes
No	Yes
No	No
No	No
No	No
No	No

E-LL 2 H-LL 1 H-LL 2	Linlithgow Linlithgow Linlithgow	Employment Housing Housing	burghmuir north of blackness rd 81 - 87 high st westerlea court	EOI-0014 HLI27	300,244 677,08	37 10/13	Surface water – part No No	None None None	Yes No No	N/A N/A N/A	None known None known None known	No developer requirements mentioned. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. There is also a spring shown on the eastern site boundary. This should be investigated further and it is recommended that contact is made with the flood prevention officer. No developer requirements mentioned. No developer requirements mentioned.	Yes Yes Yes
H-LL 3	Linlithgow	Housing	boghall east	EOI-0015	301,707 677,87	70 10/13	Surface water – small par	None	Yes	N/A	None known	No developer requirements mentioned but noted that "Site drainage is particularly sensitive in this part of Linlithgow". Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
H-LL 4	Linlithgow	Housing	land east of manse rd	EOI-0045	, ,		Surface water – small par		Yes	N/A	None known	Developer requirements mentions "Site susceptible to pluvial flooding. Flood Risk Assessment required. Drainage Impact Assessment required to assess the impact of development on the local network". We hold no further information on the flood risk at this location.	is Yes
H-LL 5	Linlithgow	Housing	falkirk rd	EOI-0105	299,058 676,90	01 10/13	No	None	No	N/A	None known	No developer requirements mentioned.	Yes
H-LL 6	Linlithgow	Housing	mill road	E0I-0131		09 10/13	Surface water / fluvial - part	None	Yes	Burn in 1998 and surface water issues nearby in 2007.	Formal scheme upstream of site designed to 0.5% AP standard but unclear what (if any) protection afforded to site.	Developer requirements mentions "Site susceptible to fluvial flooding associated with the Mill Burn. Flood Risk Assessment required which assesses the flood risk from the Mains Burn. Consideration should be given to culverted structures within/nearby the site which may exacerbate flood risk to the site". FRA has been provided and SEPA satisfied this addresses flood risk from Mains Burn but that to reduce residual risk from surcharging of MS culvert, floor levels should be raised to at leas 40.5mAOD. We support the statements for "The site is traversed by drainage infrastructure which requires to be identified and protected" and "Requirement to accommodate a buffer strip of 6m between the development and the Mains Burn which straddles the eastern boundary of the site".	d s t 9 st
H-LL 7	Linlithgow	Housing	clarendon house, 30 manse road	EOI-0184			No	None	No	N/A	None known	No developer requirements mentioned.	Yes
												Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the small watercourses that transect the site. Due to steep topography consideration should be given to surface runoff issues to ensure adequate mitigation is implemented. Consideration should be given to the flood risk from the Union Canal and flood mitigation measures and early engagement with Scottish Canals is	d t
H-LL 10	Linlithgow	Housing	clarendon farm		300,675 676,58	32 10/13	Νο	None	Νο	N/A	None known	recommended". Our previous response requesting the FRA was for consultation on a much larger site than currently proposed. We have no information to indicate flood risk to this smaller site and would not request an FRA. However, we do still recommend measures to mitigate flood risk due to steep topography.	
H-LL 10	Linlithgow	Housing	clarendon farm		300,675 676,58	32 10/13	No	None	No	N/A	None known	requesting the FRA was for consultation on a much larger site than currently proposed. We have no information to indicate flood risk to this smaller site and would not request an FRA. However, we do still recommend measures to mitigate flood risk due to steep topography.	e Yes k
H-LL 10	Linlithgow	Housing	clarendon farm		300,675 676,58	32 10/13	No	None	No	N/A Surface water flooding issues reported nearby in		requesting the FRA was for consultation on a much larger site than currently proposed. We have no information to indicate flood risk to this smaller site and would not request an FRA. However, we do still recommend measures to mitigate flood risk due to steep topography.	Yes k be

E-LL 2 H-LL 1 H-LL 2	Linlithgow Linlithgow Linlithgow	Employment Housing Housing	burghmuir north of blackness rd 81 - 87 high st westerlea court	EOI-0014 HLI27	301,786 300,244 300,063	678,262 10/13 677,087 10/13 676,342 10/13	Surface water – part No No	None None None	Yes No No	N/A N/A N/A	None known None known None known	No developer requirements mentioned. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. There is also a spring shown on the eastern site boundary. This should be investigated further and it is recommended that contact is made with the flood prevention officer. No developer requirements mentioned. No developer requirements mentioned.	Yes Yes Yes
H-LL 3	Linlithgow	Housing	boghall east	EOI-0015	301,707	677,870 10/13	Surface water – small pa	rt None	Yes	N/A	None known	No developer requirements mentioned but noted that "Site drainage is particularly sensitive in this part of Linlithgow". Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
H-LL 4	Linlithgow	Housing	land east of manse rd	EOI-0045	300,504	676,235 10/13 & 10/14	Surface water – small pa		Yes	N/A	None known	Developer requirements mentions "Site susceptible to pluvial flooding. Flood Risk Assessment required. Drainage Impact Assessment required to assess the impact of development on the local network". We hold no further information on the flood risk at the location.	is Yes
H-LL 5	Linlithgow	Housing	falkirk rd	EOI-0105	299,058	676,901 10/13	No	None	No	N/A	None known	No developer requirements mentioned.	Yes
H-LL 6 H-LL 7	Linlithgow Linlithgow	Housing Housing	mill road clarendon house, 30 manse road	EOI-0131 EOI-0184	298,710 300,564	677,609 10/13 676,691 10/13	Surface water / fluvial - part No	None None	Yes No	SEPA had no objection to LIVE/0244/FUL/15 following provision of a FRA (EnviroCentre, April 2015) but did recommend floor levels raised to minimum of 40.5mAOD. History of flooding along Mains Burn in 1998 and surface water issues nearby in 2007. N/A	Formal scheme upstream of site designed to 0.5%	Developer requirements mentions "Site susceptible to fluvial flooding associated with the Mill Burn. Flood Risk Assessment required which assesses the flood risk from the Mains Burn. Consideration should be given to culverted structures within/nearby the site which may exacerbate flood risk to the site". FRA has been provided and SEPA satisfied thi addresses flood risk from Mains Burn but tha to reduce residual risk from surcharging of M culvert, floor levels should be raised to at leas 40.5mAOD. We support the statements for "The site is traversed by drainage n infrastructure which requires to be identified and protected" and "Requirement to accommodate a buffer strip of 6m between the development and the Mains Burn which straddles the eastern boundary of the site". No developer requirements mentioned.	d is t 9 st
H-LL 10	Linlithgow	Housing	clarendon farm			676,582 10/13	Νο	None	Νο	N/A	None known	Developer requirements mentions "Flood Ris Assessment required which assesses the floor risk from the small watercourses that transec the site. Due to steep topography consideration should be given to surface runoff issues to ensure adequate mitigation is implemented. Consideration should be given to the flood risk from the Union Canal and flood mitigation measures and early engagement with Scottish Canals is recommended". Our previous response requesting the FRA was for consultation on a much larger site than currently proposed. We have no information to indicate flood risk to this smaller site and would not request an FRA. However, we do still recommend measures to mitigate flood risk due to steep topography.	k d t
п-LL 10	LIIIIIIngow	nousing	uarenuun iarm		300,675	070,382 10/13	INU	INUTIE	INU	N/A		Developer requirements mentions "Flood Ris Assessment required. Consideration should b given to the flood risk from the Union Canal and flood mitigation measures and early engagement with Scottish Canals is recommended. There is also a potential risk o	k be
H-LL 11	Linlithgow	Housing	wilcoxholm farm pilgrims hill	EOI-0114	301,608	677,109 10/13	Surface water – part	adjacent to site	Yes	Surface water flooding issues reported nearby in 2005 and 2008.	None known	flooding to properties in the town due to the balancing function performed by the loch through a complex series of level controls". We support this requirement and would advise that FRA should also consider risk from small watercourse to south of site alongside B9080. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues adjacent to the railway. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	n

H-LL 10	Linlithgow	Housing	clarendon farm	300,675	676,582 10/13

# No No

No No No No

No No

H-LL 12	Linlithgow	Housing	preston farm	EOI-0168	299,449	676,133 10/13	Surface water – part	adjacent to site	Yes	Flooding along Mains Burn reported in 1998 and surface water flooding nearby in 2001 and 2008.	None known	Developers requirements mentions "Flood Risk Assessment required which assesses the flood risk from the Preston Burn/Mains Burn and the reservoir on site. Due to steep topography consideration should be given to surface runoff issues to ensure adequate mitigation is implemented". The surface wate flood maps indicate there may be a small watercourse running through the site from the reservoir to the Union Canal. Consideration should also be given to flood risk from the Union Canal and flood mitigation measures and early engagement with Scottish Canals is recommended. Not included within table in proposed plan? We would require FRA to assess risk to site from Breich Water and River Almond. It is likely the majority of the site is developable and site layout and topographic information may be sufficient. Review of the surface wate 1 in 200 year flood map shows that there may	er
										FRA was completed by	_	be flooding issues within the site. This should be investigated further and it is recommended	d
	Livingston	CDA		CDA-GF	302,164	665,323 No	Surface water / fluvial - part	None	Yes	URS in 2008 in support o development at this site.		that contact is made with the flood prevention officer.	ı
E-LV 1	Livingston	Employment	Brucefield park west	ELv2	304,178	664,283 10/27	Surface water – part	on boundary	Yes	N/A	None known	No developer requirements mentioned. We would require a FRA to assess the flood risk from the small watercourse which runs along the western and southern boundary of the site. The impact of culverts on flood levels in the watercourse should be considered. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues in part of the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
E-LV 2	Livingston	Employment	brucefield east	ELv3	304,561	664,482 10/27	No Surface water – adjacen	None t	No	N/A	None known	No developer requirements mentioned.	Yes
E-LV 3 E-LV 4	Livingston Livingston	Employment Employment	brucefield north nairn road north east	ELv63 ELv5	304,191 302,292	664,841 10/27 669,891 10/27	to No	adjacent to site None	No No	N/A N/A	None known None known	No developer requirements mentioned. No developer requirements mentioned.	Yes Yes
E-LV 5	Livingston	Employment	dunlop sq west	ELv9a/b	301,173	668,137 10/27	Surface water – adjacen to	adjacent to site	No	N/A	None known	No developer requirements mentioned.	Yes
E-LV 6 E-LV 7 E-LV 8	Livingston Livingston Livingston	Employment Employment Employment	dunlop sq west caputhill rd east caputhill rd central	ELv9a/b ELv15 ELv16	301,243 301,339 301,180	668,205 10/27 668,810 10/27 668,713 10/27	Surface water – adjacen to No No	t None None None	No No No	N/A N/A N/A	None known None known None known	No developer requirements mentioned. No developer requirements mentioned. No developer requirements mentioned.	Yes Yes Yes
E-LV 9 E-LV 10	Livingston Livingston	Employment Employment	caputhill road west 1 caputhill road west 2	E-LV 09 ELv17a/b	301,074 301,049	668,631 10/27 668,610 10/27	No No	None None	No No	N/A N/A	None known None known	No developer requirements mentioned. No developer requirements mentioned.	Yes Yes
E-LV 11	Livingston	Employment	caputhill rd	ELv18		668,850 10/27	Surface water – small pa		Yes	N/A	None known	No developer requirements mentioned. FRA required to assess risk from small drain to north of site. Given proposed site use, basic information likely to be acceptable including site layout and levels. Measures to ensure no increased runoff likely to be required.	
E-LV 12	Livingston	Employment	appleton parkway west	ELv21	302,335	667,804 10/27	Surface water / fluvial – small part	None	Yes	N/A	None known	Developer requirements mentions "Flood Rish Assessment required". This should assess the risk from the Lochshot Burn running to the south of the site. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues in part of the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes
E-LV 13	Livingston	Employment	appleton parkway north west	ELv22	302,280	668,107 10/27	No	None	No	N/A	None known	No developer requirements mentioned.	Yes
E-LV 14	Livingston	Employment	appleton parkway north east	ELv23	302,605	668,116 10/27	Surface water – small pa	art None	Yes	N/A	None known	No developer requirements mentioned.	Yes
E-LV 15	Livingston	Employment	appleton parkway east	ELv25 & EOI- 0222	302,754	667,801 10/27	Surface water / fluvial – small part	on boundary	Yes	N/A	None known	Developer requirements mentions "Development must respect location of Lochshot Burn and Greenway to south and no buildings within 10m of south boundary". We require an FRA to determine the risk to the site from the Lochshot Burn and also small watercourses that run along north and west boundaries. The majority of the site is likely developable and site layout and topographic information may be sufficient. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues in part of the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	

No No

No Yes

No Yes No No

No Yes

No No No No No No

Yes No

E-LV 16	Livingston	Employment	appleton parkway south	ELv26 & EOI- 0223	302,782	667,471 10/27	Surface water – small pa	rt None	Yes	N/A	None known		No
E-LV 17	Livingston	Employment	appleton parkway south west	ELv27	302.702	667,229 No	Surface water – small pa	rt adiacent to site	Yes	N/A	None known	No developer requirements mentioned. We require a FRA to assess the risk of flooding to the site from the small watercourse to the west of the site. Consideration of flood risk from the pond is also advised. It is likely the majority of the site is developable and site layout and topographic information may be sufficient. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues in the developed area of Appleton Place and the map may also be indicating a pond on site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Νο
/	8	p.c,c			,			,					
E-LV 18	Livingston	Employment	appleton parkway	EOI-0224	302,633	667,288 10/27	Surface water – small pa	rt None	Yes	N/A	None known	Developer requirements mentions "Flood Risk Assessment required". Review of the surface water 1 in 200 year flood map shows that there may be flooding issues in part of the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. We have no further flood risk information for this location.	Yes
E-LV 19	Livingston	Employment	appleton parkway south east	ELv28 & EOI- 0024	302,945	667,360 part 10/27	No	None	No	N/A	None known		Yes
E-LV 21 E-LV 22	Livingston Livingston	Employment Employment	firth rd south nettlehill road east	ELv34 ELv36	305,887 305,890	668,865 10/27 670,220 10/27	No Surface water – small pa	None rt None	Yes Yes	N/A N/A	None known None known		Yes Yes
				ELv39a & EOI-								No developer requirements mentioned. We require a FRA to determine the flood risk to the site from the Killandean Burn. The majority of the site is likely to be developable and site layout and topographic information may be sufficient to determine risk. Flood risk from the small watercourse issuing to the southwest of the site should also be	
E-LV 23	Livingston	Employment	former rosebank nursery	0181	303,153	665,821 No	Fluvial - small part	adjacent to site	Yes	N/A	None known		No
				ELv39c & EOI-								No developer requirements mentioned. We require a FRA to determine the flood risk to the site from the Killandean Burn. The majority of the site is likely to be developable and site layout and topographic information may be sufficient to determine risk. Flood risk from the small watercourse in the southwest and northeast of the site should also be	
E-LV 24	Livingston	Employment	former rosebank nursery	0181	303,299	666,027 No	Fluvial - adjacent to	adjacent to site	Yes	N/A	None known		No
E-LV 25	Livingston	Employment	former rosebank nursery	ELv39d & EOI- 0181	303,468	666,023 No	Νο	going through site	Yes	N/A	None known	No developer requirements mentioned. We require a FRA to determine the flood risk to the site from the Killandean Burn and small drain running through the site. The majority of the site is likely to be developable and site layout and topographic information may be sufficient to determine risk.	No
												Developer requirements mentions "Flood Risk	
E-LV 26	Livingston	Employment	alba campus	ELv42c	303,098	665,396 No	Fluvial - small part	None	Yes	N/A	None known	Assessment required due to proximity of Harwood Water & West Calder Burn". We support request for FRA although majority of site likely developable and site layout and	Yes
												Developer requirements mentions "Flood Risk Assessment required due to proximity of West Calder Burn". We support this request for FRA although majority of site likely developable and site layout and topographic information	
E-LV 27 E-LV 29a	Livingston Livingston	Employment Employment	alba campus alba campus	ELv41d	303,107 303,617	665,672 No 665,453 No	Fluvial - adjacent to Surface water – adjacent to	None adjacent to site	Yes Yes	N/A N/A	None known None known		Yes Yes
L-LV ∠Jd	Livingstull		aisa cumpus		505,017	003,733 110		agavon to one		ч <b>у</b> Л		No developer requirements mentioned. No developer requirements mentioned. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues in part of the site. This should be investigated further and it is recommended that contact is made with the flood prevention	
E-LV 29b	Livingston	Employment	alba campus		303,645	665,345 No	Surface water – part	adjacent to site	Yes	N/A	None known		Yes

D	Yes

No

No Yes

No No No No No No

No Yes

No Yes

Yes

No

No

No No No No

E-LV 29c E-LV 29d	Livingston Livingston	Employment Employment	alba campus alba campus	ELv44 & EOI-	303,591 303,441	665,254 No 665,216 No	Surface water – small pa No Surface water – adjacent	None	Yes No	N/A N/A	None known None known	No developer requirements mentioned. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues in part of the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. No developer requirements mentioned.	Yes Yes
E-LV 31 E-LV 32	Livingston Livingston	Employment Employment	macintosh rd west kirkton rd south	0036 ELv45	302,751 303,842	666,149 No 666,360 No	to No	None None	No No	N/A N/A	None known None known	No developer requirements mentioned. No developer requirements mentioned.	Yes Yes
E-LV 33	Livingston	Employment	gregory rd east	ELv46	303,980	665,994 10/27	Surface water – small pa	rt on boundary	Yes	N/A	None known	No developer requirements mentioned. We require a FRA for the small watercourse on the northern boundary. The majority of the site is likely developable and site layout and topographical information may be sufficient. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues along the east and south parts of the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
												No developer requirements mentioned. We require a FRA for the small watercourses running along the western boundary and through the middle of the site. The impact of	
E-LV 34	Livingston	Employment	kirkton rd south	ELv47		666,250 10/27	Surface water – part	going through site	Yes	N/A	None known	culverts on flood levels should be considered. No developer requirements mentioned. We require a FRA for the small watercourse running through the site (culverted in parts) and also running along the northern boundary. Development should not take place on top of, or immediately adjacent to,	
E-LV 35	Livingston	Employment	gregory rd west	ELv48		665,736 10/27	Surface water – small pa		Yes	N/A	None known	culverted watercourses. No developer requirements mentioned. We require a FRA for the small watercourse on the northern boundary. The majority of the site is likely developable and site layout and topographical information may be sufficient. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues along the east and south parts of the site. This should be investigated further and it is recommended that contact is made with the	2
E-LV 36 E-LV 37	Livingston Livingston	Employment Employment	gregory rd williamston north	ELv49 ELv59a	304,221 306,910	666,028 10/27 665,592 No	Surface water – part No	adjacent to site None	Yes No	N/A N/A	None known None known	flood prevention officer. No developer requirements mentioned. Developer requirements mentions "A buffer strip required including recommended with a minimum of 6m width to the pond within the site". The pond appears to be in the larger site	No Yes
E-LV 38 E-LV 39	Livingston Livingston	Employment Employment	williamston north williamston south	ELv59b ELv60	306,606 307,028	665,505 No 665,402 No	Surface water – adjacent to No	None None	No No	N/A N/A	None known None known	from previous Local Plan rather than this smaller site. No developer requirements mentioned. Developer requirements mentions "Flood risk	Yes Yes
E-LV 40	Livingston	Employment	houston interchange	ELv68	305,274	669,103 10/27	Surface water – adjacent to	None	No	N/A	None known	assessment and Drainage Impact assessment required". We have no information on flood risk for this site. No developer requirements mentioned. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues in parts of the site. This should be investigated further and it is recommended that contact is made with the flood prevention	Yes
E-LV 41	Livingston	Employment	starlaw park	ELv57b	301,282	667,605 10/27	Surface water – small pa	rt None	Yes	N/A	None known	officer.	Yes
E-LV 42	Livingston	Employment	starlaw park	ELv57c	301,724	667,460 10/27	Surface water / fluvial – small part	None	Yes	N/A	None known	No developer requirements mentioned. We require a FRA for the small watercourse which runs under the Tailend Roundabout adjacent to the site. The SEPA flood map indicates that should the culvert under the roundabout surcharge the site may be impacted. The majority of the site is likely to be developable and site layout and topographic information may be sufficient.	No

No No	No No
No No	No No
No	Yes
No	Yes
No	Yes
No No	Yes No
No No	No No
No	No

No No

No Yes

E-LV 43 E-LV 44	Livingston Livingston	Employment Employment		ELv57d ELv61			Surface water – small par Surface water – adjacent to	t None None		N/A N/A	None known None known		No Yes
C-LV 44	LIVINGSLOIT	Employment		ELVOI	304,383	070,203 10/27	10	None	NO	N/A	None known	No developer requirements mentioned.	Tes
E-LV 45	Livingston	Employment	beugh burn	ELv64	305,412	670,563 10/27	Surface water / fluvial - part	multiple watercourses through site	Yes	N/A	None known	Developer requirements mentions "Re- alignment of Beugh Burn and integrated SUDS scheme". We would require a FRA to assess the risk to the site from the Beugh Burn and any proposed re-alignment works. A number of small watercourses/drains run through the site and flood risk from these should also be assessed. Developer requirements need to include requirement for FRA as re-alignment should not be undertaken without detailed assessment. Re-alignment works will also require CAR licence.	No
E-LV 46	Livingston	Employment	linhouse	ELv54 & EOI- 0099	306,790	664,783 No		multiple watercourses through site	Yes	N/A	None known	Developer requirements mentions "Separation of Linhouse Water and protection of watercourse from surface water contamination". We require a FRA to determine flood risk from the small watercourses that run through the site. This should include any culverted watercourses and no development should take place above these structures. The majority of the site is likely to be developable and site layout and topographical information may be sufficient.	No
												Developer requirements mentions "West Calder burn to south, possible requirement for Flood Risk Assessment and Drainage Impact Assessment". We would support recommendation for FRA to assess flood risk from West Calder Burn and also small watercourse which runs adjacent to B7015 at Gavieside. The majority of the site is likely to be developable and site layout and	
E-LV 48	Livingston	Employment	almond south gavieside	CDA-AS	302,570	665,754 No	Surface water – part	going through site	Yes	N/A	None known	topographic information may be sufficient.	Yes
E-LV 49	Livingston	Employment	cousland wood	EOI-0012	301,894	666,972 part 10/27	Surface water – small par	None	Yes	N/A	None known	No developer requirements mentioned.	Yes
E-LV 30	Livingston	Employment	macintosh rd	ELv43	302,864	666,294 No	Surface water – small par	None	Yes	N/A	None known	No developer requirements mentioned.	Yes
H-LV 1	Livingston	Housing	ballantyne place south	HLv26 HLv59 & EOI-	303,902	667,400 10/27	Surface water – part	going through site		Report of surface water flooding nearby in 2003.	None known	Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the small watercourses which flows through the east of the site (The Folly Burn). Consideration should be given to culverted structures within/nearby the site which may exacerbate flood risk to the site. The development may be constrained due to flood risk". We support this requirement. No developer requirements mentioned. We require a Flood Risk Assessment to determine flood risk to the site from the small watercourse on the southern boundary of the	Yes
H-LV 2	Livingston	Housing	murieston south 6a	0030	306,034	664,261 No	Surface water - small part	t on boundary	Yes	N/A	None known	site.	No
H-LV 3	Livingston	Housing	murieston south 8	HLv61	305,936	665,033 No	No	None	No	N/A	None known	Developer requirements mentions "Drainage Impact Assessment required". We have no further information on flood risk at this location Developer requirements mentions "Flood Risk	Yes
H-LV 4	Livingston	Housing	calder road	HLv73		665,133 10/27	No	on boundary		N/A	None known	Assessment required which assesses the flood risk from the small watercourse to the east of the site. Drainage Impact Assessment and sensitivity analysis required. Requirement to accommodate a buffer strip of 6m between the development and the watercourse at its eastern end". We support these requirements. Developer requirements mentions "Drainage Impact Assessment required to assess the impact of the development on the local network". We have no further information on	Yes
H-LV 5	Livingston	Housing	ettrick drive	HLv76	306,668	668,116 10/27	No	None	No	N/A	None known	flood risk at this site.	Yes

Yes No No

No Yes

No Yes

No No No No No No

No Yes No No No No No No

												Developer requirements mentions "Drainage Impact Assessment required to assess the impact of the development on the local	
H-LV 6	Livingston	Housing	forth drive	HLv79	306,872	668,145 10/27	No	None	No	N/A	None known	network". We have no further information on flood risk at this site.	Yes
H-LV 7	Livingston	Housing	dedridge east	HLv85	305,234	666,011 10/27	No	adjacent to site	No	N/A	None known	Developer requirements mentions "Drainage Impact Assessment required". We have no further information on flood risk in this area.	Yes
	J		U									Developer requirements mentions "Introduction of water resilience measures required. The site has a history of flooding and retaining runoff. There is a culverted watercourse traversing the site". Although no flood risk identified from SEPA flood maps or historic records, given the comments we would require a FRA to determine the flood risk from the culverted watercourse. There should also be no development above, or immediately adjacent to,	
H-LV 9	Livingston	Housing	kirkton north	HLv111	302,488	666,996 No	No	None	No	N/A	None known	a culverted watercourse.	No
												Developer requirements mentions "Risk of flood water accumulating on Hardie Road. Measures required to ensure that runoff can be satisfactorily dealt with". There is a possible culvert running through this site and should this be the case a FRA should be	
H-LV 10 H-LV 11	Livingston Livingston	Housing Housing	deans west hardie rd brucefield industrial	HLv122 HLv136	301,761 303,834	669,113 10/27 664,434 part 10/27	No No	adjacent to site None	No No	N/A N/A	None known None known	provided to assess the flood risk. No developer requirements mentioned.	Yes Yes
H-LV 11	Livingston	Housing	brucefield industrial		303,962	664,238 part 10/27	No	None	No	N/A	None known	Assessment required which assesses the flood risk from the River Almond and the small watercourse which flows through the south east corner of the site. Consideration should be	Yes
										FRAs have been carried out previously for		given to any structures which may increase flood risk to the site". We support the	
H-LV 12	Livingston	Housing	land north of almondvale stadium		304,766	667,031 10/27	Fluvial - small part	None	Yes	adjacent sites.	None known	requirement for a FRA.	Yes
							Surface water / fluvial -			FRA has been carried out for proposed		<ul> <li>Developer requirements mentions "Flood Risk</li> <li>Assessment required. Drainage Impact</li> <li>Assessment required". We support this and</li> <li>would require a FRA to determine risk to site</li> <li>from Breich Water and River Almond.</li> <li>Consideration should be given to any</li> <li>structures which may increase flood risk to the</li> <li>site. Review of the surface water 1 in 200 year</li> <li>flood map shows that there may be flooding</li> <li>issues to parts of the site. This should be</li> <li>investigated further and it is recommended</li> <li>that contact is made with the flood prevention</li> </ul>	2
H-LV 13 H-LV 14	Livingston Livingston	Housing Housing	Gavieside Farm appleton parkway south east	EOI-0024	302,159 302,910	665,321 No 667,234 No	part Surface water – part	None None	Yes Yes	development in this area N/A	None known None known		Yes Yes
	-	-		EOI-0002, EOI- 0043 & EOI-									
H-LV 15	Livingston	Housing	kirkton business centre	0117	303,792	667,050 No	No	None	No	N/A	None known	No developer requirements mentioned.	Yes
H-LV 17	Livingston	Housing	almond link rd	EOI-0158	305,934	667,241 10/27	Fluvial - part	None	Yes	FRA carried out by Kaya in 2015 for northern part of this site	None known	Developer requirements mentions "Flood Risk Assessment required. Requirement to accommodate a buffer strip of 6m to 12m between the development and the River Almond". We support the requirement for FRA. We previously removed objection to development in northern part of this site following submission of FRA but any changes to the proposals in 0239/FUL/15 would require further information submitted.	Yes
										Topographic information provided as part of application		Developer requirements mentions "Some susceptibility to pluvial flooding. History of flooding associated with the flow of surface water from Kenilworth Rise. Flood Risk Assessment required". We had no objection to 0239/FUL/15 at this site following provision of information on site levels and proposed floor levels. Should there be any changes to the proposals we would require further information. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues to parts of the site. This should be investigated further and it is recommended that contact is made with the	
H-LV 18 H-LV 20	Livingston Livingston	Housing Housing	dedridge east road glenn road broomyknowes drive	EOI-0172 DI28	305,672 302,485	666,514 10/27 668,713 10/27	Surface water – part No	adjacent to site None	Yes No	(0239/FUL/15) at this site N/A	None known None known	•	Yes Yes

												Developer requirements mentions "Drainage	
												Impact Assessment required to assess the impact of the development on the local network" We have no further information or	
H-LV 6	Livingston	Housing	forth drive	HLv79	306,872	668,145 10/27	No	None	No	N/A	None known	network". We have no further information or flood risk at this site.	Yes
H-LV 7	Livingston	Housing	dedridge east	HLv85	305,234	666,011 10/27	No	adjacent to site	No	N/A	None known	Developer requirements mentions "Drainage Impact Assessment required". We have no further information on flood risk in this area.	
												Developer requirements mentions "Introduction of water resilience measures required. The site has a history of flooding and retaining runoff. There is a culverted watercourse traversing the site". Although no flood risk identified from SEPA flood maps or historic records, given the comments we would require a FRA to determine the flood risk from the culverted watercourse. There should also be no development above, or immediately adjacent to	1 - -
H-LV 9	Livingston	Housing	kirkton north	HLv111	302,488	666,996 No	No	None	No	N/A	None known	a culverted watercourse.	No
												Developer requirements mentions "Risk of flood water accumulating on Hardie Road. Measures required to ensure that runoff can be satisfactorily dealt with". There is a possible culvert running through this site and should this be the case a FRA should be	
H-LV 10 H-LV 11	Livingston Livingston	Housing Housing	deans west hardie rd brucefield industrial	HLv122 HLv136	301,761 303,834	669,113 10/27 664,434 part 10/27	No No	adjacent to site None	No No	N/A N/A	None known None known	provided to assess the flood risk. No developer requirements mentioned.	Yes Yes
H-LV 11	Livingston	Housing	brucefield industrial		303,962	664,238 part 10/27	No	None	No	N/A FRAs have been carried	None known	No developer requirements mentioned. Developer requirements mentions Flood Kisk Assessment required which assesses the flood risk from the River Almond and the small watercourse which flows through the south eas corner of the site. Consideration should be given to any structures which may increase	
H-LV 12	Livingston	Housing	land north of almondvale stadium		304,766	667,031 10/27	Fluvial - small part	None	Yes	out previously for adjacent sites.	None known	flood risk to the site". We support the requirement for a FRA.	Yes
										FRA has been carried out		Developer requirements mentions "Flood Risk Assessment required. Drainage Impact Assessment required". We support this and would require a FRA to determine risk to site from Breich Water and River Almond. Consideration should be given to any structures which may increase flood risk to the site. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues to parts of the site. This should be investigated further and it is recommended	e
H-LV 13	Livingston	Housing	Gavieside Farm	EOI-0024	302,159 302,910	665,321 No 667,234 No	Surface water / fluvial - part Surface water – part	None None	Yes	for proposed development in this area N/A	None known None known	that contact is made with the flood prevention officer.	n Yes Yes
H-LV 14	Livingston	Housing	appleton parkway south east	EOI-0024 EOI-0002, EOI- 0043 & EOI-	502,910	007,234 NU	Sunace water – part	None	Yes	N/A	Note known	No developer requirements mentioned.	163
H-LV 15	Livingston	Housing	kirkton business centre	0117	303,792	667,050 No	No	None	No	N/A	None known	No developer requirements mentioned.	Yes
H-LV 17	Livingston	Housing	almond link rd	EOI-0158	305,934	667,241 10/27	Fluvial - part	None	Yes	FRA carried out by Kaya in 2015 for northern part of this site	None known	Developer requirements mentions "Flood Risk Assessment required. Requirement to accommodate a buffer strip of 6m to 12m between the development and the River Almond". We support the requirement for FRA. We previously removed objection to development in northern part of this site following submission of FRA but any changes to the proposals in 0239/FUL/15 would require further information submitted.	Yes
										Topographic information provided as part of application		Developer requirements mentions "Some susceptibility to pluvial flooding. History of flooding associated with the flow of surface water from Kenilworth Rise. Flood Risk Assessment required". We had no objection to 0239/FUL/15 at this site following provision of information on site levels and proposed floor levels. Should there be any changes to the proposals we would require further information. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues to parts of the site. This should be investigated further and it is recommended that contact is made with the	
H-LV 18 H-LV 20	Livingston Livingston	Housing Housing	dedridge east road glenn road broomyknowes drive	EOI-0172 DI28	305,672 302,485	666,514 10/27 668,713 10/27	Surface water – part No	adjacent to site None	Yes No	(0239/FUL/15) at this site N/A	None known None known	flood prevention officer. No developer requirements mentioned.	Yes Yes

												Developer requirements mentions "Drainage Impact Assessment required to assess the impact of the development on the local network". We have no further information or	
H-LV 6	Livingston	Housing	forth drive	HLv79	306,872	668,145 10/27	No	None	No	N/A	None known	flood risk at this site.	Yes
H-LV 7	Livingston	Housing	dedridge east	HLv85	305,234	666,011 10/27	No	adjacent to site	No	N/A	None known	Developer requirements mentions "Drainage Impact Assessment required". We have no further information on flood risk in this area.	Yes
												Developer requirements mentions "Introduction of water resilience measures required. The site has a history of flooding and retaining runoff. There is a culverted watercourse traversing the site". Although no flood risk identified from SEPA flood maps or historic records, given the comments we would require a FRA to determine the flood risk from the culverted watercourse. There should also be no development above, or immediately adjacent to	, ,
H-LV 9	Livingston	Housing	kirkton north	HLv111	302,488	666,996 No	No	None	No	N/A	None known	a culverted watercourse. Developer requirements mentions "Risk of	No
												flood water accumulating on Hardie Road. Measures required to ensure that runoff can be satisfactorily dealt with". There is a possible culvert running through this site and should this be the case a FRA should be	
H-LV 10 H-LV 11	Livingston Livingston	Housing Housing	deans west hardie rd brucefield industrial	HLv122 HLv136	301,761 303,834	669,113 10/27 664,434 part 10/27	No No	adjacent to site None	No No	N/A N/A	None known None known	provided to assess the flood risk. No developer requirements mentioned.	Yes Yes
H-LV 11	Livingston	Housing	brucefield industrial		303,962	664,238 part 10/27	No	None	No	N/A	None known	No developer requirements mentioned. Developer requirements mentions rood risk Assessment required which assesses the flood risk from the River Almond and the small watercourse which flows through the south eas corner of the site. Consideration should be	Yes
										FRAs have been carried out previously for		given to any structures which may increase flood risk to the site". We support the	
H-LV 12	Livingston	Housing	land north of almondvale stadium		304,766	667,031 10/27	Fluvial - small part	None	Yes	adjacent sites.	None known	requirement for a FRA.	Yes
										FRA has been carried out		Developer requirements mentions "Flood Risk Assessment required. Drainage Impact Assessment required". We support this and would require a FRA to determine risk to site from Breich Water and River Almond. Consideration should be given to any structures which may increase flood risk to the site. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues to parts of the site. This should be investigated further and it is recommended	e
H-LV 13	Livingston	Housing	Gavieside Farm		302,159	665,321 No	Surface water / fluvial - part	None	Yes	for proposed development in this area	None known	that contact is made with the flood prevention officer.	n Yes
H-LV 14	Livingston	Housing	appleton parkway south east	EOI-0024 EOI-0002, EOI- 0043 & EOI-	302,910	667,234 No	Surface water – part	None	Yes	N/A	None known	No developer requirements mentioned.	Yes
H-LV 15	Livingston	Housing	kirkton business centre	0117	303,792	667,050 No	No	None	No	N/A	None known	No developer requirements mentioned.	Yes
H-LV 17	Livingston	Housing	almond link rd	EOI-0158	305,934	667,241 10/27	Fluvial - part	None	Yes	FRA carried out by Kaya in 2015 for northern part of this site	None known	Developer requirements mentions "Flood Risk Assessment required. Requirement to accommodate a buffer strip of 6m to 12m between the development and the River Almond". We support the requirement for FRA. We previously removed objection to development in northern part of this site following submission of FRA but any changes to the proposals in 0239/FUL/15 would require further information submitted.	Yes
										Topographic information provided as part of application		Developer requirements mentions "Some susceptibility to pluvial flooding. History of flooding associated with the flow of surface water from Kenilworth Rise. Flood Risk Assessment required". We had no objection to 0239/FUL/15 at this site following provision of information on site levels and proposed floor levels. Should there be any changes to the proposals we would require further information. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues to parts of the site. This should be investigated further and it is recommended that contact is made with the	
H-LV 18 H-LV 20	Livingston Livingston	Housing Housing	dedridge east road glenn road broomyknowes drive	EOI-0172 DI28	305,672 302,485	666,514 10/27 668,713 10/27	Surface water – part No	adjacent to site None	Yes No	(0239/FUL/15) at this site N/A	None known None known	flood prevention officer. No developer requirements mentioned.	Yes Yes

												Developer requirements mentions "Drainage	
												Impact Assessment required to assess the	
												impact of the development on the local network". We have no further information on	1
H-LV 6	Livingston	Housing	forth drive	HLv79	306,872	668,145 10/27	No	None	No	N/A	None known	flood risk at this site.	Yes
												Developer requirements mentions "Drainage	
	15 de cetere	Ulausiaa		111-05	205 224		N	adiacant ta aita	N	N1/A	Negelar	Impact Assessment required". We have no	Vaa
H-LV 7	Livingston	Housing	dedridge east	HLv85	305,234	666,011 10/27	No	adjacent to site	No	N/A	None known	further information on flood risk in this area. Developer requirements mentions "Introduction	
												of water resilience measures required. The site	
												has a history of flooding and retaining runoff. There is a culverted watercourse traversing the	
												site". Although no flood risk identified from SEPA flood maps or historic records, given the	
												comments we would require a FRA to	
												determine the flood risk from the culverted watercourse. There should also be no	
H-LV 9	Livingston	Housing	kirkton north	HLv111	302,488	666,996 No	No	None	No	N/A	None known	development above, or immediately adjacent to, a culverted watercourse.	, No
H-LV 9	Livingston	Housing			302,400	000,990 100	NO	None	NO	N/A	None known		NO
												Developer requirements mentions "Risk of flood water accumulating on Hardie Road.	
												Measures required to ensure that runoff can	
												be satisfactorily dealt with". There is a possible culvert running through this site and	
												should this be the case a FRA should be	
H-LV 10 H-LV 11	Livingston Livingston	Housing Housing	deans west hardie rd brucefield industrial	HLv122 HLv136	301,761 303,834	669,113 10/27 664,434 part 10/27	No No	adjacent to site None	No No	N/A N/A	None known None known	provided to assess the flood risk. No developer requirements mentioned.	Yes Yes
H-LV 11	Livingston	Housing	brucefield industrial	HEVISO	303,962	664,238 part 10/27	No	None	No	N/A	None known	No developer requirements mentioned.	Yes
												Assessment required which assesses the flood	
												risk from the River Almond and the small watercourse which flows through the south east	t
										FRAs have been carried		corner of the site. Consideration should be given to any structures which may increase	
										out previously for		flood risk to the site". We support the	
H-LV 12	Livingston	Housing	land north of almondvale stadium		304,766	667,031 10/27	Fluvial - small part	None	Yes	adjacent sites.	None known	requirement for a FRA.	Yes
												Developer requirements mentions "Flood Risk	
												Assessment required. Drainage Impact Assessment required". We support this and	
												would require a FRA to determine risk to site	
												from Breich Water and River Almond. Consideration should be given to any	
												structures which may increase flood risk to the	
												site. Review of the surface water 1 in 200 year flood map shows that there may be flooding	
												issues to parts of the site. This should be	
							Surface water / fluvial -			FRA has been carried out for proposed		investigated further and it is recommended that contact is made with the flood prevention	n
H-LV 13	Livingston	Housing	Gavieside Farm		302,159	665,321 No	part	None	Yes	development in this area		officer.	Yes
H-LV 14	Livingston	Housing	appleton parkway south east	EOI-0024 EOI-0002, EOI-	302,910	667,234 No	Surface water – part	None	Yes	N/A	None known	No developer requirements mentioned.	Yes
	Livingston	Housing	kielten husingss gentra	0043 & EOI-	202 702		No	None	No	NI / A	Noneknown	No doualanar requirements montioned	Vee
H-LV 15	Livingston	Housing	kirkton business centre	0117	303,792	667,050 No	No	None	No	N/A	None known	No developer requirements mentioned.	Yes
												Developer requirements mentions "Flood Risk	
												Assessment required. Requirement to	
												accommodate a buffer strip of 6m to 12m between the development and the River	
												Almond". We support the requirement for	
												FRA. We previously removed objection to development in northern part of this site	
										FRA carried out by Kaya		following submission of FRA but any changes	
H-LV 17	Livingston	Housing	almond link rd	EOI-0158	305,934	667,241 10/27	Fluvial - part	None	Yes	in 2015 for northern part of this site	None known	to the proposals in 0239/FUL/15 would require further information submitted.	Yes
	Livingston	Housing		201-0138	505,554	007,241 10/27		None	163	of this site	None known	require further mornation submitted.	100
												Developer requirements mentions "Some	
												susceptibility to pluvial flooding. History of	
												flooding associated with the flow of surface water from Kenilworth Rise. Flood Risk	
												Assessment required". We had no objection	
												to 0239/FUL/15 at this site following provision of information on site levels and proposed	
												floor levels. Should there be any changes to	
												the proposals we would require further information. Review of the surface water 1 in	
												200 year flood map shows that there may be	
										Topographic information provided as part of		flooding issues to parts of the site. This should be investigated further and it is	
										application		recommended that contact is made with the	
H-LV 18 H-LV 20	Livingston Livingston	Housing Housing	dedridge east road glenn road broomyknowes drive	EOI-0172 DI28	305,672 302,485	666,514 10/27 668,713 10/27	Surface water – part No	adjacent to site None	Yes No	(0239/FUL/15) at this site N/A	None known None known	flood prevention officer. No developer requirements mentioned.	Yes Yes
		0		-	,	,,		-					

No	No
No	No
No	Yes
No No No	No No No
No	No
No No	No No
No	No
No	No
No	No

No No No No

NBM     NBM     NAM     NAM     NAM     NAM     NAM     NAM     NAM     NAMM     NAM													Assessment required. A 450mm surface water pipe transects the site and Scottish Water should be engaged to access what protective measures or possible re-routing of infrastructure is required". We have no further information on flood risk at this location but should West Lothian Council have information to indicate flood risk we support the requirement for FRA. We would recommend that there is no development on,	
1 Augu	H-LV 21	Livingston	Housing	glen road rear of new deans house	EOI-0180	302,510	668,796 10/27	Surface water – part	None	No	N/A	None known	sewer. Developer requirements mentions "Site subject	Yes
1100     1000	H-LV 22	Livingston	Housing	kirkton north road	EOI-0209	304,256	667,296 10/27	Surface water – small p	art None	No	N/A	None known	•	Yes
1 Nice Name Nam											carried out for site (WSP, 2014). FRA also carried		site susceptible to pluvial flooding. Flood Risk Assessment required". We support the requirement for a FRA to assess the risk to the site from the Nell Burn. Consideration should be given to any structures i.e. culverts or bridges, which may impact on the risk to the	
i N more is no more is not set in the	H-LV 23	Livingston	Housing	houston road north	EOI-0221	302,913	668,219 10/27			Yes	area.	None known	developable.	Yes
Horizon     Augence	H-LV 24	Livingston	Housing	eagle brae depot	PJ-0005	304,724	667,961 10/27			No	N/A	None known	No developer requirements mentioned.	Yes
<ul> <li>I vision</li> <li>Vision</li> <li>Vision <li>Vision</li> <li>Vision</li> <li>Vis</li></li></ul>	H-LV 25	Livingston	Housing	deans south phase 1	-	302,361	668,298 10/27			No	flooding nearby in	None known	record of surface water flooding nearby. Flood Risk Assessment required". We have no further	
Horizo         Isolati Source contractor         Kali SP 000 (0.000)	H-LV 26	Livingston	Housing	deans south phase 2	•	302,661	668,388 10/27			No	flooding nearby in	None known	record of surface water flooding nearby. Flood Risk Assessment required". We have no further	
invest     invest <td></td> <td>•</td> <td>•</td> <td></td> <td>3)</td> <td>-</td> <td>, ,</td> <td>•</td> <td></td> <td></td> <td>flooding nearby in August 2008.</td> <td></td> <td>record of surface water flooding nearby. Flood Risk Assessment required". We have no further information on flood risk at this site.</td> <td>Yes</td>		•	•		3)	-	, ,	•			flooding nearby in August 2008.		record of surface water flooding nearby. Flood Risk Assessment required". We have no further information on flood risk at this site.	Yes
MU2       Unigator       Housing       multieston valley road       LC2 TOU & ECD TOU & E	H-LV 29	Livingston	Housing	howden south road	TCU1	305,740	667,111 10/27	Fluvial - part	None	Yes	by Mott MacDonald for Rivers and Fisheries Trusts of Scotland to investigate potential removal of Howden Bridge Weir. This does not extend to full site but indicates potential risk to	t	require a FRA to assess the risk to the site from the River Almond. This should consider any impacts of structures i.e. culverts and	No
H W31       Linegeton       Housing       municition valley road       L2       Point	H-LV 30	Livingston	Housing	land south of almondvale stadium		304,740	666,856 10/27	Surface water – small p	art None	No	N/A	None known	No developer requirements mentioned.	Yes
M22       Uvingston       Mixed Use       Site north of almondvale way       0.06       30,6469       666,554 10/27       Surface water - andjoer       No       No       No       No       None known       Not included within table in proposed plan?         MU3       Livingston       Mixed Use       Site north of almondvale road       305,340       666,92 10/27       to       None       No       N/A       None known       Noticituded within table in proposed plan?         MU6       Uvingston       Mixed Use       Site north of almondvale road       TO2       30,320       666,92 10/27       None       None       No       N/A       None known       Noticituded within table in proposed plan?         MU6       Uvingston       Mixed Use       site wast of almondvale road       TO2       30,132       666,62 10/27       Surface water - adjacent       no houndary       No       N/A       None known       Note known       Note included within table in proposed plan?         MU4       Uvingston       Mixed Use       site wast of almondvale road       TO2       30,132       666,62 10/27       Surface water - adjacent       no houndary       No       N/A       None known       No readjacent for histo transite water almondvale with table in proposed plan?         MU4       Livingston       Mixed Use	H-LV 31	Livingston	Housing	murieston valley road		305,288	664,618 10/27	No	adjacent to site	No	N/A	None known	Impact Assessment required". We have no	Yes
MU3       Livingston       Mixed Use       Site north of almondvale road       305,340       666,492 10/27       to       None       No       N/A       None known       Not included within table in proposed plan?         MU5       Livingston       Mixed Use       site west of almondvale road       TO2       304,322       666,602 10/27       To       None       No       N/A       None known       Not included within table in proposed plan?         MU5       Livingston       Mixed Use       site west of almondvale road       TO2       304,322       666,602 10/27       To       None       No       N/A       None known       Not included within table in proposed plan?         MU5       Livingston       Mixed Use       site west of almondvale road       TO2       304,322       666,602 10/27       To       No	MU2	Livingston	Mixed Use	Site north of almondvale way		305,469	666,554 10/27	•		No	N/A	None known	Not included within table in proposed plan?	
MU6 Livingston Mixed Use site west of almondvale roundabout TCU2 304,32 666,002 10/27 to on boundary Yes N/A None known any structures on flood risk should be considered. Not included within table in proposed plan? We require a F/A to assess the flood risk to be site west of almondvale way TCU4 304,35 66,118 10/27 Surface water - part on boundary Yes N/A None known any structures on flood risk should be considered. MU4 Livingston Mixed Use site south of almondvale way TCU4 304,35 66,118 10/27 Surface water - part on boundary Yes N/A None known flood risk should be investigated further and it is recommended that contacter may be flood risk to be the site. This should be investigated further and it is recommended that contacter may be flood risk should be investigated further and it is recommended that contacter may be flood risk should be investigated further and it is recommended that contacter south or almondrale way to CU4 as sets the flood risk should be investigated further and it is recommended that contacter south or almondrale way to CU4 as sets the flood risk should be investigated further and it is recommended that contacter south or almondrale way to CU4 as sets the flood risk to be investigated further and it is recommended that contacter south or almondrale way to CU4 as sets the flood risk to be investigated further and it is recommended that contacter south or almondrale way to CU4 as sets the flood risk to be investigated further and it is recommended that contacter south or almondrale way to the set for the sate flood risk to be investigated further and it is recommended that contacter south or almondrale way to CU4 as sets the flood risk to be the flood recommended that contacter south or almondrale way to cut as sets the flood risk to be the flood recommended that contacter south or almondrale way to cut as sets the flood risk to be the flood recommended that contacter south risk to and within table in proposed plan?	MU3	Livingston	Mixed Use	Site north of almondvale road		305,340	666,492 10/27	•		No	N/A	None known	Not included within table in proposed plan? We require a FRA to assess the flood risk to	
MU4 Livingston Mixed Use site south of almondvale way TCU4 304,353 666,118 10/27 Surface water – part on boundary Yes N/A None known flood prevention officer.	MU6	Livingston	Mixed Use	site west of almondvale roundabout	TCU2	304,732	666,602 10/27			Yes	N/A	None known	any structures on flood risk should be considered.	
We require a FRA to assess the flood risk to the site from the small watercourse running along the northern site boundary. Impacts of any structures on flood risk should be	MU4	Livingston	Mixed Use	site south of almondvale way	TCU4	304,353	666,118 10/27	Surface water – part	on boundary	Yes	N/A	None known	We require a FRA to assess the flood risk to the site from the small watercourse running along the western site boundary. Impacts of any structures on flood risk should be considered. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues to parts of the site. This should be investigated further and it is recommended that contact is made with the	
Livingston Mixed Use LIV31 304,420 665,956 10/27 Surface water – small part on boundary Yes N/A None known considered. Same site as MU5?													We require a FRA to assess the flood risk to the site from the small watercourse running along the northern site boundary. Impacts of any structures on flood risk should be	
		Livingston	Mixed Use		LIV31	304,420	665,956 10/27	Surrace water – small p	art on boundary	Yes	N/A	None known	considered. Same site as MU5?	

												Assessment required. A 450mm surface water pipe transects the site and Scottish Water should be engaged to access what protective measures or possible re-routing of infrastructure is required". We have no further information on flood risk at this location but should West Lothian Council have information to indicate flood risk we support the requirement for FRA. We would recommend that there is no development on,	
H-LV 21	Livingston	Housing	glen road rear of new deans house	EOI-0180	302,510	668,796 10/27	Surface water – part	None	No	N/A	None known	or immediately adjacent to, the surface water sewer. Developer requirements mentions "Site subject to some pluvial flooding. Flood Risk	Yes
H-LV 22	Livingston	Housing	kirkton north road	EOI-0209	304,256	667,296 10/27	Surface water – small pa	rt None	No	N/A	None known	Assessment required". We have no further information on flood risk at this location.	Yes
										Level 1 FRA has been carried out for site (WSP, 2014). FRA also carried out by WLC for wider		Developer requirements mentions "Parts of site susceptible to pluvial flooding. Flood Risk Assessment required". We support the requirement for a FRA to assess the risk to the site from the Nell Burn. Consideration should be given to any structures i.e. culverts or bridges, which may impact on the risk to the site. It is likely the majority of the site is	
H-LV 23	Livingston	Housing	houston road north	EOI-0221	302,913	668,219 10/27	Surface water – small pa Surface water – adjacent		Yes	area.	None known	developable.	Yes
H-LV 24	Livingston	Housing	eagle brae depot	PJ-0005	304,724	667,961 10/27	to	None	No	N/A	None known	No developer requirements mentioned.	Yes
H-LV 25	Livingston	Housing	deans south phase 1	HLv137 (Phase 1)	302,361	668,298 10/27	Surface water – adjacent to	None	No	Record of surface water flooding nearby in August 2008.	None known	Developer requirements mentions "There is a record of surface water flooding nearby. Flood Risk Assessment required". We have no further information on flood risk at this site.	Yes
H-LV 26	Livingston	Housing	deans south phase 2	HLv137 (Phase 2)	302,661	668,388 10/27	Surface water – adjacent to	None	No	Record of surface water flooding nearby in August 2008.	None known	Developer requirements mentions "There is a record of surface water flooding nearby. Flood Risk Assessment required". We have no further information on flood risk at this site.	Yes
H-LV 27 H-LV 28	Livingston Livingston	Housing Housing	deans south remainder deans south road	HLv137 (Phase 3) LIV12	302,528 302,703	668,337 10/27 668,604 10/27	Surface water – part No	None None	Yes No	Record of surface water flooding nearby in August 2008. N/A	None known None known	Developer requirements mentions "There is a record of surface water flooding nearby. Flood Risk Assessment required". We have no further information on flood risk at this site. No developer requirements mentioned.	Yes Yes
H-LV 29	Livingston	Housing	howden south road	TCU1	305,740	667,111 10/27	Fluvial - part	None	Yes	FRA has been carried out by Mott MacDonald for Rivers and Fisheries Trusts of Scotland to investigate potential removal of Howden Bridge Weir. This does not extend to full site but indicates potential risk to part of site.		No developer requirements mentioned. We require a FRA to assess the risk to the site from the River Almond. This should consider any impacts of structures i.e. culverts and bridges	No
H-LV 30	Livingston	Housing	land south of almondvale stadium	1001	304,740	666,856 10/27	Surface water – small pa		No	N/A	None known	No developer requirements mentioned.	Yes
H-LV 30	Livingston	nousing			504,740	000,830 10/27	Sunace water – Smar pa	t None	NU	N/A	None known	Developer requirements mentions "Drainage Impact Assessment required". We have no	163
H-LV 31	Livingston	Housing	murieston valley road	LC2 TCU3 & EOI-	305,288	664,618 10/27	No	adjacent to site	No	N/A	None known	further information on flood risk in this area.	Yes
MU2	Livingston	Mixed Use	Site north of almondvale way	0106	305,469	666,554 10/27	Surface water – small pa Surface water – adjacent	rt None	No	N/A	None known	Not included within table in proposed plan?	
MU3	Livingston	Mixed Use	Site north of almondvale road		305,340	666,492 10/27	to Surface water – adjacent	None	No	N/A	None known	Not included within table in proposed plan? Not included within table in proposed plan? We require a FRA to assess the flood risk to the site from the small watercourse running along the northern site boundary. Impacts of any structures on flood risk should be	
MU6	Livingston	Mixed Use	site west of almondvale roundabout			666,602 10/27	to	on boundary	Yes	N/A	None known	considered. Not included within table in proposed plan? We require a FRA to assess the flood risk to the site from the small watercourse running along the western site boundary. Impacts of any structures on flood risk should be considered. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues to parts of the site. This should be investigated further and it is recommended that contact is made with the	
MU4	Livingston	Mixed Use	site south of almondvale way	TCU4	304,353	666,118 10/27	Surface water – part	on boundary	Yes	N/A	None known	flood prevention officer. Not included within table in proposed plan? We require a FRA to assess the flood risk to the site from the small watercourse running along the northern site boundary. Impacts of any structures on flood risk should be	
	Livingston	Mixed Use		LIV31	304,420	665,956 10/27	Surface water – small pa	rt on boundary	Yes	N/A	None known	considered. Same site as MU5?	

n.d.     i.e.g.     i.e.g. <th></th> <th>Assessment required. A 450mm surface water pipe transects the site and Scottish Water should be engaged to access what protective measures or possible re-routing of infrastructure is required". We have no further information on flood risk at this location but should West Lothian Council have information to indicate flood risk we support the requirement for FRA. We would recommend that there is no development on,</th> <th></th>													Assessment required. A 450mm surface water pipe transects the site and Scottish Water should be engaged to access what protective measures or possible re-routing of infrastructure is required". We have no further information on flood risk at this location but should West Lothian Council have information to indicate flood risk we support the requirement for FRA. We would recommend that there is no development on,	
· 1 (2)     · 1 (2)	H-L	V 21 Livingstor	Housing	glen road rear of new deans house	EOI-0180	302,510	668,796 10/27	Surface water – part	None	No	N/A	None known	Developer requirements mentions "Site subject to some pluvial flooding. Flood Risk	Yes
1.1     1.2 <td>H-L</td> <td>V 22 Livingstor</td> <td>Housing</td> <td>kirkton north road</td> <td>EOI-0209</td> <td>304,256</td> <td>667,296 10/27</td> <td>Surface water – small pa</td> <td>rt None</td> <td>No</td> <td>N/A</td> <td>None known</td> <td>•</td> <td>Yes</td>	H-L	V 22 Livingstor	Housing	kirkton north road	EOI-0209	304,256	667,296 10/27	Surface water – small pa	rt None	No	N/A	None known	•	Yes
N Desc     N Desc <td></td> <td>carried out for site (WSP, 2014). FRA also carried</td> <td></td> <td>site susceptible to pluvial flooding. Flood Risk Assessment required". We support the requirement for a FRA to assess the risk to the site from the Nell Burn. Consideration should be given to any structures i.e. culverts or bridges, which may impact on the risk to the</td> <td>2</td>											carried out for site (WSP, 2014). FRA also carried		site susceptible to pluvial flooding. Flood Risk Assessment required". We support the requirement for a FRA to assess the risk to the site from the Nell Burn. Consideration should be given to any structures i.e. culverts or bridges, which may impact on the risk to the	2
in 10 in the pine in solution     index magnetic sector in the pine interval	H-L	V 23 Livingston	Housing	houston road north	EOI-0221	302,913	668,219 10/27			Yes		None known		Yes
Image: state     Reading the state </td <td>H-L</td> <td>V 24 Livingstor</td> <td>Housing</td> <td>eagle brae depot</td> <td>PJ-0005</td> <td>304,724</td> <td>667,961 10/27</td> <td>•</td> <td></td> <td>No</td> <td>N/A</td> <td>None known</td> <td>No developer requirements mentioned.</td> <td>Yes</td>	H-L	V 24 Livingstor	Housing	eagle brae depot	PJ-0005	304,724	667,961 10/27	•		No	N/A	None known	No developer requirements mentioned.	Yes
Horse     Boday	H-L	V 25 Livingstor	Housing	deans south phase 1	•	302,361	668,298 10/27	,		No	flooding nearby in	None known	record of surface water flooding nearby. Flood Risk Assessment required". We have no further	
1 + 27         Unrys         Note: and the formation of the second matrix transfer o	H-L	V 26 Livingstor	Housing	deans south phase 2	•	302,661	668,388 10/27	•		No	flooding nearby in	None known	record of surface water flooding nearby. Flood Risk Assessment required". We have no further	
No.22       Markets	H-L	V 27 Livingstor	Housing	deans south remainder	HLv137 (Phase		668,337 10/27	Surface water – part	None		flooding nearby in	None known	record of surface water flooding nearby. Flood Risk Assessment required". We have no further	
<ul> <li>in the series of the series of</li></ul>	H-L	V 28 Livingston	Housing	deans south road	LIV12	302,703	668,604 10/27	No	None	No	N/A	None known	No developer requirements mentioned.	Yes
Here       Housing	H-L	V 29 Livingstor	n Housing	howden south road	TCU1	305,740	667,111 10/27	Fluvial - part	None	Yes	by Mott MacDonald for Rivers and Fisheries Trusts of Scotland to investigate potential removal of Howden Bridge Weir. This does not extend to full site but indicates potential risk to	)	require a FRA to assess the risk to the site from the River Almond. This should consider any impacts of structures i.e. culverts and	No
I W130       Howing to implementation will yr varitheting in proposed plant in the proposed plant in proposed plant	H-L	V 30 Livingstor	Housing	land south of almondvale stadium		304,740	666,856 10/27	Surface water – small pa	rt None	No	N/A	None known	No developer requirements mentioned.	Yes
N2       Uniget       Nied Use       Site north of aimondvale way       0.06       30,469       666,531 10/27       Surface water - andjourn       No       No       NA       Noe known       No knickled within table in proposed plan?         MU3       Uvingston       Mixed Use       Site north of aimondvale road       305,240       666,492 10/27       to       Nore       No       N/A       None known       No knickled within table in proposed plan?         MU6       Uvingston       Mixed Use       Site north of aimondvale road       TO2       301,32       666,602 10/27       Surface water - adjoorn       No       N/A       None known       No knickled within table in proposed plan?         MU6       Uvingston       Mixed Use       site west of aimondvale road ball       TO2       301,32       666,602 10/27       Surface water - adjoorn       no bondary       N/A       None known       No knickled within table in proposed plan?         MU4       Uvingston       Mixed Use       site south of aimondvale road ball       TO2       301,332       666,602 10/27       Surface water - part       on bondary       ves       N/A       None known       No knickled within table in proposed plan?         MU4       Uvingston       Mixed Use       site south of aimondvale way       TO4       301,332       666,602 10	H-L	V 31 Livingstor	Housing	murieston valley road		305,288	664,618 10/27	No	adjacent to site	No	N/A	None known	Impact Assessment required". We have no	Yes
MU3       Livingston       Niked Use       Site north of almondvale road       305,30       666,92 10/27       10       None       No       N/A       None known       Not included within table in proposed plan?         MU6       Livingston       Mixed Use       site west of almondvale road labor       TCU2       304,32       666,602 10/27       10       None       No       N/A       None known       Not included within table in proposed plan?         MU6       Livingston       Mixed Use       site west of almondvale road labor       TCU2       304,32       666,602 10/27       10       None       No       N/A       None known       Not included within table in proposed plan?         MU6       Livingston       Mixed Use       site west of almondvale road labor       TCU2       304,32       666,602 10/27       10       on boundary       Yes       N/A       None known       Not included within table in proposed plan?         MU4       Livingston       Mixed Use       site west of almondvale road labor       TCU4       304,33       666,118 10/27       Surface water - pair       on boundary       Yes       N/A       None known       Not included within table in proposed plan?         MU4       Livingston       Mixed Use       stee south of almondvale way       TCU4       304,33       6	MU	J2 Livingstor	Mixed Use	Site north of almondvale way		305,469	666,554 10/27	•		No	N/A	None known	Not included within table in proposed plan?	
MU6       Livingston       Mixed Use       site west of almondvale roundabue       TCU2       304,32       666,602 10/27       Io       on boundary       Yes       N/A       None known       any structures on flood risk should be considered.         MU6       Livingston       Mixed Use       site west of almondvale roundabue       TCU2       304,32       666,602 10/27       Io       on boundary       Yes       N/A       None known       any structures on flood risk should be considered.         MU4       Livingston       Mixed Use       site west of almondvale roundabue       TCU4       304,353       666,118 10/27       Surface water – part       on boundary       Yes       N/A       None known       Anoticulided within table in proposed plan?         MU4       Livingston       Mixed Use       site south of almondvale way       TCU4       304,353       666,118 10/27       Surface water – part       on boundary       Yes       N/A       None known       Anoticulided within table in proposed plan?         MU4       Livingston       Mixed Use       site south of almondvale way       TCU4       304,353       666,118 10/27       Surface water – part       on boundary       Yes       N/A       None known       Anoticulided within table in proposed plan?         We require a FRN to assessis the flood ris is to the site front is si	MU	J3 Livingston	n Mixed Use	Site north of almondvale road		305,340	666,492 10/27			No	N/A	None known	Not included within table in proposed plan? We require a FRA to assess the flood risk to the site from the small watercourse running	
MU4 Livingston Mixed Use site south of almondvale way TCU4 304,353 666,118 10/27 Surface water – part on boundary Yes N/A None known flood prevention officer.	ML	I6 Livingstor	Mixed Use	site west of almondvale roundabout	TCU2	304,732	666,602 10/27	•		Yes	N/A	None known	any structures on flood risk should be considered.	
We require a FRA to assess the flood risk to the site from the small watercourse running along the northern site boundary. Impacts of any structures on flood risk should be	ML	J4 Livingstor	n Mixed Use	site south of almondvale way	TCU4	304,353	666,118 10/27	Surface water – part	on boundary	Yes	N/A	None known	We require a FRA to assess the flood risk to the site from the small watercourse running along the western site boundary. Impacts of any structures on flood risk should be considered. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues to parts of the site. This should be investigated further and it is recommended that contact is made with the	
Livingston Mixed Use LIV31 304,420 665,956 10/27 Surface water – small part on boundary Yes N/A None known considered. Same site as MU5?													We require a FRA to assess the flood risk to the site from the small watercourse running along the northern site boundary. Impacts of any structures on flood risk should be	
		Livingstor	I Mixed Use		LIV31	304,420	065,956 10/2/	Surrace water – small pa	ii on boundary	Yes	N/A	None known	considered. Same site as MU5?	

Developer requirements mentions "Flood Risk Assessment required. A 450mm surface water

> No No No No

No No No No No No No No

No No No No

No Yes No No No No No No

No No No Yes

No Yes No Yes

MU1 MU7	Livingston	Mixed Use Mixed Use	site east of almondvale stadium former police station almondvale road	? TCU8	304,954 304,581	667,004 10/27 666,493 10/27	Fluvial - part No	None on boundary	Yes	N/A N/A	None known None known	Not included within table in proposed plan? We require a FRA to assess the flood risk to the site from the River Almond and the tributary to the south of the site. Not included within table in proposed plan? We require a FRA to assess the flood risk to the site from the small watercourse running along the northern site boundary. Impacts of any structures on flood risk should be considered.	
N 41 10			to see a sub- place a due to an ad-	TOUD	204 712		Surface water amalling	ort Niese	Ne	N/ A	Negelie	Net in shuded with in table in successful also 2	
MU8	Livingston	Mixed Use	temp car park, almondvale road	TCU9	304,712	666,387 10/27	Surface water – small pa	irt None	No	N/A	None known	Not included within table in proposed plan?	
MU9	Livingston	Mixed Use	site west of almondvale place	TCU10	304,718	666,244 10/27	Surface water – part	going through site	Yes	N/A	None known	Not included within table in proposed plan? We require a FRA to assess the flood risk to the site from the small watercourse running through the site. This appears to be partly culverted and the Impacts of any structures on flood risk should be considered.	n No
MU5	Livingston	Mixed Use	almondvale rbout south north of bluebell glade		304,420	665,956 10/27	Surface water – small pa	irt on boundary	Yes	N/A	None known	Not included within table in proposed plan? We require a FRA to assess the flood risk to the site from the small watercourse running along the northern site boundary. Impacts of any structures on flood risk should be considered. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues to parts of the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	No
mos	Livingston	WINCE OSC	Side Sell Bidde		504,420	003,550 10/27		ar on boundary				Not included within table in proposed plan and no reference? May possibly be a culverted watercourse running through site and if so	d
	Livingston	Other		COU35	305,143	666,284 10/27	No	culverted through site	Yes	N/A	None known	would require FRA to assess flood risk. Further information required as to existence of culvert	
	Livingston	Other (School)		EOI-0179	303,207	669,398 10/27	No	None	No	N/A	None known	Not in proposed plan and no reference?	
	Livingston	Retail		LC8	305,703	667,666 10/27	Surface water – small pa	irt None	Yes	N/A	None known	Not included within table in proposed plan and no reference?	
	Livingston	Retail		EOI-0155	304,670	665,757 10/27	No	None	No	N/A	None known	Not included within table in proposed plan and no reference?	
	_											Not included within table in proposed plan	
	Livingston	Retail (LNC)		LC3	303,480	668,720 10/27	Surface water – small pa	iit None	Yes	N/A	None known	and no reference?	
												Not included within table in proposed plan and no reference? We require a FRA to assess the risk to the site from the small watercourse (tributary of Murieston Water) running through site and also Murieston Water adjacent to eastern site boundary. The impact of structures i.e. culverts and bridges, on flood	2
	Livingston	Retail (LNC)		LC1	306,057	665,275 No	Surface water – part	going through site	Yes	N/A	None known	levels should be considered.	
	Livingston	Retail (LNC)		LC4	302,091	668,578 10/27	Surface water – small pa	art None	Yes	N/A	None known	Not included within table in proposed plan and no reference?	
	Livingston	Retail (LNC)		LC7	305,412	668,217 10/27	No	None	No	N/A	None known	Not included within table in proposed plan and no reference?	
	Livingston	Retail (LNC)		LC10	304,901	669,342 10/27	Surface water – small pa	art None	Yes	N/A	None known	Not included within table in proposed plan and no reference?	
	Livingston	Retail (LNC)		LC9	306,550	668,139 10/27	No	None	No	N/A	None known	Not included within table in proposed plan and no reference?	
	Livingston	Retail (LNC)		LC6	304,317	668,346 10/27	No	None	No	N/A	None known	Not included within table in proposed plan and no reference?	
	Livingston	Retail (LNC)		LC12	305,713	666,219 10/27	No	None	No	N/A	None known	Not included within table in proposed plan and no reference?	
	_				306,331	666,521 10/27	Surface water – small pa		Yes	N/A	None known	Not included within table in proposed plan and no reference?	
	Livingston	Retail (LNC)		LC13	·							Not included within table in proposed plan	
	Livingston	Retail (LNC)		LC11	304,712	665,708 10/27	Surface water – part	None	Yes	N/A	None known	and no reference? Not included within table in proposed plan	
	Livingston	Retail (LNC)		LC5	303,723	667,809 10/27	Surface water – part	None	Yes	N/A	None known	and no reference?	
E-LV 28 H-LR 1	Livingston Longridge	Employment Housing	alba campus curling pond lane	ELv41e HLr3	303,480 294,878	665,784 No 662,429 No	Surface water – small pa No	irt None None	Yes No	N/A N/A	None known None known	No developer requirements mentioned. No developer requirements mentioned. Developer requirements mentions "Flood KISK Assessment required. Drainage Impact Assessment required to assess the impact of the development on the local network". We	Yes Yes
H-LR 2	Longridge	Housing	fauldhouse rd north	HLr6	294,686	662,562 No	Surface water – small pa	art None	Yes	N/A	None known	have no further information on flood risk at this site.	Yes

No	Yes
No	Yes
No	No
No	Yes
No	Yes
No No	Yes No
No	No
No	No
No	No
No	Yes
No	No
No No	No No

No No

H-PU 1 H-PU 2	Pumpherston Pumpherston	-	drumshoreland kirkforthar brickworks pumpherston golf course	COU28		669,915 No 669,095 No	Surface water – part No	through site None	Yes No	No	None known None known	made with the flood prevention officer. Developer requirements states that a drainage impact assessment	yes yes
								multiple watercourses				Developer requirements state "flood risk assessment and drainage impact assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is	
Н-РВ 2	Polbeth	Housing		HWc10	302,510	664,255 No	Fluvial - adjacent to	adjacent to site	Yes	N/A	None known	Not mentioned in settlements in proposed plan. We require FRA to assess risk to site from West Calder Burn. Site layout and topographical information may be sufficient.	
H-PB 1	Polbeth	Housing	west calder high school	MIRQLATE2	303,706	664,226 No	Νο	None	Νο	N/A	None known	Developer requirements mentions "Previous record of surface water flooding on site. Flood Risk Assessment required". We have no further information on flood risk.	Yes
H-LW 1	Polbeth	Housing		15/41	302,024	664,305 No	Νο	going through site	Yes	N/A	None known	No developer requirements mentioned. We require a FRA for the small watercourse running through the site. It is likely the majority of the site is developable and site layout and topographic information may be sufficient.	No
	Polbeth	CDA		CDA-CB	301,960	663,538 No	Fluvial - part	None	Yes	Report of surface water flooding adjacent to site in July 2007.	None known	No developer requirements noted in proposed plan. We require a FRA to determine flood risk to site from the West Calder Burn. It is likely the majority of the site is developable and site layout and topographic information may be sufficient.	
	Polbeth	CDA		CDA-MO	301,680	663,788 No	Surface water / fluvial - part	None	Yes	SEPA have river gauging station on Breich Water adjacent to site.	None known	No developer requirements noted in proposed plan. We require a FRA to determine flood risk to site from Breich Water and West Calder Burn. We previously commented on LIVE/0349/FUL/11 and LIVE/0875/FUL/14 and had no objection as the sites did not encroach on the functional floodplain. This larger site includes area immediately adjacent to the watercourses. It is likely the majority of the site is developable and site layout and topographic information may be sufficient.	2
H-PH 1	Philpstoun	Housing	philpstoun bowling club	COU36	304,837	677,134 10/14	Νο	None	Νο	Report of surface water flooding at site in May 2004.	None known	Developer requirements mentions "Previous record of surface water flooding on site. Flood Risk Assessment required". Recommend flood resilient and resistant measures to address surface water flood risk.	
H-MC 1	Midcalder	Housing	new calder paper mill		306,386	667,258 10/27	Fluvial - small part	multiple watercourses through site	Yes	FRA previously carried out for site (URS, 2006 and Millard Consulting, 2012 &2014). Also FRA carried out by Rivers and Fisheries Trust for Howden Bridge Weir removal (Mott MacDonald, Aug 2014)	None known	Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the River Almond, small watercourses and lade structure. Site likely to be constrained due to flood risk. There are no water resilient measures required. Requirement to accommodate a buffer strip or 12m to 20m between development and the River Almond". We support requirement for FRA.	
H-LR 4	Longridge	Housing	longridge park	LON1	295,024	662,617 No	Νο	None	No	N/A	None known	Developer requirements mentions "The area is subject to run off from adjacent land. Flood Risk Assessment required". We have no further information on flood risk at this site.	Yes
H-LR 3	Longridge	Housing	land at back o moss and main st	E0I-0120	295,205	662,156 No	Νο	culverted through site	Yes	Report of surface water flooding adjacent to site in July 2004.	None known	Flood Risk Assessment required. Water impact assessment required. A small watercourse flows behind the existing developments on Northfield Meadows and may be culverted beneath Main Street and the development site. This should be investigated to determine if it is possible to open this watercourse (on the condition that it does not increase the risk of flooding to neighbouring areas). No development should occur on top of the culvert". We support the requirements and require FRA for small/culverted watercourse.	

										Report of surface water		Flood Risk Assessment required. Water impact assessment required. A small watercourse flows behind the existing developments on Northfield Meadows and may be culverted beneath Main Street and the development site. This should be investigated to determine if it is possible to open this watercourse (on the condition that it does not increase the risk of flooding to neighbouring areas). No development should occur on top of the	
H-LR	3 Longridge	Housing	land at back o moss and main st	EOI-0120	295,205	662,156 No	No	culverted through site	Yes	flooding adjacent to site in July 2004.	None known	culvert". We support the requirements and require FRA for small/culverted watercourse.	Yes
												Developer requirements mentions "The area is subject to run off from adjacent land. Flood Risk Assessment required". We have no	
H-LR	4 Longridge	Housing	longridge park	LON1	295,024	662,617 No	No	None multiple watercourses	No	N/A FRA previously carried out for site (URS, 2006 and Millard Consulting, 2012 &2014). Also FRA carried out by Rivers and Fisheries Trust for Howden Bridge Weir removal (Mott	None known	further information on flood risk at this site. Developer requirements mentions "Flood Risk Assessment required which assesses the flood risk from the River Almond, small watercourses and lade structure. Site likely to be constrained due to flood risk. There are no water resilient measures required. Requirement to accommodate a buffer strip of 12m to 20m between development and the River Almond". We support requirement for	
H-M	C1 Midcalder	Housing	new calder paper mill		306,386	667,258 10/27	Fluvial - small part	through site	Yes	MacDonald, Aug 2014)	None known	FRA.	Yes
H-PF	H 1 Philpstoun	Housing	philpstoun bowling club	COU36	304,837	677,134 10/14	No	None	No	Report of surface water flooding at site in May 2004.	None known	Developer requirements mentions "Previous record of surface water flooding on site. Flood Risk Assessment required". Recommend flood resilient and resistant measures to address surface water flood risk.	
	Polbeth	CDA		CDA-MO	301,680	663,788 No	Surface water / fluvial - part	None	Yes	SEPA have river gauging station on Breich Water adjacent to site.	None known	No developer requirements noted in proposed plan. We require a FRA to determine flood risk to site from Breich Water and West Calder Burn. We previously commented on LIVE/0349/FUL/11 and LIVE/0875/FUL/14 and had no objection as the sites did not encroach on the functional floodplain. This larger site includes area immediately adjacent to the watercourses. It is likely the majority of the site is developable and site layout and topographic information may be sufficient.	2
	Polbeth	CDA		CDA-CB	301,960	663,538 No	Fluvial - part	None	Yes	Report of surface water flooding adjacent to site in July 2007.	None known	No developer requirements noted in proposed plan. We require a FRA to determine flood risk to site from the West Calder Burn. It is likely the majority of the site is developable and site layout and topographic information may be sufficient.	
H-LV	V 1 Polbeth	Housing		15/41	302,024	664,305 No	Νο	going through site	Yes	N/A	None known	No developer requirements mentioned. We require a FRA for the small watercourse running through the site. It is likely the majority of the site is developable and site layout and topographic information may be sufficient.	No
												Developer requirements mentions "Previous	
H-PE	3 1 Polbeth	Housing	west calder high school	MIRQLATE2	303,706	664,226 No	No	None	No	N/A	None known	record of surface water flooding on site. Flood Risk Assessment required". We have no further information on flood risk.	Yes
H-PE	3 2 Polbeth	Housing		HWc10	302,510	664,255 No	Fluvial - adjacent to	adjacent to site	Yes	N/A	None known	Not mentioned in settlements in proposed plan. We require FRA to assess risk to site from West Calder Burn. Site layout and topographical information may be sufficient.	
								multiple watercourses				Developer requirements state "flood risk assessment and drainage impact assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is	
H-PL	J 1 Pumpherston	Housing	drumshoreland kirkforthar brickwo	rks	306,762	669,915 No	Surface water - part	through site	Yes	No	None known	made with the flood prevention officer. Developer requirements states that a drainage	yes
H-PL	J 2 Pumpherston	Housing	pumpherston golf course	COU28	306,895	669,095 No	No	None	No	No	None known	impact assessment	yes

Developer requirements mentions "There is a record of surface water flooding to north of the development site at Northfield Crescent. Flood Risk Assessment required. Water impact

No No No No

No No

No

No

No Yes No Yes

> No Yes No No No Yes

No No No No

1/1     1/2     1/2     1/2     1/2     1/2     2/2 <th>H-PU 3 H-SF 1</th> <th>Pumpherston Seafield</th> <th>Housing Housing</th> <th>uphall station road old rows</th> <th>HLv119 MIRQLATE3</th> <th>307,190 300,408</th> <th>669,561 666,129</th> <th></th> <th>Surface water – small part No</th> <th>None None</th> <th>Yes No</th> <th></th> <th>None known None known</th> <th>No developer requirements for flood risk. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. No</th> <th></th>	H-PU 3 H-SF 1	Pumpherston Seafield	Housing Housing	uphall station road old rows	HLv119 MIRQLATE3	307,190 300,408	669,561 666,129		Surface water – small part No	None None	Yes No		None known None known	No developer requirements for flood risk. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. No	
Inter-     Inter- <td>H-SB 1</td> <td>Stoneyburn</td> <td>Housing</td> <td>stoneyburn farm east</td> <td>HSb6</td> <td>298,238</td> <td>662,687</td> <td>No</td> <td>Surface water – small part</td> <td>a on boundary</td> <td>Yes</td> <td>No</td> <td>None known</td> <td>assessment and drainage impact assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Developer requirement states that a drainage impact assessment is required. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be</td> <td>yes</td>	H-SB 1	Stoneyburn	Housing	stoneyburn farm east	HSb6	298,238	662,687	No	Surface water – small part	a on boundary	Yes	No	None known	assessment and drainage impact assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Developer requirement states that a drainage impact assessment is required. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be	yes
H 13     Baraba	H-SB 2	Stoneyburn	Housing	stoneyburn farm west	HSb7	297,849	662,524	No	Surface water – small part	None	Yes	No	None known	that contact is made with the flood preventio	n yes
Kots     Langles     Langles <thlangles< th=""> <thlangles< th=""> <thlangles< th=""> <t< td=""><td>H-SB 3</td><td>Stoneyburn</td><td>Housing</td><td>stoneyburn workshons</td><td>HSb8</td><td>208 105</td><td>663 017</td><td>No</td><td>Νο</td><td>None</td><td>Νο</td><td>No</td><td>None known</td><td>Developer requirement states that a drainage impact assessment is required. Based upon the review of available information, we are have found no source of flood risk to this allocation. We recommend that contact is made with the flood prevention officer</td><td>yes</td></t<></thlangles<></thlangles<></thlangles<>	H-SB 3	Stoneyburn	Housing	stoneyburn workshons	HSb8	208 105	663 017	No	Νο	None	Νο	No	None known	Developer requirement states that a drainage impact assessment is required. Based upon the review of available information, we are have found no source of flood risk to this allocation. We recommend that contact is made with the flood prevention officer	yes
4.8.5BiocyamHauityHauitylice note dire $19.023$ $27.15$ $65.057$ No <th< td=""><td>11 50 5</td><td>Stoneyburn</td><td>nousing</td><td>stone yourn workshops</td><td>1550</td><td>250,155</td><td>003,017</td><td></td><td></td><td>none</td><td></td><td></td><td></td><td>Developer requirement states that a flood risk assessment is required. Based upon the review of available information, we are have found no source of flood risk to this allocation</td><td>¢</td></th<>	11 50 5	Stoneyburn	nousing	stone yourn workshops	1550	250,155	003,017			none				Developer requirement states that a flood risk assessment is required. Based upon the review of available information, we are have found no source of flood risk to this allocation	¢
-587 Somehar No.	H-SB 5	Stoneyburn	Housing	foulshields road site a	PJ-0002	298,159	663,067	No	No	None	No	No	None known	Developer requirement states that a flood risk assessment is required. Review of the available information suggest that the allocation is a sufficient distance away from the watercourse. We recommend that	yes
1-50 6     Someyharn     Housing     meadow road     Col-011     297,52     62,23 ho     Southow meter small port going through size     Yes     Somewharn i requires through size for a southow road is a physical for a southow road is a so	H-SB 7	Stoneyburn	Housing	foulshields road site b	EOI-0084	297,878	663,045	No	Surface water – part	on boundary	Yes	No	None known	•	yes
E-UH 2       Uphall       Employment       Land at uphall ind est north       EUB14       306,686       671,051 10/27       Surface water / fluvial - multiple watercourses       uphall multiple watercourses       uphall ind est north       EUB14       306,686       670,011 10/27       small part       multiple watercourses       uphall ind est north       EUB14       306,686       670,011 10/27       small part       multiple watercourses       uphall ind est north       EUB14       306,686       670,011 10/27       small part       multiple watercourses       uphall ind est north       EUB14       306,686       670,011 10/27       small part       multiple watercourses       uphall ind est north       EUB14       306,686       670,011 10/27       small part       not acceptable.       None known       September requirement states that a float supple requirement states float a float su					EOI-0119							planning application in principle and offered no objection but highlighted the requirement of consideration of small watercourse		available information suggest that the allocation is a sufficient distance away from the watercourse. We recommend that contact is made with the flood prevention	Yes
E-UH 2       Uphall       Employment       Land at uphall ind est north       EUB 4       306,686       671,054       10/27       Surface water / fluvial - small part       multiple watercourses       information during early consultations of the plan into early consultations of the plan interver early consultatint early consultatin	E-UH 1	Uphall	Employment	stankards south		306,548	671,273	10/27	No	None	No	No	None known		Yes
E-UH 3 Uphall Employment I and at uphall indicest south E0I-0216 306,606 670,814 10/27 Surface water – small part on boundary Yes No Power it is likely this map is sim picking up the low lying small watercourd channel for Bury Surface water – small part on boundary Yes No None known Channel Developer requirement states "There is a six channel to surface water – small part on boundary Yes No None known Channel Surface water – small part on boundary Yes No None known Channel There is a six channel to surface water – small part on boundary Yes No None known Channel There is a six channel to surface water – small part on boundary Yes No None known Channel There is a six channel to surface water – small part on boundary Yes No None known Channel There is a six channel to surface water – small part on boundary Yes No None known Channel There is a six channel to surface water – small part on boundary Yes No None known Channel There is a six channel to surface water – small part on boundary Yes No None known Channel There is a six channel to surface water – small part on boundary Yes No None known Channel There is a six channel to surface water / surface water / surface water / fluvial -	E-UH 2	Uphall	Employment	land at uphall ind est north	EUB14	306.686	671.054	10/27		•	Yes	consultations of the plan WLC highlighted that the culvert on Beugh Burn is	None known	assessment is required. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is	2
Significant flooding on the Brox Burn in August 2008. A property on Badgers Park locate to the south of the site was Surface water / fluvial -														Developer requirement states that a flood risk assessment is required. There is a risk of surface water flooding shown on our flood maps however it is likely this map is simply picking up the low lying small watercourses	< C
Significant flooding on the Brox Burn in August 2008. A property on Badgers Park located to supjacted to significantSignificant flooding from out of bank flows in the watercourse. Flood Risk Assessment require assesses the flood risk form the Brox Burn. need to take into comment flowial -Surface water / fluvial -Surface water / fluvial -Badgers Park located to subjected to significantBroxburn FPS (2007) whether this is part of water out flow of the site was whether this is part of whether this is part of	E-UH 3	Uphall	Employment	land at uphall ind est south	EOI-0216	306,606	670,814	10/27	Surface water – small part	on boundary	Yes	No	None known		Yes
H-BU 6 Broxburn Housing Holmes North site A HUB20 307,155 671,838 10/27 part None Yes flooding.	H-BU 6	Broxburn	Housing	Holmes North site A	HUB20	307,155	671,838	10/27		None	Yes	the Brox Burn in August 2008. A property on Badgers Park located to the south of the site was subjected to significant	unable to comment whether this is part of	risk of flooding from out of bank flows in the watercourse. Flood Risk Assessment required whic assesses the flood risk from the Brox Burn". Site w need to take into consideration the Broxburn FPS and current SEPA guidance on development behin flood defences. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made	h III D

H-PU 3	Pumpherston	Housing	uphall station road	HLv119	307,190	669,561 No	Surface water – small pa	t None	Yes	Νο	None known	No developer requirements for flood risk. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
H-SF 1	Seafield	Housing	old rows	MIRQLATE3	300,408	666,129 No	No	None	No	No	None known	No	yes
												Developer requirements state "flood risk assessment and drainage impact assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is	
H-SB 1	Stoneyburn	Housing	stoneyburn farm east	HSb6	298,238	662,687 No	Surface water – small par	t on boundary	Yes	No	None known	made with the flood prevention officer.	yes
												Developer requirement states that a drainage impact assessment is required. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention	
H-SB 2	Stoneyburn	Housing	stoneyburn farm west	HSb7	297,849	662,524 No	Surface water – small par	t None	Yes	No	None known	officer.	yes
H-SB 3	Stoneyburn	Housing	stoneyburn workshops	HSb8	298,195	663,017 No	No	None	Νο	Νο	None known	Developer requirement states that a drainage impact assessment is required. Based upon the review of available information, we are have found no source of flood risk to this allocation. We recommend that contact is made with the flood prevention officer.	yes
												Developer requirement states that a flood risk assessment is required. Based upon the review of available information, we are have found no source of flood risk to this allocation We recommend that contact is made with the	۱.
H-SB 5	Stoneyburn	Housing	foulshields road site a	PJ-0002	298,159	663,067 No	No	None	No	No	None known	flood prevention officer. Developer requirement states that a flood risk assessment is required. Review of the available information suggest that the allocation is a sufficient distance away from the watercourse. We recommend that contact is made with the flood prevention	yes k
H-SB 7	Stoneyburn	Housing	foulshields road site b	EOI-0084	297,878	663,045 No	Surface water – part	on boundary	Yes	No	None known	officer.	yes
H-SB 6	Stoneyburn	Housing	meadow road	EOI-0119	297,592	662,293 No	Surface water – small par	t going through site	Yes	Commented on a planning application in principle and offered no objection but highlighted the requirement of consideration of small watercourse	None known	Developer requirement states that a flood risk assessment is required. The site does lie adjacent to indicative flood outline however there is a 5m height difference and as a result there is no risk of flooding from the Breich Water that lies within 40m of the boundary of the site to the south. There is a risk of surface water flooding shown on our flood maps however it is likely this map is simply picking up the low lying small watercourses channel Developer requirement states that a flood risk assessment is required. Review of the available information suggest that the allocation is a sufficient distance away from the watercourse. We recommend that	f Yes
E-UH 1	Uphall	Employment	stankards south		306,548	671,273 10/27	No	None	No	No	None known	contact is made with the flood prevention officer.	Yes
						· · ·	Surface water / fluvial –	multiple watercourses		Information during early consultations of the plan WLC highlighted that the culvert on Beugh Burn is		Developer requirement states that a flood risk assessment is required. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is	k e
E-UH 2	Uphall	Employment	land at uphall ind est north	EUB14	306,686	671,054 10/27	small part	through site	Yes	not acceptable.	None known	<ul> <li>made with the flood prevention officer.</li> <li>Developer requirement states that a flood risk assessment is required. There is a risk of surface water flooding shown on our flood maps however it is likely this map is simply picking up the low lying small watercourses</li> </ul>	Yes
E-UH 3	Uphall	Employment	land at uphall ind est south	EOI-0216	306,606	670,814 10/27	Surface water – small par	t on boundary	Yes	No	None known	channel	Yes
H-BU 6	Broxburn	Housing	Holmes North site A	HUB20	307,155	671,838 10/27	Surface water / fluvial - part	None	Yes	Significant flooding on the Brox Burn in August 2008. A property on Badgers Park located to the south of the site was subjected to significant flooding.		Developer requirement states "There is a significant risk of flooding from out of bank flows in the watercourse. Flood Risk Assessment required whic assesses the flood risk from the Brox Burn". Site w need to take into consideration the Broxburn FPS and current SEPA guidance on development behin flood defences. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	:h iill id 0

No No	No No
No	No
No	No
No	No

E-LW	N 3	West Calder	Employment		EWc1 & EOI- 0164	301,286 664	,569 No	Surface water – small pa	rt on boundary	Yes	Νο	None known	No developer requirements assigned with this allocation. A flood risk assessment is required as outlined within our responses on previous allocationsEWc1 & EOI-0164. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
E-LW	N 4	West Calder	Employment		EWc4 & EOI- 0164	300,944 664	,378 No	Surface water – small pa	rt on boundary	Yes	Νο	None known	No developer requirements assigned with this allocation. A flood risk assessment is required as outlined within our responses on previous allocationsEWc4 & EOI-0164. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
								Surface water / fluvial -	-				Developer requirements state "flood risk assessment and drainage impact assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is	
H-W	/C 1	West Calder	Housing	Cleugh Brae CDA		301,960 663	,541 No	part	None	Yes	No Commented on an application 0349/FUL/11 which incorporated part of the site and offered no objection as the development was a sufficient distance and	None known	Developer requirements state "flood risk assessment and drainage impact assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated	Yes
H-W	/C 2	West Calder	Housing	Mossend phase 1 site a CDA		301,613 663	,852 No	Surface water / fluvial – small part	None	Yes	height above the watercourse	None known	further and it is recommended that contact is made with the flood prevention officer. Developer requirements state that a flood risk assessment and drainage impact assessment is	
													required. However for this allocation	
H-W	/C 3	West Calder	Housing	Mossend phase 1 site b cda		301,583 663	,586 No	No	None	Νο	Νο	None known	<b>-</b> .	Yes
H-W H-W		West Calder West Calder		Mossend phase 1 site b cda mossend remainder CDA		301,583 663 301,464 663		No Surface water – small pa		No	No	None known	required. However for this allocation shapefile we have not identified any risk of flooding. Allocation H-WC4 developer requirements covers 3 GIS shapefiles and in turn states that a flood risk assessment and drainage impact assessment is required. However for this allocation shapefile we have not identified any risk of flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the	Yes
H-W	/C 4	West Calder	Housing			301,464 663	,662 No	Surface water – small pa	rt None	No	No		<ul> <li>required. However for this allocation shapefile we have not identified any risk of flooding.</li> <li>Allocation H-WC4 developer requirements covers 3 GIS shapefiles and in turn states that a flood risk assessment and drainage impact assessment is required. However for this allocation shapefile we have not identified any risk of flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.</li> <li>Allocation H-WC4 developer requirements covers 3 GIS shapefiles and in turn states that a flood risk assessment and drainage impact assessment is required. However for this allocation shapefile we have not identified any is required. However for this allocation shapefile we have not identified any have not identified any flood risk assessment and drainage impact assessment is required. However for this allocation shapefile we have not identified any have not iden</li></ul>	Yes
	/C 4 /C 4	West Calder		mossend remainder CDA		301,464 663 301,692 663						None known	<ul> <li>required. However for this allocation shapefile we have not identified any risk of flooding.</li> <li>Allocation H-WC4 developer requirements covers 3 GIS shapefiles and in turn states that a flood risk assessment and drainage impact assessment is required. However for this allocation shapefile we have not identified any risk of flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.</li> <li>Allocation H-WC4 developer requirements covers 3 GIS shapefiles and in turn states that a flood risk assessment and drainage impact assessment is required. However for this allocation shapefile we have not identified any risk of flooding.</li> <li>Developer requirements state "flood risk assessment and drainage impact assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is required that contact is made with required flooding.</li> </ul>	Yes
H-W	/C 4 /C 4	West Calder West Calder	Housing	mossend remainder CDA	<pre>y EOI-0031</pre>	301,464 663 301,692 663 301,891 663	,662 No ,597 No	Surface water – small pa	rt None	No	No	None known None known	<ul> <li>required. However for this allocation shapefile we have not identified any risk of flooding.</li> <li>Allocation H-WC4 developer requirements covers 3 GIS shapefiles and in turn states that a flood risk assessment and drainage impact assessment is required. However for this allocation shapefile we have not identified any risk of flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.</li> <li>Allocation H-WC4 developer requirements covers 3 GIS shapefiles and in turn states that a flood risk assessment and drainage impact assessment is required. However for this allocation shapefile we have not identified any risk of flooding.</li> <li>Developer requirements state "flood risk assessment and drainage impact assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.</li> <li>Developer requirements state "flood risk assessment and drainage impact assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.</li> <li>Developer requirements state "flood risk assessment and drainage impact assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is</li> </ul>	Yes

E-LW 3	West Calder	Employment		EWc1 & EOI- 0164	301,286 6	64,569 No	Surface water – small par	t on boundary	Yes	Νο	None known	No developer requirements assigned with this allocation. A flood risk assessment is required as outlined within our responses on previous allocationsEWc1 & EOI-0164. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
E-LW 4	West Calder	Employment		EWc4 & EOI- 0164	300,944 6	64,378 No	Surface water – small par	t on boundary	Yes	Νο	None known	No developer requirements assigned with this allocation. A flood risk assessment is required as outlined within our responses on previous allocationsEWc4 & EOI-0164. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	
H-WC 1	West Calder	Housing	Cleugh Brae CDA		301,960 6	63,541 No	Surface water / fluvial - part	None	Yes	Νο	None known	Developer requirements state "flood risk assessment and drainage impact assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes
					201 642	62.052 No	Surface water / fluvial –	Need		Commented on an application 0349/FUL/11 which incorporated part of the site and offered no objection as the development was a sufficient distance and height above the	)	Developer requirements state "flood risk assessment and drainage impact assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is	
H-WC 2	West Calder	Housing	Mossend phase 1 site a CDA			63,852 No	small part	None	Yes	watercourse	None known	Developer requirements state that a flood risk assessment and drainage impact assessment is required. However for this allocation shapefile we have not identified any risk of	5
H-WC 3 H-WC 4	West Calder	Housing	Mossend phase 1 site b cda mossend remainder CDA		301,583 6 301,464 6	63,586 No 63,662 No	No Surface water – small par	None	No	No	None known	flooding. Allocation H-WC4 developer requirements covers 3 GIS shapefiles and in turn states that a flood risk assessment and drainage impact assessment is required. However for this allocation shapefile we have not identified any risk of flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	-
H-WC 4	West Calder	Housing	mossend remainder CDA		301,692 6	63,597 No	Νο	None	No	Νο	None known	Allocation H-WC4 developer requirements covers 3 GIS shapefiles and in turn states that a flood risk assessment and drainage impact assessment is required. However for this allocation shapefile we have not identified any risk of flooding.	/ Yes
H-WC 4	West Calder	Housing	mossend remainder CDA		301,891 6	63,807 No	Surface water / fluvial – small part	None	Yes	Νο	None known	Developer requirements state "flood risk assessment and drainage impact assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes
H-WC 5		Housing	Burngrange west of calder cemetery	501 0021	200.050	62,541 No	Quefess under seri	an boundar.		No	None known	Developer requirements state "flood risk assessment and drainage impact assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is	Yes
	West Calder	nousing	buildinge west of culder certain is	Y E01-0031	300,869 6	02,541 NO	Surface water – part	on boundary	Yes	No		made with the flood prevention officer.	res

# No Yes

No Yes

No No No No

No No No No

> No No

No

No

No No

H-WF 1	Westfield	Housing	north logie brae		294 107	671,986 10/13	Surface water / fluvial -	going through site	Vec	Surface water flooding to nearby property in 2003 and 2005. No further details provided and contact with FPO is recommended. We have recently commented on a FRA in support of 0191/FUL/15 which is located adjacent to the site and have an outstanding objection due to the inadequacy of the report		Developer requirements state "flood risk assessment and drainage impact assessment required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer	Vec
H-WF 1	Westfield	Housing	north logie brae		294,107	671,986 10/13	part Surface water – adjacent	going through site	Yes	the report.	None known	made with the flood prevention officer. Developer requirements state "flood risk assessment and drainage impact assessment required". We have no further information on flood risk and cant identify any fluvial flood risk at this site as was the case in our comments on this allocation EWb3 in Feb 2012.Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the	Yes
E-LW 2 E-LW 5	Whitburn	Employment		EWb3		666,162 No 665,736 No	Surface water /fluvial - majority	None multiple watercourses through site	No	Provided comments on the proposed yard at	None known		Yes
E-WH 1	Whitburn	Employment		EWb4		665,185 No	Surface water / fluvial -	multiple watercourses through site		We provided comments on an application, 0493/P/02, for the erection of an office and	None known	This allocation is not within the proposed plan supporting document dated October 2015. Flood risk is extremely complex in this area and a detailed assessment would be required	
H-WH 1	Whitburn	Housing	polkemmet heartlands 1	E W 04		664,475 No	part	None	Yes		None known	No developer requirements assigned to this allocation. No flood risk identified	
H-WH 3	Whitburn	Housing	polkemmet remainders	HWb4	293,501		Surface water / fluvial – small part	multiple watercourses through site	Yes		None known	No developer requirements assigned to this allocation for flood risk. Flood risk assessment is required to assess the risk from the numerous small watercourses flowing through the development site. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention	
H-WH 4	Whitburn	Housing	whitdale east main st	HWb11	295,245	665,003 No	Surface water – small part	None	Νο	Νο	None known	No developer requirements assigned to this allocation for flood risk. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Within our comments in Feb 2012 we agreed with WLC that a DIA was required however this hasn't been request and the council should consider altering the plan to reflect this.	
H-WH 5	Whitburn	Housing	dixon terrace	EOI-0019	294,187	664,270 No	Surface water – small part	going through site	Yes	SEPA commented on a planning application 0295/P/13 which was supported by a FRA and offered no objection subject to a condition	None known	Developer requirements state that a flood risk assessment is required. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes
		-					·			-		·	

No No

No No

No No

No Yes No No No Yes

No No

No No

H-WH 6	Whitburn	Housing	polkemmet business centre	E0I-0108	293,513 66		Surface water – adjacent	on boundary	Yes	Νο	None known	Developer requirements state that a flood risk assessment is required. watercourse along southern boundary which derives from the Colliery Ponds has to be assessed. Watercourse is also culverted adjacent to the site and may be culverted beneath the development site. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	Yes
		-										Developer requirements states that there is a history of flooding at and within the site. We hold no records of this flooding. It also states that the Gogar Burn flows along the southern boundary which is not the case. The sole issue we have identified is that there is a possibility of a culverted watercourse flowing through the site as outlined within our comments on allocation	
H-WH 7 H-WH 2	Whitburn Whitburn	Housing Housing	murraysgate west mains st polkemmet heartlands area a b c		-			going through site None	Yes No	No No	None known None known		Yes Yes
		ŭ		HWk1 & EOI-			Surface water – small					Developer requirement states that a flood risk assessment is required. Within our previous comments (EO1-0076) we did not ask for a FRA and hold no information to suggest the site is at risk of fluvial flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention	
H-WI 1	Wilkieston	Housing	linburn		312,150 66			None	Yes	No	None known		Yes
												Developer requirement states that a flood risk assessment is required. This is presumably based upon our previous comments on EO1- 0170 which was a much larger allocation with the watercourse running along the boundary of the allocation. The new allocation is significantly smaller and away from the watercourse and a FRA is not required. Please note that the code within the proposed plan is different to the GIS information with the proposed plan code as H-WH2 (which is also	
H-WI 2	Wilkieston	Housing	east coxydene farm	EOI-0170	312,024 66	68,554 10/27	No	None	No	No	None known	This CDA allocation has been commented on within allocations H-WB 07 to 10. No	Yes
	Winchburgh	CDA		CDA-GS	307,765 67		Surface water / fluvial – small part	None	Yes	No	None known	developer requirements assigned to this allocation	
							Surface water / fluvial -					No developer requirements assigned to this allocation. We would recommend a flood risk assessment is carried out. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. The site lies adjacent to the Union Canal and contact should be made with Scottish Canal to ensure there is no residual	
	Winchburgh	CDA		CDA-GN	308,192 67			None	Yes	No	None known	risk of flooding Part of the CDA allocation has been commented on within allocations H-WB13. No developer requirements assigned to this	
	Winchburgh	CDA		CDA-NS	309,910 67	74,985 10/27	Surface water – part	going through site	Yes	No	None known	allocation and we would recommend a flood risk assessment	
												No developer requirements assigned to this allocation. We would recommend a flood risk assessment is carried out. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. We have commented on this CDA on	
	Winchburgh	CDA		CDA-MS	309,002 67	75,577 10/27	Surface water – part	going through site	Yes	No	None known	allocations H WB 05 and H WB 06. No developer requirements assigned to this allocation. We would recommend a flood risk	
	Winchburgh	CDA		CDA-NN	309,550 67	75,463 10/27	Fluvial/Coastal - part	None	Yes	No	None known	assessment is carried out.	

No No

No No No No

No

No

No

No

No Yes

No Yes No Yes

No Yes No Yes

	Winchburgh CDA		CDA-CP	308,828	675,323 10/27	Surface water / fluvial - part	going through site	yes	Νο	None known	No developer requirement and we comment on this CDA on allocation H WB 4. A pond is located within the site and it is possible that the outflow from this watercourse is culverted beneath the site. The surface water and fluvial flood map are solely identifying the pond. An FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding.	
E-WB 1	Winchburgh Employm	ent myreside east	CDA-ME	309,363	675,877 10/27	Surface water /fluvial - majority	None	Yes	Νο	None known	The developer requirements state that a flood risk assessment and drainage impact assessment is required. We would highlight that the site will be significantly constrained due to flood risk. An FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer.	95
											The developer requirements state that a flood risk assessment and drainage impact assessment are possibly required. As a result we have stated that the developer requirements are insufficient as a FRA is required. There is a small watercourse which flows along the northern boundary of the site. he FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate	
E-WB 2 H-WB 1	Winchburgh Employm Winchburgh Housing	ent myreside west castle road	CDA-MW HWh3		676,169 10/27 675,008 10/27	Fluvial - small part No	on boundary None	Yes No	No No	None known None known	flooding. No No Yes	
H-WB 2	Winchburgh Housing	dunn place	HWh5	308,422	674,860 No	No	None	No	No	None known	Record of flooding in nearby area in 2008 and 2009. No further information provided by the council. Recommend contact is made with the WLC Flood Protection Officer.	S
H-WB 3	Winchburgh Housing	niddry mains north CDA		309,550	675,464 10/27	Fluvial - small part	None	Yes	No	None known	Developer requirement states that a "flood risk assessment and drainage impact assessment is required". The FRA should consider any structures, e.g. culverts/ bridges, which may exacerbate flooding. Yes	
						Surface water / fluvial -					Developer requirement states that a "flood risk assessment and drainage impact assessment is required". Consideration should be given to the flood risk from the Union Canal and flood mitigation measures and early engagement with Scottish Canals is recommended. A pond is located within the site and it is possible that the outflow from this watercourse is culverted beneath the site. The surface water and fluvial flood map are solely identifying the pond. The FRA should consider any structures, e.g. culverts/ bridges,	
H-WB 4	Winchburgh Housing	claypit CDA		308,828	675,323 10/27	part	going through site	yes	No	None known	which may exacerbate flooding. Yes Developer requirement states that a "flood risk assessment and drainage impact assessment is required. Development will	>
H-WB 5	Winchburgh Housing	myreside block AA CDA		309,111	675,315 10/27	Surface water / fluvial – adjacent to	going through site	yes	No	None known	likely be heavily constrained due to flood risk". A pond is located to the east of the site and it is possible that the outflow from this watercourse is culverted beneath the site. Yes	S
						Surface water / fluvial -					Developer requirement states that a "flood risk assessment and drainage impact assessment is required. Development will likely be heavily constrained due to flood risk". The FRA should take account the bridges and culverts on the site and also the small watercourse flowing through the southern part of the allocation. Consideration should be given to the flood risk from the Union Canal and flood mitigation measures and early engagement with Scottish Canals is recommended. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention officer. Site may be constrained due to flood risk hence	
H-WB 6	Winchburgh Housing	myreside remainder CDA		308,947	675,710 10/27	part	going through site	yes	No	None known	capacity of 267 may not be achievable. Yes	5

No Yes

No No No Yes No No

No No No No

No No

No No

No No

Н	I-WB 7	Winchburgh	Housing	glendevon south block k site a CDA	308,047 675,083 10/27	No	None	No	No	None known	The proposed plan highlights that the development is likely to be heavily constrained due to flood risk, however we feel that the vast majority of the site is developable. The comments previously provided were for a larger site allocation (CDA GS). For the latest allocation we would advise that we have no further information on flood risk and do not require an FRA to be attached as a developer requirement. The proposed plan highlights that the development is likely to be heavily constrained due to flood risk, however we feel that the vast majority of the site is developable. The comments previously provided were for a larger site allocation (CDA GS). For the latest allocation we would advise that we have no further information on flood risk and do not require an FRA to be attached	Yes
н	I-WB 8	Winchburgh	Housing	glendevon south block k site b CDA	307,901 675,091 10/27	No	None	No	No	None known	as a developer requirement	Yes
	I-WB 9		Housing	glendevon south CDA	307,839 674,943 No	Surface water / fluvial – adjacent to	on boundary	Yes	Νο	None known	Developer requirements state "flood risk assessment and drainage impact assessment required". This should take account the various culverts/bridges over the small watercourses and also information regarding the workings and flood risk from the pond. The proposed plan highlights that the development is likely to be heavily constrained due to flood risk, however we feel that the vast majority of the site is developable. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the	Yes
						Qurfees under sevel as					Developer requirements state "flood risk assessment and drainage impact assessment required". This should take account the various culverts/bridges over the small watercourses and also information regarding the workings and flood risk from the pond. The proposed plan highlights that the development is likely to be heavily constrained due to flood risk, however we feel that the vast majority of the site is developable. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the	
Н	I-WB 10	Winchburgh	Housing	glendevon south remainder CDA	307,749 674,719 No	Surface water – small pa	rt going through site	Yes	Νο	None known	flood prevention officer. Developer requirements state "flood risk assessment and drainage impact assessment	Yes
ц	I-WB 11	Winchburgh	Housing	glendevon north block m CDA	308,127 675,276 10/27	No	None	No	No	None known	required". We have no further information on	Yes
	I-WB 12		Housing	glendevon north remainder CDA	308,075 675,601 10/27	Surface water / fluvial – small part	None	Yes	Νο	None known	Developer requirements state that a flood risk assessment and drainage impact assessment is required. Consideration should be given to the flood risk from the Union Canal and flood mitigation measures and early engagement with Scottish Canals is recommended. Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This should be investigated further and it is recommended that contact is made with the flood prevention	Yes
											Developer requirements state "flood risk assessment and drainage impact assessment required". The small watercourse is culverted at the south eastern corner of the site and	
	I-WB 13	-	Housing	Niddry Mains south CDA	309,740 675,065 10/27	Surface water – small pa	•	Yes	No	None known	should be assessed	Yes
Н	I-WB 14	Winchburgh	Housing	Main Street former beattie school WIN1	309,197 675,071 10/27	No	None	No	No	None known	No	Yes

No No

No No

No No

No No No

No No No No No No

No

H-WB 15	Winchburgh	Housing	glendevon regeneration site	COU6	308,261	674,735 No	Surface water / fluvial – small part	on boundary	Yes	A blocked culvert floode a footpath along Glendevon Park in November 2009. Surface water flooding to nearby property in 2007. No further details provided and contact with FPO is recommended.	2	Developer requirements state "Flood Risk Assessment required which assesses the floor risk from the small watercourse which flows along the southern boundary of the site" Review of the surface water 1 in 200 year flood map shows that there may be flooding issues within/ adjacent to the site. This shoul be investigated further and it is recommende that contact is made with the flood prevention officer.	ld :d
												Developer requirement state "flood risk	
												assessment is required. There appears to be	а
												small watercourse that flows through the site	
												which is culverted. SEPA recommend that the	2
												culvert is opened up if possible on the	
												condition that there was no increase in flood	
												risk locally. Another watercourse flows along	
												southern boundary of the development site.	
												There is complex hydrology in this area.	
												Review of the surface water 1 in 200 year	
												flood map shows that there may be flooding issues within/ adjacent to the site. This should be added a straight to the site.	
												be investigated further and it is recommende	
												that contact is made with the flood preventio	
H-WB 16	Winchburgh	Housing	west of ross's plantation	EOI-0198	310,258	674,822 10/27	Surface water – part	going through site	Yes	No	None known	officer.	Yes
	0	U	·		,		·	0 0 0					
												Developer requirements state "parts of the	
												site is at medium to high risk from fluvial	
												flooding. Flood risk assessment required.	
												There are large number of crossings over the	
												Niddry Burn which flows along the southern	
												boundary presumably in association with the	
												golf course. All structures will have to be	
												incorporated within the hydraulic model.	
												Review of the surface water 1 in 200 year flood map shows that there may be flooding	
												issues within/ adjacent to the site. This should	
												be investigated further and it is recommende	
							Surface water / fluvial –					that contact is made with the flood preventio	
H-WB 17	Winchburgh	Housing	site west of niddry castle	EOI-0201	309,375	674,574 No	small part	None	Yes	No	None known	officer.	Yes
	5	Ŭ				-	-					Developer requirements state "flood risk	
												assessment and drainage impact assessment	
												required". We have no further information of	on
H-WB 18	Winchburgh	Housing	site adjoining niddry mains house	MIRQ0159	309,305	675,318 10/27	No	None	No	No	None known	flood risk	Yes

No	No	

No

No

No	No
No	No

Name: Scottish Environment Protection Agency								
Address: Strathallan House, The Castle Business Park, Stirling, FK9 4TZ								
Daytime telephone:								
Email:								

# Section of Plan

Policy DES 1 Design Principles

#### Nature of Representation

Seeking a change to the document	
Supporting the content of the document, or a particular section of the	Х
document	

We **support** the overarching aim of this policy and the clear reference to the requirement for development proposals to enhance the environment of West Lothian. Furthermore, we **support** the requirements within bullet points (f) and (g) whereby the water environment and air quality, soil and water quality are specifically highlighted.

Please also see our comments in respect of polices EMG 1 and EMG 4.

Signature:

Name: Scottish Environment Protection Agency								
Address: Strathallan House, The Castle Business Park, Stirling, FK9 4TZ								
Daytime telephone:								
Email:								

# Section of Plan

Policy EMG 1 Water Environment Improvement

#### Nature of Representation

Seeking a change to the document	Х
Supporting the content of the document, or a particular section of the	Х
document	

We **support** the inclusion of this policy which will assist the Council in meeting its legal responsibilities under the Water Framework Directive and will ensure that the LDP helps to protect, improve and promote the sustainable use of our water environment which includes wetlands, rivers, lochs, transitional waters, coastal waters and groundwaters.


Development plans need to be guided by the catchment approach underpinning the RBMP 2015-2021 by adopting an integrated, holistic and sustainable approach to water issues in terms of finding room for water alongside seeking to protect and improve water quantity and quality.

As a fully integrated element within the plan, water management should drive the vision, the spatial strategy and inform site specific layouts, ensuring that the siting and design of development is informed by natural flow paths of water through the site.

We have one requirement to make regarding this policy. The policy states: "Proposals that are aligned with measures identified in the River Basin Management Plan will be supported in principle, including the retrofitting of SuDS features to the existing surface drainage system, the restoration of watercourses and the removal of redundant structures." We **require** the inclusion of a caveat such as "provided these activities are informed by an FRA".

Please also see our comments in respect of Policy ENV 11 Protection of the Water Environment and Policy EMG 3 Sustainable Drainage.

Signature:



Policy EMG 2 Flooding

# Nature of Representation

Seeking a change to the document	Х
Supporting the content of the document, or a particular section of the	Х
document	

The Scottish Government's 'Delivering Sustainable Flood Risk Management' (Scottish Government, June 2011) document sets the framework for flood management in Scotland. The main principles of flood management are identified as avoid, protect, prepare and accept. It identifies the land use planning system as one of the most powerful tools available to manage flood risk sustainability (page 21). This concept is supported by the National Planning Framework and Scottish Planning Policy, which promote a precautionary approach to flood risk management through avoidance, reduction and sustainable drainage. The principle of flood avoidance is the cornerstone of sustainable flood risk management.

Whilst we **support** the inclusion of this policy and welcome the changes to it which have been incorporated following our discussions earlier this year, we have further comment to make in relation to the wording.

We **support** the clear policy statement that the Council will, as a first principle, seek to prevent development which would have a significant probability of being affected by flooding or would increase the probability of giving rise to flooding elsewhere. We also welcome the inclusion of the precautionary approach to flood risk from all sources taking into account the predicted impact of climate change.

We **support** the wording which ensures that development will be avoided in locations at medium to high flood risk (unless in accordance with the Risk Framework in Scottish Planning Policy) or where it would lead to an increase in the probability of flooding elsewhere.

Furthermore, we **support** the policy framework which requires developers to submit a flood risk assessment for all developments deemed to be at risk of flooding from any source in medium to high risk areas and developments in low to medium risk areas identified in the Risk Framework. We also welcome the reference to flood risk assessments being prepared in accordance with the prevailing SEPA technical guidance.

The policy states that "To limit the impact of potential flood risk any development that is

subsequently permitted in medium to high risk areas (that accords with the exceptions in the risk framework) or is located in adjacent low to medium risk areas must be built to a water resilient design". We **require** the inclusion of additional wording "*and not increase flood risk elsewhere*" at the end of this sentence.

With regard to flood protection schemes, whilst we **support** the requirement that development proposed in areas that is, or will be behind a formal flood protection scheme must be an appropriate and acceptable land use for the location, designed to be resilient and must not be constructed until the flood protection scheme is operational, we **require** that the wording be amended to read: "formal flood protection scheme *that is designed to an appropriate standard and is an acceptable land use for the location..."* 

Finally, the policy states that "Alterations and small-scale extensions to existing buildings are outwith the scope of this policy, provided that they would not have a significant effect on the storage capacity of the functional floodplain or local flooding problems." We **require** the inclusion of the additional wording "*and not increase the number of persons at risk*" at the end of that sentence as extensions that increase the number of bedrooms, for example, are unlikely to be supported by SEPA.

The advice contained in this letter is supplied to you by SEPA in terms of Section 72 (1) of the Flood Risk Management (Scotland) Act 2009 on the basis of information held by SEPA as at the date hereof. It is intended as advice solely to West Lothian Council as Planning Authority in terms of the said Section 72 (1). Our briefing note entitled: *"Flood Risk Management (Scotland) Act 2009: Flood risk advice to planning authorities"* outlines the transitional changes to the basis of our advice in line with the phases of this legislation and can be downloaded from <a href="http://www.sepa.org.uk/environment/land/planning/guidance-and-advice-notes/">http://www.sepa.org.uk/environment/land/planning/guidance-and-advice-notes/</a>.

Signature:

Name: Scottish Environment Protection Agency
Address: Strathallan House, The Castle Business Park, Stirling, FK9 4TZ
Daytime telephone:
Email:

# Section of Plan

Policy EMG 3 Sustainable Drainage

#### Nature of Representation

Seeking a change to the document	
Supporting the content of the document, or a particular section of the	Х
document	


We **support** the inclusion of this policy which will assist the council in meeting their legal responsibilities under the Water Framework Directive and ensure that the LDP helps to protect, improve and promote sustainable use of our water environment.

We specifically **support** the following elements of the policy:

- A clear statement that SUDS will be required for all developments except single houses)
- The importance of developers considering the space requirements for SUDS.
- The requirement to connect to the public sewer network where possible.
- The retrofitting of SUDS where possible.
- The requirement to invest in off-site works to provide additional capacity or reduced loading on combined sewers.
- Private drainage systems only being permitted where there is no public drainage system or as temporary measures where there is no capacity in the existing public sewer.
- The cross reference to other LDP policies including flood risk and the requirement to contribute to the delivery of green infrastructure and the Green Network where appropriate.

Please also see our comments in respect of policy ENV 8 Green Network.

Signature:



# Section of Plan

Policy EMG 4 Air Quality

# Nature of Representation


Seeking a change to the document	
Supporting the content of the document, or a particular section of the	Х
document	

Local development plans have an important role to play in protecting and improving air quality in Scotland - they provide an important opportunity to address this issue through supporting sustainable transport infrastructure, the location of new development, promoting sustainable places and green infrastructure

We **support** the inclusion of this policy which states that development will not be supported where it is not possible to mitigate against the adverse effects of development on air quality effectively. We also note and support that development proposals which cause unacceptable air quality or dust impacts, or would result in sensitive uses being located within or close to uses with the potential to generate such pollution will not be supported.

We **support** the recognition within this policy of the air quality issues within Linlithgow and Broxburn/Uphall and the promotion of behavioural changes to facilitate a shift to shorter journeys and walking/cycling.

Signature:



# Section of Plan

ENV 6 Peatland and Carbon Rich Soils

# Nature of Representation


Seeking a change to the document	
Supporting the content of the document, or a particular section of the	Х
document	

Soil is a key part of our environment and soil degradation can have major implications for air and water quality as well as our climate, biodiversity and economy. Sustainable management and protection of soils is key to ensuring that soils can deliver essential functions vital for the sustainability of Scotland's environment and economy.

The management and protection of carbon-rich soils is seen as a key element of Scotland's climate change mitigation strategy because of the potential of soil to store carbon and exchange greenhouse gases ( $CO_2$ ,  $CH_4$  and  $N_2O$ ) with the atmosphere. Scottish soils hold around 3 billion tonnes of carbon mostly in peatlands which is the majority of the UK's land based carbon. Disruption of areas of carbon rich soil by development or cultivation can result in the loss of the stored carbon through release of greenhouse gases to the atmosphere. This is contrary to the target of reducing the emission of greenhouse gases set out in Part 1 of the Climate Change (Scotland) Act 2009 (CC Act) and efforts to mitigate climate change by reducing greenhouse gas emissions at source.

This policy will assist in achieving these aims and we therefore **support** the inclusion of Policy ENV 6. Please also see our comments in respect of Policy MRW 3 Impediments to Mineral Extraction.

Signature:



# Section of Plan

Policy ENV 8 Green Network

#### Nature of Representation

Seeking a change to the document	
Supporting the content of the document, or a particular section of the	Х
document	

# We **support** this policy.

In respect of our interests, the associated multiple benefits that the Green Network can deliver is fundamental to the successful implementation of the river basin management plan and sustainable flood risk management. The promotion of multi-functional green networks will therefore ensure that complimentary environmental benefits will be considered and delivered as part of the network. This accords with SPP paragraph 220 which states that planning should 'protect, enhance and promote green infrastructure, including open space and green networks as an integral component of successful placemaking'.

We also **support** the supporting text at section 5.156 which highlights that the council will encourage the inclusion of SUDS, swales, wetlands, rivers and canals and their banks as part of the green network.

In addition, we note and support the recognition within policy EMG 3 on Sustainable Drainage that drainage in new developments can contribute to the delivery of green infrastructure and the green network. We have responded to Policy EMG 3 separately.

Signature:

Name: Scottish Environment Protection Agency
Address: Strathallan House, The Castle Business Park, Stirling, FK9 4TZ
Daytime telephone:
Email:

# Section of Plan

Policy ENV 11 Protection of the Water Environment/Coastline and Riparian Corridors

# Nature of Representation

Seeking a change to the document	
Supporting the content of the document, or a particular section of the	Х
document	

We **support** the intention of this policy and in particular the clear policy position that development proposals which would lead to deterioration of the ecological status of any element of the water environment will not be supported.

We also **support** the inclusion of the specific policy requirements in terms of: protection of Groundwater Dependent Terrestrial Ecosystems (GWDTE); a presumption against unnecessary engineering works in the water environment; improvements to the water environment where possible and the development of measures identified within the Forth Area River Basin Management Plan

The application of this policy will ensure that all development proposals must minimise and mitigate impacts on the water environment. This is supportive of the Water Framework Directive (WFD) "protect" objective, reflected in your Authority's duties under the Water and Environment and Water Services (Scotland) Act 2003. (paras 2(1) and 2(2) refer).

Please also see our comments in respect of policies EMG 1 Water Environment Improvement and EMG 3 Sustainable Drainage

Signature:

Name: Scottish Environment Protection Agency
Address: Strathallan House, The Castle Business Park, Stirling, FK9 4TZ
Daytime telephone:
Email:

# Section of Plan

Policy HOU 4 Windfall Housing Development in Linlithgow and Linlithgow Bridge

## Nature of Representation

Seeking a change to the document	
Supporting the content of the document, or a particular section of the	Х
document	

In line with the comments we offered at the Main Issues Report, we **support** the aim of this policy which stresses the Council's intention to give extra scrutiny to infill proposals within these settlements to take account of the air quality and water quality issues in the area. As stated by us previously, we would welcome the opportunity to assist the Council in the preparation of Supplementary Guidance in respect of Linlithgow Loch.

Signature:

Name: Scottish Environment Protection Agency
Address: Strathallan House, The Castle Business Park, Stirling, FK9 4TZ
Daytime telephone:
Email:

# Section of Plan

Policy INF 1 Infrastructure Provision and Developer Obligations

#### Nature of Representation

Seeking a change to the document	Х
Supporting the content of the document, or a particular section of the	Х
document	

We **support** the policy commitment that development proposals will only be supported when identified infrastructure requirements have been addressed. We support the reference within the supporting text at section 5.81 to the green network and drainage. We **require**, however, that the text here is **modified** to include wording in order to reflect the potential for developer contributions to assist with the delivery of River Basin Management Plan (RBMP) objectives related to site(s) development. The improvement of the water environment through measures put in place during the development process are crucial to achieving the high level objectives of the Water Framework Directive such that the water environment is protected from deterioration and is restored to good ecological status.

Suggested additional wording for section 5.81 is as follows:

Developer contributions may also be required for the protection and enhancement of the water environment and sustainable flood management.

Signature:

Name: Scottish Environment Protection Agency
Address: Strathallan House, The Castle Business Park, Stirling, FK9 4TZ
Daytime telephone:
Email:

# Section of Plan

Policy MRW 2 Supporting Principles for Mineral Extraction

# Nature of Representation

Seeking a change to the document	
Supporting the content of the document, or a particular section of the	Х
document	

Policies relating to mineral workings should be consistent with our guidance relating to air, water and soils ensuring that there are no significant negative impacts on such issues insofar as they relate to our interests. For minerals proposals the development plan should require the submission of a restoration and aftercare plan. As the policy requires this by way of bullet point b, we **support** its inclusion.

Signature:

Name: Scottish Environment Protection Agency
Address: Strathallan House, The Castle Business Park, Stirling, FK9 4TZ
Daytime telephone:
Email:

#### Section of Plan

Policy MRW 3 Impediments to Mineral Extraction

## Nature of Representation

Seeking a change to the document	
Supporting the content of the document, or a particular section of the	х
document	

We **support** the specific reference within this policy to the presumption against mineral extraction proposals for peat extraction of where there would be irreversible damage to a peat habitat.

Please note we have commented in more detail in respect of peatland in our response to Policy ENV 6 Peatlands and Carbon Rich Soils.

Signature:

Name: Scottish Environment Protection Agency
Address: Strathallan House, The Castle Business Park, Stirling, FK9 4TZ
Daytime telephone:
Email:

# Section of Plan

Policy MRW 7 Waste Management on Construction Sites

## Nature of Representation

Seeking a change to the document	
Supporting the content of the document, or a particular section of the	Х
document	

We **support** this policy which both incorporates waste minimisation principles within the Plan to ensure that waste generation is minimised during construction, but also ensures that adequate space for waste and recycling facilities within new developments is provided.

This will assist the Council in meeting the Scottish Government's Zero Waste goal by maximising the opportunities for waste recycling.

Signature:

Name: Scottish Environment Protection Agency
Address: Strathallan House, The Castle Business Park, Stirling, FK9 4TZ
Daytime telephone:
Email:

#### Section of Plan

Policy MRW 8 Waste Management Facilities

#### Nature of Representation

Seeking a change to the document	Х
Supporting the content of the document, or a particular section of the	Х
document	

There is a pressing need to move waste management away from landfill and towards sustainable waste management. Positive planning guidance needs to be in place to help deliver new facilities and infrastructure required to facilitate this move, as well as to support the new methods of waste collection.

We **support** the inclusion of this policy as it will assist the Council in their pivotal role in helping to deliver the national waste targets reflected in the Zero Waste Plan (ZWP) through the provision of a positive policy framework for new infrastructure.

Specifically, we **support** the following aspects of the policy:

- Identification (and safeguarding of these from inappropriate adjacent development) of existing waste management sites on the proposals maps;
- The clear reference to the waste hierarchy and the associated policy framework which will ensure that applications for new waste management facilities will be assessed against this as well as the Zero Waste Plan, PAN 63 and SPP.
- The policy statement that sites generally considered suitable for waste management facilities include existing or allocated industrial land (specifically Class 5 or 6) and the re-use and extension of existing waste management sites.

SEPA does not comment individually on the proximity of waste sources to waste management facilities nor the need for such waste facilities within a Plan area. Notwithstanding this, it is important that development plans are not restrictive on the source of the waste being managed within waste facilities. As a result, when considering the potential for new waste management facilities we require that LDPs do not restrict the movement of waste to/from respective Plan areas whilst there remains a national shortage in waste infrastructure. As such we require that the Plan be **modified** to reflect this.

We **support** the requirement within this policy for the promotion of the recovery of energy from waste, whereby sites are to be designed to enable links to be made to potential users of the heat and/or power generated at such sites.

Signature:

Name: Scottish Environment Protection Agency
Address: Strathallan House, The Castle Business Park, Stirling, FK9 4TZ
Daytime telephone:
Email:

#### Section of Plan

Policy MRW 9 Landfill Sites

#### Nature of Representation

Seeking a change to the document	
Supporting the content of the document, or a particular section of the	Х
document	

We **support** the inclusion of this policy which states clearly that new landfills will only be supported where they are required in specific circumstances including where there is a requirement to meet the need for a 10 year rolling landfill capacity as identified in the Zero Waste Plan Regional Capacity Table.

Signature:

Name: Scottish Environment Protection Agency
Address: Strathallan House, The Castle Business Park, Stirling, FK9 4TZ
Daytime telephone:
Email:

#### Section of Plan

Policy NRG 1 Climate Change and Sustainability

# Nature of Representation

Seeking a change to the document	
Supporting the content of the document, or a particular section of the	Х
document	

We note and **support** the Council's overarching policy in respect of climate change and sustainability which will be promoted by way of several policies within the Proposed Plan. We have commented separately on the policies that fall within our remit and we would direct you to our comments on ENV6, MRW7, NRG3, NRG5, EMG1, EMG 2 and EMG 3 in this regard.

Signature:

Name: Scottish Environment Protection Agency
Address: Strathallan House, The Castle Business Park, Stirling, FK9 4TZ
Daytime telephone:
Email:

# Section of Plan

Policy NRG 3 Wind Energy Development

#### Nature of Representation

Seeking a change to the document	
Supporting the content of the document, or a particular section of the	Х
document	

We note that the policy directs developers to the Supplementary Planning Guidance (SPG) Wind Energy whereby 'the council supports the development of wind energy schemes in principle....wind energy proposals will be assessed against the detailed spatial framework and the criteria set out in SPG". Further, the policy states that 'development will be supported where it can be satisfactorily demonstrated that proposals will not individually or cumulatively have a significant adverse impact on local communities, natural environment, public safety and economy'. We understand that the SPG will not be adopted by the Council prior to the end of the consultation period for the LDP.

We commented on the draft SPG in July 2013 and at that point highlighted a number of concerns on the wording it contained. We note that that some of the issues highlighted in our response have been addressed by way of policy coverage in the LDP (for example, the protection of Groundwater Dependent Terrestrial Ecosystems and the avoidance of development on deep peat). Whilst we **support** the overarching aim within the policy that wind energy development will only be supported where it is demonstrated that individually or cumulatively there will be no adverse impact on the natural environment, we require to **reserve our position** on this aspect of the Proposed Plan until the SPG is published later this year.

Signature:

Name: Scottish Environment Protection Agency
Address: Strathallan House, The Castle Business Park, Stirling, FK9 4TZ
Daytime telephone:
Email:

# Section of Plan

Policy NRG 5 Energy and Heat Networks

# Nature of Representation

Seeking a change to the document	
Supporting the content of the document, or a particular section of the	Х
document	

We **support** the inclusion of this policy which aims to ensure that West Lothian's greenhouse gas emissions are mitigated by the use of district heating schemes where technically feasible. We note and welcome the Council's commitment to the preparation of a Heat Map.

We also **support** the final paragraph of the policy which encourages developers of substantial new development to consider the use of community energy networks in their development. Furthermore, we **support** the section of the policy which states that where an existing local energy network is established, developments will be expected to connect to it, if this is technically feasible.

Finally, with regard to new developments in proximity to existing or proposed heat networks, we **support** paragraph 3 of the policy which states that new development in areas identified as appropriate for district heating, or where a district heating network exists or is planned, will require to include infrastructure for connection to these networks.

Signature: