

COMMENTS AND RATINGS West Lothian Trusted Trader Scheme

Tony McCorisken Roofing & Building Services Ltd

NUMBER OF FEEDBACK FORMS RECEIVED: 80 (showing most recent 30)

AVERAGE SATISFACTION SCORE (OUT OF 10): 9.9

The following feedback forms have been completed by previous customers, rating their experience of dealing with Tony McCorisken Roofing & Building Services Ltd.

ONLINE FEEDBACK PROVIDED	Date received: 18 th June 2024				
	Total cost of w	ork: £2800			
	Description of work: Repair 2 valleys on roof, we were getting 1 valley repaired, but we had to wait several weeks for the job to start because of poor we weather. While waiting the other valley started to leak as well Comments: Tony has been a roofer for many years, I				
	think he started	d helping his fa	ther as a hol	iday job.	
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 29 th April 2024			
	Total cost of work: £900			
	Description of work: Brickwork			
	Comments: Tony replaced several damaged bricks on our house to an extremely high standard and lef the area spotless. Would definitely recommend!			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 25 th March 2024 Total cost of work: £2268 Description of work: Complete refurbishment of garage roof. Comments: If I need any further building services I shall approach Tony first. He was punctual, thorough discreet and highly diligent. All debris was removed from the site and all was left clean and tidy. I am ver satisfied with his work, which was supported by efficient administration from his office.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 11 th December 2023				
	Total cost of w	ork: £10200			
	Description of work: Total roof replacement				
	Comments: Tony & his workers done a great job! They arrived when they said they would & kept us updates of any weather related delays etc. They worked in some horrible weather but kept on going when they could. The property was given a good tid up when work was completed. Highly recommend using Tony for any of your roofing work.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 23 rd November 2023				
	Total cost of w	ork: £288			
	Description of work: Roof repairs Comments: Amazing company, would highly recommend. Definitely use again, if required, in future. Contacted Tony, who came out on Sat 18/17 sent us quote, we accepted quote, work completed on Wed 22/11. What more could you ask for?				
				ed, in Sat 18/11, ompleted	
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 13 th July 2023			
	Total cost of work: £2000			
	Description of work: Completed all Roof work on a building on our premises, one of our building roofi tiling the whole works. Comments: Did an awesome job.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 13 th July 2023			
	Total cost of w	ork: £100		
	Description of work: Fixed small hole in my Guttering and took out dead leaves etc.Comments: Did a great job.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 23 rd June 2023			
	Total cost of w	ork: £1968		
	Description of work: Remove and replace windo Repair damaged roughcast under window and f another 2 patches on wall.			
	Comments: Tony came to prepare estimate which was broken down showing work that needed to be carried out. I'm delighted with finished result. I fou Tony to be reliable, friendly and very professional. job well done. No hesitation in recommending Tor and his team.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 15 th November 2022 Total cost of work: £575			
	Description of work: Sky light in the attic roof.			pof.
	Comments: Job completed on time and to a high standard so would definitely use again and recommend.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 2 nd November 2022			
	Total cost of w	ork: £1600		
	Description of work: Stripped garage roof and replaced with new felt flat roof.			and
	Comments: Great communication, completed quickle and tidied area afterwards.			ted quickly
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

т

Total cost of the work ε 9 μ 8	Date received: 19 th May 2022			
Description of the work undertaken: loughcast Chumway Repaire Cast Gutter joints	 Total cost of work: £948 Description of work: Roughcast chimney. Repair gutter joints. Comments: Would highly recommend this compared 			·
your comments highly recommend this company	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 11 th May 2022			
	Total cost of work: £1032			
	Description of work: Roughcast chimney, repair cast gutter joints, replace cast gutter section.			repair cast
	Comments: Job well done. Very professional.			nal.
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 28 th April 2022 Total cost of work: £5016 Description of work: Replacing and repairing surrounds of dormer windows and garage roof. Also repairs to ridge tiles on house and garage roof. Comments: Tony has done a few jobs on our roof previously so we had no hesitation in asking him to carry out work on our dormer windows, house roof and garage roof. Tony was very clear in communicating the work that was required - both verbally and in his quote. He and his colleague completed the work to a very high standard. We're very happy with the result and are glad that our roof is now more durable and secure. We would highly recommend Tony.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ 11 600	Date received: 6 th January 2022			
Description of the work undertaken. Entire took replacement, chimney normaticl, roughcart	Total cost of work: £11,600			
chimney, putter repair	Description of work: Entire roof replacement, chimney removal, roughcast chimney, gutter repair.			
Your comments: Roof Replacement	Comments: Roof replacement. Roughcast chimney. Repair gutters.			
Repaire Gutters	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £	Date received: 15 th December 2021				
Description of the work undertaken: ROF Replacement Rough crist CHIMNOY Replace Gutters Your comments: Tony and his team have been reliable, friendly and happy to answer any questions before and during the	Total cost of w Description of chimney. Repa Comments: To friendly and ha and during the is great and the to keep the are definitely recor	work: Roof rep air gutters. any and his tea appy to answer work carried of ere was little di ea tidy during a	lacement. Ro m have been any questior out. The quali isruption. The	reliable, ns before ty of work ey ensured	
work car ried and. The quality of not is great and there was little disruption. They ensured to keep the areatidy during and after the job. I wood definately recommend?	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 6 th December 2021				
	Total cost of w	ork: £408			
	Description of work: Replace air vent and carry repair to roof.			carry out	
	Comments: First class service, would highly recommend. Tony and his employees very approachable and friendly. If you need any works carried out on your roof use these guys.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

Tatal cost of the work £	Date received: 2 nd September 2021				
ROOF REPIRCEMENT (SLATE)	Total cost of work: Not provided.				
	Description of work: Roof replacement (slate).				
Very profferenced, next and ticly whilst	Comments: Very professional, neat and tidy whilst working, no mess was ever left. I would highly recommend.				
working, ho mess was ever left I would highly recommend	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

Total cost of the work £ 1900 row	Date received: 10 th August 2021				
Description of the work undertaken: (1) CLEERWERS loof of MOSS (2) Reprivaces Ridge System Your commenta	Total cost of work: £1800 Description of work: 1. Cleaned roof of moss 2. Repaired ridge system Comments: First class competent job. Work carried out efficiently and well. No debris left, all tidied up and left in clean condition.				
FIRST CLASS COMPETENT JOB WORK CARRIED OUT KEPICENTLY			Tidiness		
Customer Ratings (Out of 10)	10	10	10	10	

Total cost of the work I.	Date received: 10 th August 2021			
Man Roof Replacement	Total cost of work: Not provided.			
CHANGE Configuration of FLAT Roof	Description of work: Main roof replacement. Change configuration of flat roof.			
Your comments Gradity workmanship and timeous,	Comments: Good quality workmanship and timeous, pleasant workmen!!			
pleasant workmen!	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work i <u>E13,896 (inclusive flyest)</u> Description of the work undertaken: <u>Cathoplathy learner</u> <u>Bid rendersol</u> , <u>Male repairs as necessary on the back of</u> <u>Ke perperty which included the 3 address of</u> <u>Addressed which work to make sife the bick work in cellor area which was unstable</u> <u>Addressed work to make sife the bick work in cellor area which was unstable</u> <u>Addressed work to make sife the bick work in cellor area which was unstable</u> <u>Addressed work to make sife the bick work in cellor area which was unstable</u> <u>Apply rangingest to the rear of properties and early out small addressed</u> <u>reausests</u> <u>row runs a very organized burnies and his team work very well togeth-</u> <u>work good human</u> . <u>At all times I have full confidence that they were</u> <u>unith good human</u> . <u>At all times I have full confidence that they were</u> <u>unith good human</u> . <u>At all times I have full confidence that they were</u> <u>unith good human</u> . <u>At all times I have full confidence that they were</u> <u>unith good human</u> . <u>At all times I have full confidence that they were</u> <u>unith good human</u> . <u>At all times I have full confidence that they were</u> <u>unith good human</u> . <u>At all times I have full confidence that they were</u> <u>unith good human</u> . <u>At all times I have full confidence that they were</u> <u>unith good human</u> . <u>At all times I have full confidence that they were</u> <u>unith good human</u> . <u>At all times I have no hesutation in Hommeding thin</u>	Date received: Total cost of w Description of roughcast, mai the property wi Additional worl area which wa of properties a Comments: To his team work At all times I ha ensuring that r on completing have no hesita and will certain for exterior wor	ork: £13,896 (i work: Complete ke repairs as n hich included th to make safe s unstable. App nd carry out sn ony runs a very very well toget ad full confiden to corners were the job to a ve tion in recomm ly use them ag	nclusive of V ely remove o ecessary on he 3 address the brick wor oly roughcast nall additiona organised bu her with good ice that they e cut and a 10 ry high spec. nending this c	Id the back of es of rk in cellar t o the rear I requests. usiness and humour. were 00% focus Would company
Coupony and well containly use them again as my first choice for exterior work,	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work E	Date received: 11 th May 2021			
Renew GLASS TIMber frame	Total cost of work: Not provided.			
new upvc Fasna & Guttors	Description of work: Renew glass timber frame. Repair step. New UPVC fascia and gutters.			
Your comments:	Comments: Very happy with the professional finis work and attention to detail perfect. Highly recommended.			nal finish to
New happy with the progradiant finish & work and attention to detail peopled wighty recommended	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £	Date received: 6 th May 2021			
Description of the work undertaken:	Total cost of work: Not provided Description of work: Slate repairs / repair balcony flat roof.			
SLATE REPAIR BALCONY FLAT ROOF				
Your comments	Comments: All work completed to high standard Would 100% recommend.			
ALL WARE CONFLICTOR MY WILL STRATEGIES . WHILE 100% RECEIPERS	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work #	Date received: 6 th May 2021			
Description of the work undertaken: TOP Step Replacement.	Total cost of work: Not provided			
	Description of work: Top step replacement.			
	Comments: Job well done.			
Your commonts: Jab Verr DONE.	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £	Date received: 8 th April 2021				
Description of the work undertakers SLATE & LEAD REPAIRS	Total cost of work: Not provided. Description of work: Slate and lead repairs.				
	Comments: Excellent all round work, extremely happy.				
EXERCIST ALL ROUND work Extremptoy Happy	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

Total cost of the work £	Date received: 8 th April 2021			
Description of the work undertaken: Cenart 3/ceni S	Total cost of work: Not provided.			
The Repaires install vents Demars Roof	Description of work: Cement skews, tile repairs, install vents, de-moss roof.			
Now community infrassingle with work cominal and An scallant and Anglassianal job to wory high standards. Highly No conversional	Comments: Very impressed with work carried out. An excellent and professional job to very high standards. Highly recommend.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work & Description of the work undertakence URVE FASIAS/ Soffits/new Cuttores Damoss ROOF new clicky VECTYR	Date received: 8 th April 2021 Total cost of work: Not provided. Description of work: UPVC fasias/soffits/new gutters. De-moss roof, new dry verge.			ew gutters.
Your commenter Complete Satisfaction with Tany & his Fear	Comments: Complete satisfaction with Tony and his team.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £	Date received: 8 th April 2021			
Description of the work undertaken: Poughanst Patans	Total cost of work: Not provided. Description of work: Roughcast patches. Comments: Excellent job – tidy, on time, good quality.			
Your comments: EXAMPT JOB - TIDY, DN TIME, GOOD QUAL 174	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED		ate received: 25 th March 2021 otal cost of work: £624			
	 Description of work: Remove all decorative ridge tiles. Make the ridge watertight, replace all the decorative tiles and bed them in. Replace missing/broken slates. Comments: I phoned to request a roof inspection/estimate. I got an estimate emailed next day. Estimate was acceptable and asked for work to be done asap. A few days later he came fully equipped and completed the job the same day (we thought it may take 2 days). Everything was left near and tidy. Very happy with the price and work and highly recommend this tradesman who has many years of experience. Glad he was recommended on Trusted Trader. 				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

Total cost of the work E	Date received: 1 st March 2021				
Description of the work undertaken: NEW FLAT ROOF / Timbers / NEW UPVC FASIA	Total cost of work: Not provided. Description of work: New flat roof/timbers/new UPVC fascia.				
Your comments: ABOOLUTESCI FINITACIO	Comments: Absolutely fantastic! Very professional, very courteous and a pleasure to have around the house. Would definitely recommend!				
HAVE ARDIND THE AUGE	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

Total cost of the work £	Date received: 15 th February 2021			
Description of the work undertaken:	Total cost of work: Not provided.			
	Description of work: Flat roof.			
Your commercial	Comments: Excellent work. First class job. Definitely contact for additional work.			
DEFLICENT WORK. FIRE CLASS TOS. DEFLICE CONTRES FOR ADDITIONAL WORK.	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10