

COMMENTS AND RATINGS West Lothian Trusted Trader Scheme

Almondvale Plumbing & Heating Services

NUMBER OF FEEDBACK FORMS RECEIVED: 28

AVERAGE SATISFACTION SCORE (OUT OF 10): 9.8

The following feedback forms have been completed by previous customers, rating their experience of dealing with Almondvale Plumbing & Heating Services.

ONLINE FEEDBACK PROVIDED	Date received: 2 nd May 2025			
	Total cost of w	ork: £8022.54		
	 Description of work: Supply and fit replacement shower in main bathroom along with wet wall panels. Re-route shower drain via downstairs cloakroom, renew cloakroom ceiling, renew bathroom flooring. Comments: Simon and Mike were bang on time throughout. They carried out the required work to a very high standard. Great care was taken to minimise disruption and protect the house which they left in a good tidy state at the end of each working day. All in all, I have no hesitation in recommending APHS and would certainly use their services again if required. 			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	 Date received: 3rd September 2024 Total cost of work: £9500 Description of work: We had a new en-suite fitted, comprising of wet wall panels on all walls, a new shower unit and tray and combi toilet/basin unit, heated towel rail, new flooring and lighting and a Bluetooth mirror. Comments: Simon worked with us to put together all the elements, then when we asked about options to reduce the quote slightly he was happy to amend things to get it to a price we were happy paying. The en-suite looks amazing and we are so happy with the end result, and the fact everything was tidied up and got rid of in the skip. I would highly recommend Simon and the tradespeople he works with - we will be using him again when we renovate our main bathroom. 			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 23 rd August 2024				
	Total cost of w	ork: £15,000			
	 Description of work: Refurbish both the family bathroom and the downstairs WC. This involved advising on plans and materials for new rooms; sourcing and purchasing new materials; stripping out and disposing of old fitments; fitting new ones - including floors, sanitary ware, wall coverings and lighting. The bathroom also included a new ceiling. Comments: We are delighted with quality of APH's workmanship. Simon's suggestions always worked. Simon and Mike's attention to detail was spot on at all times. We are confident that there are no hidden problems to emerge later. The finished job looks flawless. Both were friendly, cheerful, and so tidy! Not even a biscuit wrapper was left for us to deal with. Their attitude made the disruption of such a big job so much easier to bear. We would definitely use them again and recommend them to anyone. 				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 21 st March 2024			
	Total cost of work: Not provided			
	Description of work: I contacted Simon for advice about a water leak, potentially related to a new heating system, which I was hoping the installer would repair.			
	Comments: Simon took a lot of time to listen to my concerns and help me understand the possible causes of the leak. Despite the fact that he was just preparing to return to work after dealing with a family issue, he offered to come out the following day to check the situation if it had not been repaired. I found Simon friendly, reassuring and very helpful. He made no charge for his advice and help I would not hesitate to recommend him.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	N/A	N/A	10	N/A

ONLINE FEEDBACK PROVIDED	Date received: 11 th March 2024			
	Total cost of w	ork: £135		
	Description of work: Supply and fit new bathroom taps.			throom
	Comments: Excellent service would highly recommend. Very quick to respond and repair carrie out to a high standard and reasonable price.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 7 th March 2024				
	Total cost of work: £3000				
	Description of work: Installed a new cylinder hot water tank for us when the old one started leaking.				
	Comments: Very professional job and Simon prioritised the job for us so we could get hot water again.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 5 th March 2024			
	Total cost of w	ork: £85		
	Description of work: Annual service of Heating Boiler			
	Comments: Always a professional job, and nothing any bother to Simon. More than happy to keep using Almondvale for plumbing and heating jobs.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 1 st March 2024			
	Total cost of w	ork: £85		
	Description of work: Boiler service carried out by Simon (owner).			
	Comments: Very professional, neat and tidy. Arrived when said and work carried out to an excellent standard. Great value for money and would highly recommend.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 1 st March 2024			
	Total cost of w	ork: £226		
	Description of work: Supplied & fitted new flush ar ball valve to WC in downstairs cloakroom 2. Supp & fitted new shower trap to repair leak in en suite shower.			
	Comments: Despite being very busy Simon came to do the work promptly, as we were expecting visitors in a couple of weeks. He explained what was needed, gave us options, and managed to obtain the appropriate parts (despite our old fittings). Then he completed the work to a high standard and also kept the place tidy during the process. He was friendly and inspired confidence. We would have no hesitation in using his services again or in recommending him to others.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 18 th April 2023			
	Total cost of w	ork: £500		
	Description of work: Numerous plumbing jobs aroun house over the last 3 or 4 years. From fixing a cistern, to replacing radiator valves and providing a quote for a replacement gas boiler. Comments: I have found Simon to be a reliable tradesman who will undertake all jobs big or small if he has the capacity to do those and to a high standard. He explains the work needed and the part and provides a quote.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 11 th April 2023				
	Total cost of w	ork: £8888.99			
	Description of work: Refit of our en-suite. Comments: Both Simon and Mike dragged our bedroom en-suite into the twenty-first century. Both were very professional from start to finish. A job well done. They will both be back in the future!!!				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 6 th April 2023			
	Total cost of w	ork: £84		
	Description of work: Fitting a water pressure valve under kitchen sink.			
	Comments: Very friendly and explained all the work he was doingcleaned up after the work was finished. Highly recommended.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 6 th April 2023			
	Total cost of w	ork: £100		
	Description of work: Replacement of taps and thermostat.			and
	Comments: Simon is great, reliable and friendly. He is a perfectionist and always goes above & beyond. would not trust any other plumbing or heating engineer.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received	Date received: 6 th April 2023			
	Total cost of v	Total cost of work: £260			
	Description of bathroom.	Description of work: Replaced blocked waste pipe in bathroom.			
	professional.	Comments: Simon was friendly, courteous and professional. We would be happy to have him undertake any further work we might need in future.			
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 16 th April 2020 Total cost of work: £60			
	Description of work: Simon arrived quickly to fix a leak. He set out to locate source which was in the loft. He tightened a fitting which caused a slow leat Matter resolved.			
	Comments: Simon arrived on time, was professional courteous and wore appropriate clothing during the Covid Pandemic. Reduced call out charge and applied no other charge for work carried out. A lovel touch. Would certainly recommend for large or small jobs.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 17 th January 2018 Total cost of work: £90			
	Description of work: My electric shower stopped working. Simon identified that there was power getting to the shower, but that it was the pull string unit that was not working.			
	Comments: When I called, Simon was very friendly and kind enough to agree to come out that day. Once he had identified what was wrong he nipped out to g and buy the part and came back and fixed the unit for me. He was very friendly, professional, informative and helpful. I would have no hesitation in getting him out to do other work and I would recommend him to anyone.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	8	10	10	9

Total cost of the work $\pounds 2300$, $\Rightarrow 0$	Date received: 9 th June 2016			
Description of the work undertaken: Sulply of Fitt Contraction, Collission Nai Cas Conbi Boilde	Total cost of work: £2300 Description of work: Supply and fit and commission new gas combi boiler.			
Your comments: Mr. HUNT CARE OUS PROMPTIM, WHEN CONTACTED ABOUT BOILER REPAREMENT, GAVE QUOTATION FOR, VARIOUS BOILENS & COSTS, NO PRESSUE SALES JOB WAS, COMPLETED ON DAY AGREED, IN A PROFESSIONAL AND	Comments: Mr Hunt came out promptly when contacted about boiler replacement, gave quotatio for various boilers and costs, no pressure sales. Jo was completed on day agreed in a professional ar courteous manner and very tidy.			
CONFREEDUS KANNER AND VERY TIBY	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 9 th June 2016 Total cost of work: £180				
	Description of work: Repair to central heating boiler with water leaks and pressure faults. Comments: Had several issues with our central heating boiler to the extent that we thought that it would have to be replaced. I called Simon and he promptly responded by visiting us within the hour ar told us quite honestly that there was no need to have the boiler replaced and that it was repairable. We les Simon to get on with it he went and sourced the required spares and the boiler was up and running again within hours. An honest, clean, tidy and professional individual.				
	Value for Quality of Service work			Tidiness	
Customer Ratings (Out of 10)	9	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 3 rd March 2016 Total cost of work: £40			
	Description of work: Remove gas fire, remove gas pipe to fire and cap.			iove gas
	Comments: Very professional, fast and friendly service and displayed and showed me his Gas Sa credentials without being asked, cleaned up and checked work prior to leaving, would highly recommend.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 17th February 2016			
	Total cost of w	ork: £400		
	Description of work: Service hot water tank, fix leaking tap, replace broken shower, remove old sink and tap.			
	Comments: Arrived on time, courteous, listened to problems, resolved them.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	8	10	10	10

ONLINE FEEDBACK PROVIDED	 Date received: 15th February 2016 Total cost of work: £82 Description of work: Repairs to kitchen sink waste. Replace and rebuild kitchen sink waste pipes. Comments: A simple leak due to incorrect trap and the fitting of a flexible waste pipe meant that the whole sink waste system had to be replaced with new. Firm contacted on Friday and plumber (Dave) arrived at the agreed time on Monday (8:30). Job assessed. Dave had to go and get new trap and replace old system in total. Job was carried out in one hour. Excellent work, quick and professional service provided. Work area cleaned up after job completed. No hesitation in employing firm again. 			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: Total cost of w Description of theating and ho Comments: Sin knowledgeable problem, I requ a replacement sheared off. Excellent servi highly recomm	ork: £376 work: Trouble of water system mon was very and quickly fo uired a new cer cold water tap ce and would o	shoot and rep n. friendly and bund the sour ntral heating and valve wi	rce of the pump and hich had
	Value for Quality of Service T money work			Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work $\$	Date received: 20 th August 2015 Total cost of work: Not provided. Description of work: Replacement of hot water and heating system with a combi boiler. New shower			
Description of the work undertaken: REPLACEMENT OF HOT WATER AND MEATING STRTP WITH A COMBUBOLISE. NEW SHOWER INSTALLATION				
Your comments: I FEEL THE WOLK WAS CARRED OUT PROFESSIONALLY	Comments: I feel the work was carried out professionally within the agreed cost and time frame. The work was done carefully.			
WITHIN THE AGEED (OFT AND TIME FRAME. THE WORK	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	8	10	10

Total cost of the work £ 1000	Date received: 12 th December 2013			
Description of the work undertaken:	Total cost of work: £1000			
New barlingon floor as had leak i tiles and flootoorids became wayed	Description of work: New bathroom floor as had leak and tiles and floorboards became warped.			
	Comments: Pleased with result.			
Your comments: Plaged with Result	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	7	10	10	10

Total cost of the work $\ensuremath{\mathbb{S}}$	Date received: 21st October 2013			
Description of the work undertaken: MAWTHNAWCH OF OLD COMBI	Total cost of work: Not provided.			
SUPPLY AND FITTING OF NEW	Description of work: Maintenance of old combi. Supply and fitting of new combi boiler.			
Your comments: AFATHER AND SON OPERATION	Comments: A father and son operation, I feel they are very trustworthy.			
LUST WORTHY	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	9	10	10

Total cost of the work \$ 3500	Date received: 21 st October 2013			
Description of the work undertaken: Remove old borler + pipework from kitchen Resite new borler in agrase and instal necessary pipework.	 Total cost of work: £3500 Description of work: Remove old boiler and pipe work from kitchen. Supply and resite new boiler in garage and install necessary pipe work. Remove hot water tank and header tank. Dispose of all waste. Install 4 new radiators in living room and kitchen/diner. Comments: First class job carried out on all aspects. Clear explanations given on progress and any 			
Remove hot water tank and header tank. Dripose of all warte. Instal I new radiators in Tripose of Rutchen enter, Your comments: First clars job coursed out on all aspects.				
Clear explanations given on progress and any points.	issues. Ongoing support and service excellent.			llent.
Ongonie support and service excellent	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

Total cost of the work \$ 3000	Date received: 5 th September 2013			
Description of the way undertaken: Jack of New Shower Room Cubicle Basen Toulet: Your comments: JA-IS WAS AN FINSURANCE -30B.	Total cost of work: £3000 Description of work: Fitted new shower room, cubicle, basin, toilet. Comments: This was an insurance job.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work $3,000 +$	Date received: 4 th September 2013			
Description of the work undertaken: New control heading boiler + new bachroom 34, te and separate shower room Your comments: Vora fair price, quick and extremely tidy (as. Very widing to explore, help and return with further support	Total cost of work: £3000+ Description of work: New central heating boiler and new bathroom suite and separate shower room. Comments: Very fair price, quick and extremely tidy job. Very willing to explain, help and return with further support.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	9