

COMMENTS AND RATINGS

West Lothian Trusted Trader Scheme

Allbright Electrical Contractors

NUMBER OF FEEDBACK FORMS RECEIVED: 97 (showing most recent 30)

AVERAGE SATISFACTION SCORE (OUT OF 10): 9.8

The following feedback forms have been completed by previous customers, rating their experience of dealing with Allbright Electrical Contractors.

ONLINE FEEDBACK PROVIDED	Date received: 1st July 2024 Total cost of work: £262			
	Description of work: EICR for a completion certific			
	Comments: First time using Callum and would definitely recommend. We needed an EICR to provide to the council to obtain a completion certificate for works completed some time ago. Callum had availability within the week and job wa done within an hour. Full report to the council and certificate received. Thanks again.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 26th April 2024			
	Total cost of w	ork: £610.63		
	Description of work: Various small jobs. New light a back door. Replace bathroom mirror. Replace chrome shaver socket. Replace wall mounted circul mirror. Supply and fit lithium co detector. Various sockets replaced/repaired. TV aerial booster fitted. Comments: Excellent work by a father and son tear They arrived early and just worked their way throug the various jobs, including some 'add-ons' on the day. Tidied up impeccably at the end. Would highly recommend them.			lace nted circular /arious ter fitted. d son team. ay through on the
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	9	9	10

ONLINE FEEDBACK PROVIDED	Date received: 12 th April 2024				
	Total cost of w	ork: £1068			
	Description of work: Outdoor socket box changes, installation of outdoor wall lights and floodlight. Under kitchen cabinet LED lights and wall mirror light installation. Comments: Very unprofessional. Father and son who bicker with each other all day and huff and puff their way through work. Messy and disorganised. Disrespectful towards private things in my home and lack of concern for leaving doors wide open while raining and cold outside and having a small dog in the house that could have escaped. Quick and happy to quote with nothing being a problem. Very different attitude once they start the work.				
	Value for Quality of Service Tidi money				
Customer Ratings (Out of 10)	7	7	1	1	

Trader right to reply:

As shown by other very positive reviews on this website, we have, for more than 34 years been a well respected and highly rated company.

As this is the second time we have worked for you we are saddened you could not approach us with your comments before you posted them on various places on the internet.

ONLINE FEEDBACK PROVIDED	Date received: 25 th January 2024 Total cost of work: £192				
	Description of work: £192 Description of work: 1. Advise on new shower unit which best suited my needs. 2. Install new shower unit, and set up same. 3. Correct wiring faults regarding hall light switches. 4. Reconnect ceiling pendant unit and test same. Comments: 'Allbright' made the initial visit as promised. They were punctual on the day they allocated to carry out the job. They both worked without a break and completed the tasks in a very reasonable time frame. They encountered a snag regarding the plumbing of the old shower, but dealt with that efficiently. I was made aware of the costs well in advance, and was happy with the quoted charge.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	9	10	10	

	ı				
ONLINE FEEDBACK PROVIDED	Date received:	ate received: 25 th April 2022			
	Total cost of work: £1105.48				
	Description of work: Installation of an electric car home charging point, including initial survey of the location. UK government grant deducted from invoice. Comments: Installed on final day eligible for grants, and Allbright made sure this happened. The work was done professionally, and all relevant paperworl was supplied ASAP to enable additional claim for Scottish grant. The associated app was demonstrated upon completion. I would definitely recommend Allbright.				
	Value for Quality of Service Tide			Tidiness	
Customer Ratings (Out of 10)	9	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 25 th April 2022				
	Total cost of w	ork: £96			
	Description of work: Move aerial point to new position behind television that was already wall mounted. Comments: Although always busy, Allbright Electric managed to slot my job into their schedule within a couple of days. David and Callum arrived at the appointment time, are always polite and friendly an on completion of the work, left the area neat and tic Wouldn't hesitate to recommend them and will certainly use them again.				
	Value for Quality of Serv work		Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 14 th March 2022			
	Total cost of w	ork: £72		
	Description of work: Identify faulty underfloor heating which was causing the system to trip.			
	Comments: Very prompt service which is ideal when you don't know why most of the electrics in your house are not working. Much appreciated.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 25 th February 2022 Total cost of work: £1350			
	Total cost of w	ork: £1350		
	Description of work: Installation of EV charge point my home address including design and commissioning and support through the grant application process.			
	Comments: The guys have been brilliant from start to finish - really professional and on the day of the installation they were on time, worked to an exceptional level and ensured that a full handover took place before they left my premises. All details of what was required to be done and why were explained in full detail. You could not ask for more and I would not hesitate to use them again for any further projects I may have and would highly recommended them to anyone.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

	Total cost of work: Not provided.				
	Description of work: Provided and installed an electric car charger unit.				
	Comments: I thought they were very professional, from the first contact they arranged to come out quickly and provided quote and information, then booked us in for the work to be done at a convenient time. On installation day they were punctual, polite, friendly, the kind of people you can talk to and ask questions. Showed me how to work everything before they left and house was all clean and tidy when job was complete. Would not hesitate to use them again and would happily recommend them to anyone.				
	Value for Quality of Service Tiding			Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED

Date received: 15th February 2022

ONLINE FEEDBACK PROVIDED	Date received:	Date received: 12 th May 2021			
	Total cost of w	ork: £450			
	Description of work: A lot electrical wires to sort as kitchen refurb.				
	Comments: First class service. Great guys down to earth which always good. I've used few times and intend to have them back again. An electrician company you can trust to do job proper.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 10 th May 2021			
	Total cost of w	ork: £375		
	Description of work: Supplied armoured cable for supply to new summer house and first fit wiring for sockets and lighting. Supplied, wired and fitted twin waterproof outdoor socket at rear of property. Comments: Excellent service. Provided great advice and were flexible in dealing with requirements when looking at options to supply power to a new summer house. Friendly and tidy experts! Have already recommended to others.			viring for fitted twin erty. eat advice ents when w summer
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 21st September 2020			
	Total cost of w	ork: £40		
	Description of work: Outside light fitted.			
	Comments: Great service. The guys were both friendly and chatty. Everything was left very tidy; would definitely use again and recommend.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Date received: 7th September 2020 OLEU LEST GRANTS Total cost of work: OLEV/EST GRANTS Description of the work undertaken: WALL ARILIOD IN BEDROOM TO DUSH CARLE OUT SIDE Description of work: Wall drilled in bedroom to push 45 of CASIE RUN PRONG GORDEN, DUG DOWN & RAPRACED cable outside, 45 of cable run along garden, dug down and replaced by workmen. Charger fitted at BY MORKMEN , CHARGER FITTED AT BACK END OF GARDEN back end of garden. Comments: Guys were in touch before start day, on the day arrived on time. Job done and place tidy. GOYS HERE IN TOUCH BEFORE START DAY, ON THE Garden put back to original state. DAY ARRIVED ON TIME JOB GARSEN PUT BACK TO ORIGINAL STATE Value for Quality of Service **Tidiness** money work 9 10 Customer Ratings (Out of 10) 10 10

ONLINE FEEDBACK PROVIDED	Total cost of Description of new 10 way Comments: Electrical Code a quote for reflectived a complete detailed quote quote quote detailed quote for reflective and the second se	Date received: 4th September 2020 Total cost of work: £587 Description of work: Replace old consumer unit new 10 way amendment consumer unit. Comments: Fantastic service provided by Allbrig Electrical Contractors Ltd. Contacted them to proa quote for replacing our old consumer unit. Received a quick response to our request and journal was completed within a few days of receiving the detailed quote. Would definitely recommend their very professional service.				
	Value for money	Quality of work	Service	Tidiness		
Customer Ratings (Out of 10)	10	10	10	10		

ONLINE FEEDBACK PROVIDED	Date received: 26 th August 2020			
	Total cost of w	ork: £593.66		
	Description of work: Remove and replace main fuse box. Re-purpose two electric sockets, rewire electrical switch and light boss, check wiring on stair lighting.			
	Comments: The electricians were punctual and friendly. They kept me informed as to how the work was progressing. Everything was left clean and tidy. will definitely use the firm again.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Description of the work undertaken: X2 EXTERNAL ELECTRICAL SECROS	Date received: 16 th July 2020 Total cost of work: Not provided Description of work: x2 external electrical sockets. Comments: Very courteous, easy to speak with. Very				
Very Curteaus, easy to speak with- Very ethicient and tide	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

Customer Ratings (Out of 10)	10	10	10	10
Description of the work undertaken: Install Rco Spur Unit for electric towel Rayl and install towel Raylin Buthroom. Install need Outside light. leplace existing Spotlights With Leed Spotlights Your comments:	Date received: Total cost of w Description of towel rail and i I.e.d outside lights Comments: 1s	vork: Not provid work: Install R install towel rai ght. Replace e	ded CD spur unit il in bathroom xisting spotliç	n. Install
15/ 5/15/5	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	9

Description of the work undertaken: Sholallarian of Hob Oken + Mealed Yowel Rail. Culside securly light. Roparted switch on Electric File.	Date received: 24 th February 2020 Total cost of work: N/A Description of work: Installation of hob, oven and heated towel rail. Outside security light. Repaired switch on electric fire.				
Your comments: Very professional and competent persons Explained everything in a concise manner Have no heritation in	Comments: Very professional and competent persons. Explained everything in a concise mann Have no hesitation in recommending to my friend and family.				
recommending to my shrends of family.	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

Total cost of the work £	Date received:	13 th Decembe	er 2019	
Description of the work undertaken: INSTRUMENT TO DOWNLLATED (REPLACEMENTS) PEPLACING OLD CONSUMER UNIT WITH NEW CONSUMER UNITS WITH R.C.B.O'S Your comments: WORK ARRIED OUT TO A HIGHSTADAM	Total cost of work: Not provided Description of work: Installing 7 downlights (replacements). Replacing old consumer unit with new consumer units with RCBO's. Comments: Work carried out to a high standard. Punctual, courteous and respectful of my proper		unit with	
OF MY PROPERTY	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work ₤	Date received: 15 th October 2019			
Description of the work undertaken: REPLACE FUGE BOX IN OARAGE	Total cost of	work: Not provi	ded	
The same of the sa	Description of work: Replace fuse box in garage.			
Your comments: Good, Grendly service and turned up when		Good, friendly s aid they would.	ervice and tu	rned up
they said they would	Value for money	Quality of work	Service	Tidiness
ustomer Ratings (Out of 10)	8	10	10	10

Total cost of the work £	Date received: 10 th October 2019			
Description of the work undertaken: PHT Testing Sporting the Europhice went Light hithing replacement Cleaning such replace Your comments: Excellent! Lots of additional with two campleted as meday - no need to a Nettern West.	Total cost of work: Not provided Description of work: PAT testing. Spotlight bulb replacement. Light fitting replacement. Electrical switch repair. Comments: Excellent! Lots of additional work was completed on Monday – no need for a return visit Polite, friendly, helpful electricians – will def. recommend.			
Polite, Mendly, helphul electricion - will def. recommend	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Date received: 27th September 2019 Total cost of the work £ Total cost of work: Not provided Description of the work undertaken: 8x twin Sochets, Description of work: Power to external workshop. 8 x Leid Strip light, Conduct, Fuseboard, putdoor Colle twin sockets, LED strip light, conduit, fuseboard, outdoor cable. Comments: Great workmanship. Would use again Your comments: 100%. great Workmanship, would use again 100%. Value for Quality of Service **Tidiness** work money

Customer Ratings (Out of 10)	10	10	10	10
Description of the work undertaken: OLD STRIP 4 GH13 RAPLACKS IN KITCHAN	Date received Total cost of w	vork: Not provi	ded o lights replac	
OVEN E HOS DISCONNICTED AND NIEW ONES INSTALLED. FOUR COMMENTS: OLD OVEN 1108 WAS TRIPPING & ATRICING OFF CALLED ALUBRICHT AND THAT CARE ROLLING BY AND	kitchen, oven installed. Comments: Of Called Allbrigh located the issue cooker and installed.	ld oven/hob want and they car sue. They retur	as tripping el ne following ned to disco	ectricity off. day and nnect old
LUCASHO THE ISSUE THRY RETURNED TO DISCOURSE OLD COULAND AND INSTALL NAW ONA VARY ALLONHOUSE	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Description of the work undertaken: WEW CONSUMEN UNIT, REPLACUO FAMILY BADRADA LIGHT/EXTRACTION PAW AND ADDRO POWEN FO LEXTURNA SUMMEN HOURS YOUR COMMENTS: VERY DEFAILS EXPLANATIONS BUFFORN JUS STANDO KLEFT ME INFORMED AS JUS PASAGSUS FINISHED BUS WIDEN AGREE TIMUS BREES. / WAS WATCHING MY	Date received: 14 th August 2019 Total cost of work: Not provided Description of work: New consumer unit, replaced faulty bathroom light/extractor fan and applied power to external summer house. Comments: Very detailed explanations before job started. Kept me informed as job progressed. Finished job within agreed timescales. I was watching my baby grandson and the guys are very child friendly.				
BABY CRANTSON AND PAS CHYS AND VOMY CHILD FRIENCE	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

Date received: 19th July 2019 Total cost of the work £ Total cost of work: Not provided Description of the work undertaken: & SAFETY FULL HOUSE ELECTRICAL CHECK AND UPDATE (FUSE BOXES Description of work: Full house electrical safety check and update (fuse boxes replaced etc.) Supply SUPALY S FIT OUTSIDE ELECTRICAL POWER and fit outside electrical power points. POINTS Comments: Very happy with all work carried out. VERY HAPPY WITH ALL WORK CARRIED OUT Value for Quality of Service **Tidiness** work money

Customer Ratings (Out of 10)	10	10	10	10	
Total cost of the work £	Data wasaiwa	d. 04st May 2004	0		
	Date receive	d: 31 st May 201	9		
Description of the work undertaken: REPLACEMENT OF OLD LIGHT FITTINGS WITH	Total cost of	work: Not prov	ded		
BYCKEY EFFICIENT, LED - INDOOR AND OUTDOOR	Description of work: Replacement of old light fittings with energy efficient LED – indoor and outdoor.				
Your comments: QUICK RESPONSE & QUOTE TIDY WORKERS, TURNED		Quick response time, polite and	•	dy workers	
UP ON TIME POLITE 4 CURTEDUS	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

Total cost of the work £	Date received: 24 th April 2019			
Description of the work undertaken:	Total cost of w	ork: Not provid	led	
THEO CAPE PROPERTY CHARLES COSTS	Description of work: Fuse box replaced, fan fitted, light fitted, smoke alarms and heat sensors fitted. Comments: No complaints.			
Your comments:	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ OLEV Grant	Date received: 24 th April 2019			
Description of the work undertaken:	Total cost of work: OLEV Grant			
FITTING AN ELECTRIC VEHICLE CHARGING POINT.	Description of work: Fitting an electric vehicle charging point.			
Your comments: VERY CONSCIENTIONS AND PERSONAGE. VERY PROFESSIONAL AND. DILIGENT WITH ALL LIVER WHISTIANSN. PHANK YOU!	Comments: Very conscientious and personable. Very professional and diligent with all work undertaken. Thank you!			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Customer Ratings (Out of 10)	10	10	10	10	
Description of the work undertaken: New bornson lights filled with bornson for and Switch charged to antique of bornson New downlighters filled in larden. Outside light fixed + new switches Your comments: excellent service work done quickly and very recsarchee pages I would have no hesitation in	Date received: 15 th April 2019 Total cost of work: Not provided Description of work: New bathroom lights fitted, with bathroom fan and switch changed to outside of bathroom. New downlighters fitted in kitchen. Outside light fixed and new switches. Comments: Excellent service, work done quickly and very reasonable prices. I would have no hesitation in recommending them and using them again in the future.				
reconnedit them and using them again in the fithe	Value for money	Quality of work	Service	Tidiness	
ustomer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 15 th April 2019				
	Total cost of work: £502.24				
	Description of work: Supply, wire, fit LED fire rated downlighter and light switch in wardrobe. In the attic, remove existing wiring and batten holder and supply, wire, fit light switch and LED fluorescent light fitting. Also tidy cabling and install junction boxes on downlighters in bathroom done by previous electrician. Remove existing external halogen security light, supply and fit LED security light with sensor. Replace faulty 4" extract fan in bathroom. Comments: We are very pleased with the work carried out by David. He was prompt and professional from estimate to finish job. We were grateful that he was able to replace the bathroom fan on short notice as we asked only the day before he was due to carry out the work. We will definitely use him again.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	9	