

## **COMMENTS AND RATINGS**

West Lothian Trusted Trader Scheme

## **Waterways Plumbing Ltd**

NUMBER OF FEEDBACK FORMS RECEIVED: 187 (showing most recent 30)

**AVERAGE SATISFACTION SCORE (OUT OF 10): 9.9** 

The following feedback forms have been completed by previous customers, rating their experience of dealing with Waterways Plumbing Ltd.

| ONLINE FEEDBACK PROVIDED     | Date received: 9 <sup>th</sup> July 2025   |                 |         |          |
|------------------------------|--|-----------------|---------|----------|
|                              | Total cost of w  | vork: £70       |         |          |
|                              | Description of work: Replacement of push-click wa in sink.   |                 |         |          |
|                              | Comments: Excellent service as always from Waterways. Very quick response, courteous, tidy work and value for money. |                 |         |          |
|                              | Value for money  | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10   | 10              | 10      | 10       |

| ONLINE FEEDBACK PROVIDED     | Date received: 7 <sup>th</sup> July 2025   |                 |         |          |
|------------------------------|--|-----------------|---------|----------|
|                              | Total cost of w  | ork: £130       |         |          |
|                              | Description of work: Fixed toilet that wasn't workin by completely replacing internal mechanism, provided advice on issue with sink and sealed outside tap.  Comments: Arrived on time, helpful advice and cle quote. Very satisfied with work done. Would recommend James for anyone requiring plumbing work. |                 |         |          |
|                              |  |                 |         |          |
|                              | Value for money  | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10   | 10              | 10      | 10       |

| ONLINE FEEDBACK PROVIDED     | Date received  | 7 <sup>th</sup> July 2025 |         |          |  |
|------------------------------|--|---------------------------|---------|----------|--|
|                              | Total cost of work: £70  |                           |         |          |  |
|                              | Description of work: Replace old shower unit with new shower unit.   |                           |         |          |  |
|                              | Comments: James arrived next day after messaging him and changed shower unit. As always he was on time and polite. Clean and tidy plumber and a good price for job. Will always use James for any plumbing jobs. |                           |         |          |  |
|                              | Value for money  | Quality of work           | Service | Tidiness |  |
| Customer Ratings (Out of 10) | 10   | 10                        | 10      | 10       |  |

| ONLINE FEEDBACK PROVIDED     | Date received: 30 <sup>th</sup> June 2025 |                 |         |          |
|------------------------------|---|-----------------|---------|----------|
|                              | Total cost of work: £65                   |                 |         |          |
|                              | Description of work: Toilet leak repair   |                 |         |          |
|                              | Comments: Reliable and professional       |                 |         |          |
|                              | Value for money                           | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10  | 10              | 10      | 10       |

| ONLINE FEEDBACK PROVIDED     | Date received: 30 <sup>th</sup> June 2025  |                 |         |           |
|------------------------------|--|-----------------|---------|-----------|
|                              | Total cost of w  | ork: £70        |         |           |
|                              | Description of work: Repair two leaks from kitchen water pipes.  |                 |         | n kitchen |
|                              | Comments: James was on time, efficient and very pleasant. His work is of excellent standard and I would highly recommend him as a plumber. |                 |         |           |
|                              | Value for money  | Quality of work | Service | Tidiness  |
| Customer Ratings (Out of 10) | 9  | 10              | 10      | 10        |

| ONLINE FEEDBACK PROVIDED     | Date received: 16 <sup>th</sup> June 2025  |                 |         |          |  |
|------------------------------|--|-----------------|---------|----------|--|
|                              | Total cost of work: £70  |                 |         |          |  |
|                              | Description of work: Supplied and fitted a replacement pop up plug in wash hand basin.   |                 |         | sin.     |  |
|                              | Comments: James was very quick to respond to my message and give a quote for the job. He was able to come the next day to do the work. Excellent communication and speedy service. |                 |         |          |  |
|                              | Value for money  | Quality of work | Service | Tidiness |  |
| Customer Ratings (Out of 10) | 10   | 10              | 10      | 10       |  |

| ONLINE FEEDBACK PROVIDED     | Date received: 16 <sup>th</sup> June 2025   |                 |         |          |  |
|------------------------------|---|-----------------|---------|----------|--|
|                              | Total cost of work: £70   |                 |         |          |  |
|                              | Description of work: Continuous running, overflowing and leaking toilet repaired. Flush / Plunger replaced  |                 |         |          |  |
|                              | Comments: Excellent service, second to none. Contacted Waterways Plumbing Ltd (James), he gave me a quote price and was with me in no time. Toilet repaired very quickly. |                 |         |          |  |
|                              | Value for money   | Quality of work | Service | Tidiness |  |
| Customer Ratings (Out of 10) | 10  | 10              | 10      | 10       |  |

| ONLINE FEEDBACK PROVIDED     | Date received: 9th June 2025  |                 |         |          |  |
|------------------------------|---|-----------------|---------|----------|--|
|                              | Total cost of w   | ork: £55        |         |          |  |
|                              | Description of work: To replace old tap for new.  Comments: James answered my message very promptly and asked for a description of the fault at to send a picture of the tap. Once he knew what t problem was told me a price and when he could come out. Kept me informed with times and days. Excellent service and would definitely recommend. James |                 |         |          |  |
|                              |   |                 |         |          |  |
|                              | Value for money   | Quality of work | Service | Tidiness |  |
| Customer Ratings (Out of 10) | 10  | 10              | 10      | 10       |  |

| ONLINE FEEDBACK PROVIDED     | Date received: 9 <sup>th</sup> June 2025   |                 |         |          |  |
|------------------------------|--|-----------------|---------|----------|--|
|                              | Total cost of w  | ork: £85        |         |          |  |
|                              | Description of work: Old outside tap removed an new tap and pipework installed.  |                 |         | ved and  |  |
|                              | Comments: James arrives promptly at the time give He was friendly and informative about what needed done and the job was completed in a timely manner Great service from James and I would definitely recommend to others. |                 |         |          |  |
|                              | Value for money  | Quality of work | Service | Tidiness |  |
| Customer Ratings (Out of 10) | 10   | 10              | 10      | 10       |  |

| ONLINE FEEDBACK PROVIDED     | Date received: 4 <sup>th</sup> June 2025  |    |    |          |  |
|------------------------------|---|----|----|----------|--|
|                              | Total cost of work: £122  |    |    |          |  |
|                              | Description of work: Replacement of a toilet bowl a cistern.  Comments: James was incredibly helpful - replied t messages promptly, outlined the issues and how he fix them, and provided full quotation for all work up front. He arrived promptly for the job, removed the old toilet and replaced with the new one, with all ne fittings, fully tested everything, and tidied up after the work was all finished. Extremely impressed, would heartily recommend to anyone needing plumbing work doing. |    |    |          |  |
|                              |   |    |    |          |  |
|                              | Value for Quality of Service work   |    |    | Tidiness |  |
| Customer Ratings (Out of 10) | 10  | 10 | 10 | 10       |  |

| ONLINE FEEDBACK PROVIDED     | Date received: 2 <sup>nd</sup> June 2025                             |                 |         |          |
|------------------------------|--|-----------------|---------|----------|
|                              | Total cost of w  | ork: £125       |         |          |
|                              | Description of work: Replacement tap and toilet flush mechanism.     |                 |         |          |
|                              | Comments: Very satisfied. Very professional, helpful and responsive. |                 |         |          |
|                              | Value for money  | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 9  | 10              | 10      | 10       |

| ONLINE FEEDBACK PROVIDED     | Date received: 22 <sup>nd</sup> May 2025  |                 |         |          |  |
|------------------------------|---|-----------------|---------|----------|--|
|                              | Total cost of work: £115  |                 |         |          |  |
|                              | Description of work: Remove waste disposal and replace with 1/2 sink basket and update plumber properly to support. |                 |         |          |  |
|                              | Comments: Excellent job. Very professional and highly reliable. Could not recommend him highly enough.              |                 |         |          |  |
|                              | Value for money   | Quality of work | Service | Tidiness |  |
| Customer Ratings (Out of 10) | 10  | 10              | 10      | 10       |  |

| Total cost of the work £ 5 14-  | Date received: 19 <sup>th</sup> May 2025  |                 |         |          |
|---|---|-----------------|---------|----------|
| Description of the work undertaken:  REMOUE OLD WASTE BOOK + INSTALL NEW KIT  | Total cost of work: £54  Description of work: Remove old waste bowl and install new kit.  |                 |         |          |
| YOUR COMMENTS:  COUNDA'T AGK FOR BETTER SERVICE. VERY POLITE RESPECTIVE,  EFFICIENT AND KNOWLEDGABLE. EXTREMENY FAIR PRICING, CLEAN  AND TIDY WORK. | Comments: Couldn't ask for better service. Very polite, respectful, efficient and knowledgeable. Extremely fair pricing, clean and tidy work. |                 |         | able.    |
|   | Value for money   | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10)  | 10  | 10              | 10      | 10       |

| ONLINE FEEDBACK PROVIDED     | Date received: 16th May 2025  |                 |         |          |  |
|------------------------------|---|-----------------|---------|----------|--|
|                              | Total cost of w   | vork: £74       |         |          |  |
|                              | Description of work: Identifying and fixing faulty be valve which was causing leaks.  Comments: Excellent service! Good communication good price and trader clearly cares about doing a professional job. |                 |         |          |  |
|                              |   |                 |         |          |  |
|                              | Value for money   | Quality of work | Service | Tidiness |  |
| Customer Ratings (Out of 10) | 10  | 10              | 10      | 10       |  |

| ONLINE FEEDBACK PROVIDED     | Date received: 14 <sup>th</sup> May 2025                                     |                 |         |          |  |
|------------------------------|--|-----------------|---------|----------|--|
|                              | Total cost of w  | ork: £85        |         |          |  |
|                              | Description of work: Outside tap fitted.                                     |                 |         |          |  |
|                              | Comments: Cannot recommend enough. Very punctual, friendly and professional. |                 |         |          |  |
|                              | Value for money  | Quality of work | Service | Tidiness |  |
| Customer Ratings (Out of 10) | 10   | 10              | 10      | 10       |  |

| ONLINE FEEDBACK PROVIDED     | Date received: 2 <sup>nd</sup> May 2025  |                 |         |          |
|------------------------------|--|-----------------|---------|----------|
|                              | Total cost of w  | ork: £45        |         |          |
|                              | Description of work: Washers changed in two toile  |                 |         |          |
|                              | Comments: James is really professional, good communications, reasonably priced and I wouldn't hesitate to recommend him to others or for myself in the future. |                 |         |          |
|                              | Value for money  | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10   | 10              | 10      | 10       |

| ONLINE FEEDBACK PROVIDED     | Date received: 30th April 2025   |                 |         |          |
|------------------------------|--|-----------------|---------|----------|
|                              | Total cost of work: £75  |                 |         |          |
|                              | Description of work: Change of faulty basin tap and waste.                                     |                 |         |          |
|                              | Comments: James was on time and organised and provided a fantastic service in a timely manner. |                 |         |          |
|                              | Value for money  | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10   | 10              | 10      | 10       |

| Total cost of the work £  | Date received: 30 <sup>th</sup> April 2025  |                    |         |          |  |
|---|---|--------------------|---------|----------|--|
| Description of the work undertaken: Repair Lean from Toilet Washe and Cistern.                  | Total cost of work: Not provided.  Description of work: Repair leak from toile waste and cistern. |                    |         |          |  |
| Your comments:<br>Very proffesional, and explained<br>Job very well. Can't recommend<br>enough. | Comments: Very professional and explained job very well. Can't recommend enough.                  |                    |         |          |  |
|   | Value for money   | Quality of<br>work | Service | Tidiness |  |
| Customer Ratings (Out of 10)  | 10  | 10                 | 10      | 10       |  |

| Total cost of the work £ 194  | Date received: 30 <sup>th</sup> April 2025   |                 |         |          |
|---|--|-----------------|---------|----------|
| Description of the work undertaken:  Renewing the radiator in the hall  | Total cost of work: £194  Description of work: Renewing the radiator in the hall.  |                 |         |          |
| Your comments:  James is avery professional and competent worker  and I would have no hesitation in using him again | Comments: James is a very professional and competent worker and I would have no hesitation i using him again and I would definitely recommend him to friends and family. |                 |         |          |
| and I would definitly recommend him to friends and family   | Value for money  | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10)  | 8  | 9               | 10      | 10       |

|                              | T  |                 |         |          |
|------------------------------|--|-----------------|---------|----------|
| ONLINE FEEDBACK PROVIDED     | Date received: 28th April 2025                 |                 |         |          |
|                              | Total cost of work: £45                        |                 |         |          |
|                              | Description of work: Replacing a dripping tap. |                 |         |          |
|                              | Comments: None provided.                       |                 |         |          |
|                              | Value for money                                | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 9  | 10              | 10      | 10       |

| ONLINE FEEDBACK PROVIDED     | Date received: 28 <sup>th</sup> April 2025                                   |                    |         |          |  |
|------------------------------|--|--------------------|---------|----------|--|
|                              | Total cost of w  | ork: £50           |         |          |  |
|                              | Description of work: Repair and replacement of leak pipe.                    |                    |         |          |  |
|                              | Comments: Very happy with all aspects of interaction and the completed work. |                    |         |          |  |
|                              | Value for money  | Quality of<br>work | Service | Tidiness |  |
| Customer Ratings (Out of 10) | 10   | 10                 | 10      | 10       |  |

| ONLINE FEEDBACK PROVIDED     | Date received: 28 <sup>th</sup> April 2025  Total cost of work: £40  |                 |         |          |  |
|------------------------------|--|-----------------|---------|----------|--|
|                              | Total cost of w  | ork: £40        |         |          |  |
|                              | Description of work: Poor flow and pressure at outdoor tap rectified by replacing tap.  Comments: James arrived less than an hour after I messaged to ask him to look at the job. He provided a price before arriving. On arrival James was very polite and friendly. He quickly confirmed his suspicions of what the problem was and had it fixed within 20 minutes. I wouldn't hesitate to recommend James, used his services several times over the years and he has always been exemplary. |                 |         |          |  |
|                              |  |                 |         |          |  |
|                              | Value for money  | Quality of work | Service | Tidiness |  |
| Customer Ratings (Out of 10) | 8  | 10              | 10      | 10       |  |

| Total cost of the work £ / 3 O   | Date received: 25 <sup>th</sup> April 2025  |                 |         |          |
|--|---|-----------------|---------|----------|
| Description of the work undertaken:                                    | Total cost of work: £130  |                 |         |          |
| Inside of toilet replaced (was not flushing properly before)           | Description of work: Inside of toilet cistern replaced (was not flushing properly before).      |                 |         |          |
| Your comments:  Excellent tradesman so nice to come                    | Comments: Excellent tradesman. So nice to come across a super, kind, professional tradesperson. |                 |         |          |
| Expellent tradesman so rice to come across a super, kind, professional | Value for money   | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10)   | 10  | 10              | 10      | 10       |

| Total cost of the work £ 55  | Date received: 16 <sup>th</sup> April 2025  |                 |         |          |
|--|---|-----------------|---------|----------|
| Description of the work undertaken:  REMOVED OLD MIXED TAP IN KITCHEN AND FITTED NEW ONE  Your comments:  EXCENDED TOB HIGHLY RECOMMEND PUNCTUAL | Total cost of work: £55  Description of work: Removed old mixer tap in kitchen and fitted new one.  Comments: Excellent job, highly recommend, punctual, reliable and informative. Neat and tidy work. Reasonably priced. Call again if required. |                 |         |          |
| RELIABLE & THEORMATIVE. NEAT & TIDY WORK. REASONABLY PRICED. CALL AGAIN IF REQUIRED  | Value for money   | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10)   | 10  | 10              | 10      | 10       |

| Total cost of the work £ 55 lab our                            | Date received: 16th April 2025                  |                 |         |          |
|--|---|-----------------|---------|----------|
| Description of the work undertaken:  New Wiyar late in Estaben | Total cost of work: £55 (labour)                |                 |         |          |
|  | Description of work: New mixer taps in kitchen. |                 |         |          |
| Your comments: Jab well done                                   | Comments: Job well done.                        |                 |         |          |
|  | Value for money                                 | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10)                                   | 10  | 10              | 10      | 10       |

| ONLINE FEEDBACK PROVIDED     | Date received: 15 <sup>th</sup> April 2025  |                 |         |          |
|------------------------------|---|-----------------|---------|----------|
|                              | Total cost of work: £75  Description of work: Old plug removed from bathroom sink and new plug installed.  Comments: Very professional job completed by James, friendly & reliable. Also managed to get to u promptly to sort the plumbing issue. Highly recommend! |                 |         |          |
|                              |   |                 |         |          |
|                              |   |                 |         |          |
|                              | Value for money   | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10  | 10              | 10      | 10       |

| ONLINE FEEDBACK PROVIDED     | Date received: 15 <sup>th</sup> April 2025  |                 |         |          |
|------------------------------|---|-----------------|---------|----------|
|                              | Total cost of work: £55   |                 |         |          |
|                              | Description of work: Replacement kitchen mixer tap.  Comments: Excellent service and speedy response. |                 |         |          |
|                              |   |                 |         |          |
|                              | Value for money   | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10  | 10              | 10      | 10       |

| ONLINE FEEDBACK PROVIDED     | Date received: 14 <sup>th</sup> April 2025  |                 |         |          |
|------------------------------|---|-----------------|---------|----------|
|                              | Total cost of work: £40   |                 |         |          |
|                              | Description of work: Leak on feed pipe below cistern Comments: Can't speak highly enough of this company. |                 |         |          |
|                              |   |                 |         |          |
|                              | Value for money   | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10  | 10              | 10      | 10       |

| ONLINE FEEDBACK PROVIDED     | Date received: 7 <sup>th</sup> April 2025  Total cost of work: £55  Description of work: Replaced kitchen tap and fixed a fault on the stop cock.  Comments: Amazing work, arrived on time, cleared |    |    |          |
|------------------------------|---|----|----|----------|
|                              | up no mess and charged the quoted price. Amazing stuff would highly recommend.  Value for Quality of Service Tidines work   |    |    | Tidiness |
| Customer Ratings (Out of 10) | 10  | 10 | 10 | 10       |

| ONLINE FEEDBACK PROVIDED     | Date received: 7 <sup>th</sup> April 2025   |                 |         |          |
|------------------------------|---|-----------------|---------|----------|
|                              | Total cost of work: £75   |                 |         |          |
|                              | Description of work: Installation of electric shower.  Comments: Fantastic service. Have used this company before and each time they are quick, reliable and well priced. |                 |         |          |
|                              |   |                 |         |          |
|                              | Value for money   | Quality of work | Service | Tidiness |
| Customer Ratings (Out of 10) | 10  | 10              | 10      | 10       |