

COMMENTS AND RATINGS

West Lothian Trusted Trader Scheme

Lothian Monoblocks & Landscapes Ltd

NUMBER OF FEEDBACK FORMS RECEIVED: 15

AVERAGE SATISFACTION SCORE (OUT OF 10): 9.8

The following feedback forms have been completed by previous customers, rating their experience of dealing with Lothian Monoblocks & Landscapes Ltd.

Description of the work undertaken: Jell getting make-over! Cleared side completely - all protons correct state the stand precious this should edging and growth paths. Duy have for planting. Your comments: Excellent work! Worked were hard at full speed.	Total cost of Description of site complete porcelain tile hole and fille	d: 8th Septembe work: £9500 of work: Full gard ely – all paving, o s, added edging d with topsoil for Excellent work! \	den make-ove concrete slab and gravel p r planting.	s etc. Laid paths. Dug
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	N/A	10	10	10
			I	

Total cost of the work & would prefer not to disclose	Date received: 14 th August 2025 Total cost of work: Not provided			
Installation of a new driverial and ficuldoor step. Installation was monoblock paring and relevant drain cales Your comments: Excellent workmanship, quality products used Communication was	Description of work: Installation of a new driveway and front door step. Installation was monoblock pairing and relevant drain covers. Comments: Excellent workmanship, quality product used. Communication was excellent throughout the entire process. Highly recommended.			oblock ity products
excellent throughout the entire piccess. Highly recommended.	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	8	9	10	9


Total cost of the work £ 2, 500	Date received: 23 rd June 2025			
Description of the work undertaken: RENDVATING and UPGRADING GARDEN PATTS &	Total cost of	work: £2500		
FRONT STEAS	Description of work: Renovating and upgrading garden path and front steps.			ading
FREST TOPS DONE BY THE YEAR TEATER EFFICIENT AND RELIANSEE	Comments: Great job done by the whole team, efficient and reliable. Cleaned away all waste and left garden in a neat and tidy condition.			
A NETTS V TIDY CONDITION	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ 72,500	Date receive	ed: 23 rd June 202	25	
Description of the work undertaken: Remove acciden + dirt wewcess for lass	Total cost of work: £7500			
municipals and another her first decretops	Description of work: Remove garden and driveway to lay monoblocks and create new front doorsteps.			
Hourcommences Great from - hard working + afficient. Von depart with Ronal result and house	Comments: Great team – hard working and efficient Very pleased with final result and have already booked them to do more work in back garden!			ready
already booked them to do wone work we loved garden!	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £	Date received: 29th May 2025				
Description of the work undertaken: CLEAR GARGEN THEN LAY PRETIFICIAL TURE SLABS AND SLATE CHIPS.	Description of work: Clear garden then lay artificial				
Your comments: COST OF WORK IS BETWEEN ME AND	turf, slabs and slate chips. Comments: Cost of work is between me contractor.			and	
CONTEACTOR	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	8	9	9	10	

Total cost of the work £ $\not\downarrow$ + 2 $\not\downarrow$ \Rightarrow \Rightarrow	Date received: 29 th May 2025			
Description of the work undertaken: RELAY NEW PATA AND STEEL	Total cost of w	ork: £12,000		
The state of the s	Description of work: Relay new patio and steps.			steps.
Your comments Excessed Jos Completed DY Shillen And Very				
WEATHER CONTRACT UNDETERED BY FOOR	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work &	Date received: 15 th May 2025			
Description of the work undertaken: To INSTALL A PORCELAIN PATIO AT THE REAL OF	Total cost of	work: Not provi	ded.	
TO INSTALL A PORCELAIN PATIO AT THE REAR OF	Description of work: To install a porcelain patio at the rear of the house			patio at the
Yourcomments: The Wore CARRIED OUT BY DARREN & FIRE TEAM WAS ENRICE OUT IN A PROFESSIONA MANNER & AM PLEASED WITH	Comments: The work carried out by Darren and the team was carried out in a professional manner an am pleased with the work done. I would definitely recommend Lothian Monoblocks & Landscapes L			anner and definitely
THE WORK DONG, I WAKE DEFINITELY RECOMMEND LOTHERN MONOCLOSES & LANGERARING LTS.	Value for money	Quality of work	Service	Tidiness
customer Ratings (Out of 10)	10	10	10	10



Total cost of the work £ $20,400$	Date receive	ed: 26 th Novembe	er 2024	
Description of the work undertaken	Total cost of	work: £20,400		
Remove old driveway paving + Renov Remove existing patie dats, prepare formation + lay even patie pavings. Remove dd timber forsed planters + resework stone poised planters up lift + relay existing manabled path.	and renew, remove existing patio slabs, prepare formation and lay new patio paving. Remove old			
Very professional beam, worked well and provided what I was a looking for Hage word than provided to lift That excess over a lay new stabled area.	provided what I was looking for. Have used them previously to lift rear grass area and lay new slal			d them
	Value for money	Quality of work	Service	Tidiness
customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ 11,000	Date received: 20 th November 2024			
New driverial - monoblock Second job - includin sandistone to back gauden Nour comments: The driverial was finished beautifully. To garden was also honever I wast happy with the aboustep. They made sure this was fixed and I was happy with it before asking for any sauvent. They would only	Total cost of work: £11,000 Description of work: New driveway – monoblo Second job – Indian sandstone to back garder Comments: The driveway was finished beautif The garden was also however I wasn't happy the doorstep. They made sure this was fixed a was happy with it before asking for any payme They would only complete a job if the custome happy. I have recommended to many friends a continue to do so.		autifully. ppy with ed and I yment. omer is	
complete a job if he customer is happy. I have recommended to many friends and will continue to do so.	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	9	9	9

Date received: 14th November 2024 Total cost of the work £ 8,000 Total cost of work: £8000 Description of the work undertaken: Description of work: Remove existing monoblock REMOVE EXISTING MONOBUCK DOLVEWAY AND EXISTING LAVIN, REVEN WITH SAME. driveway and existing lawn. Renew with same. Reduce height of boundary wall. Add coping stones. REDUCE HEIGHT OF BURNDARY WALL . ADD COPING STOKES. Repoint and jet wash patio to rear. REPOINT AND TETHACH PATIO TO REAR. Comments: A cheery hardworking team who got on with the job in spite of the challenges. The original plan was for the existing monoblocks to be re-laid Your comments: and were jet washed in preparation. Unfortunately, A CHEBRY HARDWORKING TEAM WHO GOT ON WITH THE JOB IN SPITEOF THE the bricks had been laid 36 years earlier using cement. New bricks had to be purchased. They had CHALLENGES. THE ORIGINAL PLAN WAS FOR THE EXISTING MUNOBLOCKS TO BE quite a task removing roots of a 50 year old cherry RELAIDAND WERE JET WASHED IN PREPARATION, INFORTINGTELY THE BRICKS HOD tree from the existing lawn. BEEN LAID 36 YEARS EARLIER WING CEMENT. NEW BUCKS HAD TO BE AURCHASED THEY HAD QUITE A TRIK REMOVING ADOS OF A FOYER OLD CHERRY THEE FROM THE EXISTING LAWN. Value for Quality of Service Tidiness work money Customer Ratings (Out of 10) 10 10 10 10

Date received: 31st October 2024 Total cost of work: £6500 Loyung Patio Description of work: Laying patio. Comments: Excellent job, very friendly, polite and reasonable price. Would recommend to friends and excellent job, very friendly polite and reasonable family. price, would recommend to friends and Value for Quality of Service Tidiness work money Customer Ratings (Out of 10) 10 10 10 10

Customer Ratings (Out of 10)

Date received: 31st October 2024

Total cost of work: £11,700 for back garden tiling, complete new fence and gate (double fence at rear).

Description of work: £11,700 as above. £5000 new monoblock driveway and path. New wall on one side of driveway and path.

Comments: We had a great experience and relationship with Darren and his team from getting a quote, to completion of the works. Couldn't recommend them highly enough. Great team.

Value for money	Quality of work	Service	Tidiness
10	10	10	10

Total cost of the work s \$\frac{1}{100}\$ Description of the work undertaken: Acrovia Soll and & Sheekells And Sully and LAY Concident And Any SANDSTONE TO THE AREAS WHICHES THE PLANTERS WORK. Your comments: We have used Lothian Mones lock hares at Foul	Date received: 24 th October 2024 Total cost of work: £1100 Description of work: Remove soil and sleepers and supply and lay concrete and lay sandstone to the areas where the planters were. Comments: We have used Lothian Monoblocks and Landscapes at four different addresses over the past 15 years and on every occasion we have received outstanding service in respect of quality and value			
EVELO OCCASION OF MAND RECEIVED OUTSTANDING SCHUTCH IN RESERVED OUTSTANDING.	and reliability.			Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ 5,000.00	Date received: 23 rd October 2024			
Description of the work undertaken: Removal of old discussions, and installation of	Total cost of work: £5000 Description of work: Removal of old driveway and			
new block driveway.	Description of work: Removal of old driveway and installation of new block driveway.			
Your commence The guys showed up early on the agreed clates, completed the work to a high standard	Comments: The guys showed up early on the dates, completed the work to a high standard charged what was agreed.			
and charged what was agreed.	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10