

NUMBER OF FEEDBACK FORMS RECEIVED: 415 (showing most recent 30)

AVERAGE SATISFACTION SCORE (OUT OF 10): 9.8

The following feedback forms have been completed by previous customers, rating their experience of dealing with Taylor Roofs.

ONLINE FEEDBACK PROVIDED	Date received: 14 th January 2024			
	Total cost of w	ork: £650		
	Description of work: Repair chimney which was weakened by the elements. Clean surrounding are leaving roof tiles free from debris. Stopped leak inte chimney cavity.			
	Comments: Excellent service as usual from Taylor Roofs. Professional survey followed up by quick an courteous tradesman repair. Highly recommended a repeat customer.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ 3807.67	Date received: 14 th January 2025			
Description of the work undertaken: INSTALLING NEW DEEP FLOW GU77ERING	 Total cost of work: £3807.67 Description of work: Installing new deep flow guttering. Installing dry verge interlocking units. Comments: Considering it was the coldest day we've had so far this year, we got a professional job from Guy and Lewis. 			
FNSTALLING DRY VERCE INTERLOCKING UNITS. Your comments: CONSIDERING 17 WAS THE COLDEST DAY WE'VE HAD SOFFAR				
CONSIDERING 17 WAS THE COLDEST DAY WE'VE HAD SOFFAR THIS YEAR, WE GOT A PROFESSION JOB FROM Guy & LEWIS	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	8	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 13 th January 2025			
	Total cost of work: £134			
	Description of work: Replaced dislodged tile			ile
	Comments: Couldn't fault Taylor Roofs kept in tou from start to finish came when they said they wou and above all very friendly.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Т

٦

ONLINE FEEDBACK PROVIDED	Date received: 7 th January 2025				
	Total cost of w	ork: £2002			
	Description of work: removing old drainpipes and gutters and pvc above garage door and side of garage. Putting up new gutters around full house a garage.				
	Comments: Done a great job really pleasant workmen when finished removed all old gutters ar drainpipes. left really tidy. Would really recommen this company to anyone.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 6 th January 2025			
	Total cost of w	ork: £132		
	Description of work: Replacing 2 cracked tiles on roof.			
	Comments: This was a very small job and Taylor fitted me in within a couple of days. Excellent service.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 17 th December 2024				
	Total cost of w	ork: £250			
	Description of work: Roof repair to moved tiles an replacing an obsolete vent tile.				
	Comments: Very easy to deal with from first call to survey/quote then repair. Roofing team were polite very knowledgeable, quick and you would not ever know they had been there afterwards. I would high recommend this company.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 10 th December 2024				
	Total cost of w	ork: £1200			
	Description of work: Two new gutters replaced and downpipe repaired.				
	Comments: Very happy with outcome, workman thoroughly professional as are all office staff, would highly recommend Taylor Roofs.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 9 th December 2024			
	Total cost of work: £11,000			
	Description of work: Full roof, fascias and gutteri replacement.			
	Comments: Great customer service from start to finish. Kept in contact to check all ok. One small issue however was resolved very quickly. Friendly team. Work completed timely and area left as tidy a possible whilst scaffolding was still in place. Completely satisfied from initial contact to completion. Definitely recommend Taylor Roofs.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 28th November 2024			
	Total cost of w	ork: £2300.04		
	Description of work: To bird and rodent proof the solar panels. Also, to replace the lead watergate at the right hand side of the rear dormer. Comments: All works carried out in a professional manner with friendly tradesmen who kept me informed as works progressed. The only downside was the long wait from me accepting the quote and paying a deposit to works beginning. We await som wet weather to assess whether or not the replacement lead watergate has cured the problem which we were experiencing!			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 28 th November 2024 Total cost of work: £7562			
	Description of work: Re lead coping stones on roc Comments: The workmen, Craig and Evan, were exemplary. They were very professional, keeping informed at every stage of the repair. They worke diligently and non-stop. The finished work looks excellent. The whole experience with Taylor roofin showed a level of customer care beyond my expectations.			n, were keeping me y worked looks or roofing
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 27 th November 2024			
	Total cost of w	ork: £1800		
	Description of work: Roof repairs			
	Comments: Would recommend Taylor Roofs for repairs.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	9	10	10

Total cost of the work £ 1475	Date received: 26 th November 2024			
Description of the work undertaken:	Total cost of work: £1475			
Roof repair	Description of work: Roof repair			
Your comments: Brilliant job, roof now repaired and quality work completed.	Comments: Brilliant job, roof now repaired and quality work completed.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 25th November 2024				
	Total cost of w	ork: £1338.42			
	Description of work: Repair lead to upstair bedroom window cill and lead under lead apron. Comments: Arrived on time. Workmen were professional and friendly and completed work in go time. Left property very tidy. Will definitely use aga for any roofing work.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	9	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 19 th November 2024				
	Total cost of w	ork: £2400			
	Description of work: Replace flashing front and rear of roof. Comments: Work carried out speedily and efficiently. Men involved were friendly, efficient and informative.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	8	10	10	9	

ONLINE FEEDBACK PROVIDED	Date received: 18th November 2024			
	Total cost of w	ork: £7000		
	Description of work: Turret roof repair.			
	Comments: Excellent service. Very helpful team.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ 30,968. Description of the work undertaken: <u>Report</u> the whole bungalows and replaces all ranworks goods. En finchy managed by Taylor Roofs - Sacaffeldus, Materials and labour.	 Date received: 14th November 2024 Total cost of work: £30,968 Description of work: Reroof the whole bungalow and replace all rainwater goods. Entirely managed by Taylor Roofs – scaffolding, materials and labour. Comments: Work carried out in expected timescale – both lead time and duration on site. Excellent communication from office staff and on site team – who explained what they were doing and answered questions. A very professional operation. 			
Your comments: 				
they were doing a annuel questions. A very professional operation	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	N/A	9	10	8

ONLINE FEEDBACK PROVIDED	Date received: 11 th November 2024 Total cost of work: £4000				
	 Description of work: Building a warm roof on a garage conversion (to a garden room), and new roughcasting on side wall. Comments: I'm satisfied with the whole process with Taylor Roofs. Quote was prompt and competitive. Work was done to a high standard. My only complaint is that there was very little time between some of the work being scheduled and carried out (i.e. less than one day), meaning it was difficult to warn my neighbour as he had to move his car. 				
	Value for Quality of Service Tic money work			Tidiness	
Customer Ratings (Out of 10)	7	8	8	9	

ONLINE FEEDBACK PROVIDED	Date received: 5 th November 2024 Total cost of work: £2081.18				
	Description of work: Works to address bird infestations in the eaves and under roof tiles at a residential property Comments: I'm really satisfied with the work carried out by Taylor Roofs and their communication throughout has been prompt and highly efficient. I'd really struggle to fault the service I have received and would have no reservation in recommending this company. The only thing I might have preferred would be an itemised invoice (I received an invoice detailing all works to be carried out and the total cost but no breakdown). That said, I did not request this a the time.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

Total cost of the work £ Approx £13,000 Description of the work undertaken: full roof to be replaced, old roop to be stapped and disposed of. Guttering to be reposed	Date received: 31 st October 2024 Total cost of work: Approx. £13,000 Description of work: Full roof to be replaced, old root to be stripped and disposed of. Guttering to be replaced.			
Your comments: Bunty, Jake, Robbie and Stuart pove been amoging, super propositional and want the attra mile to ensure I was	Comments: Bu been amazing, mile to ensure aspects of wor	ional and we rmed and ha	nt the extra ppy on all	
pully informed and happy on all aspects op work completed. Couldn't bok for batta	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 29th October 2024				
	Total cost of w	ork: £280			
	Description of work: Roof repair including replace felt and tiles.				
	Comments: No hesitation recommending Taylor Roofs. Excellent service from start to finish at a reasonable price.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 23 rd October 2024			
	Total cost of work: £500			
	Description of work: Repair and replace flashings/slates etc. Comments: From the first point of contact until the day of repair, everyone I dealt with, were friendly, informative and professional. The quote showed exactly what needed done, with explanation and pictures. The communication was amazing at every step and they followed up to ensure complete satisfaction. We were very impressed!			
	Value for Quality of Service T money work			Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 21 st October 2024 Total cost of work: £11,500				
	Description of work: Complete new roof Comments: We were happy with the workmanship, however we were surprised that the old boards rained down from the roof onto the garden, which was cleared up at the end of their working day. Whe the job was complete and the scaffolding dismantle we were surprised how dirty our windows were with grime and dust, which took some time cleaning completely. However, we are happy with the quality of our new roof.				
	Value for Quality of Service Ti money			Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 14 th October 2024				
	Total cost of work: £3000				
	Description of work: Roofing repairs and installation of new dry ridge.				
	Comments: From the initial survey to completion of the work the team were excellent. They carried out the work efficiently and in a timely manner leaving the work sight clean and tidy. Highly recommended.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	9	9	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 9 th October 2024 Total cost of work: £258.30			
	Description of work: Replace 2 ridge tiles and 4 of tiles.			
	Comments: Taylor roofs were excellent from first contact to job completion, also managed to fit my joi in early as I had water entering my house causing damage. Thank you to everyone at Taylor Roofs.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 8 th October 2024			
	Total cost of work: £9990			
	Description of work: New roof			
	Comments: The boys were polite friendly and very efficient I would have them back anytime			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 8 th October 2024 Total cost of work: £300			
	Description of work: Clean and repair of gutters. Comments: One call to arrange a survey. Quotation provided immediately after survey along with an approximate lead time for the job. Regular updates as to place in queue. Was then called to arrange the			
	exact date and time. Crew turned up on time and completed the job without any hassle. Whole proce extremely professional from start to finish.			ole process
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	8	9	10	10

ONLINE FEEDBACK PROVIDED		Date received: 23 rd September 2024 Total cost of work: £814.80			
	Description of work: Cleaning all gutters, fixing damaged lead and cladding on the roof, replacing cracked roof tile and repairing a seal under a wind				
	Comments: The service received was extremely professional. A surveyor came, inspected my roof and recommended action. I received a detailed quote and was contacted to be advised the work could be done much sooner than the 8 weeks I expected, in fact only 3 weeks after receiving my quote. The work was completed, with everything left clean and tidy. I received money off my bill from the cost of the initial survey and promptly received a receipt. Everyone I spoke with/met were friendly and courteous.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 23 rd August 2024			
	Total cost of work: £32,000			
	Description of work: Removal of old roof down to timbers, including flat dormers. Complete new roof and guttering, plus solar / battery installation. Comments: Phenomenal work by Taylor Roofs. Ver professional, extremely high quality work, whole process was very clear and communication was excellent. Would absolutely use Taylor Roofs for any roofing work in future, and would whole heartedly recommended to a friend.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 21 st August 2024 Total cost of work: £21,000			
	 Description of work: We had a full reroof, dormer windows retiled and ridgeline completed. The weather was atrocious, but the guys worked tirelessly. Minimal noise and disruption throughout and a purely professional finish achieved. Comments: Thank you so much, Taylor Roofs team. Big shout out to the entire team. The roofing team and the admin staff were polite and courteous and happy to help. Absolutely would recommend Taylor Roofs for fantastic service. 			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	9

Total cost of the work £ CIRLA £ 3K	Date received: 5 th August 2024			
Description of the work undertaken:	Total cost of work: circa £3k			
Reparen Rost Maintenned / Brity Prostant.	 Description of work: Roof maintenance / bird proofing. 			
Your comments:	Comments: Good job, well done!!			
LID JOB, Well Dong !!	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	9	9	8